

INS. CASE OWNER:

CC 4 / III1800

9250

R1

4039

LKK:
IDAC:

Surveyor:

RASUL

DOI:

ASSIGNMENT

22/8/18

Date / Time:

21/05/2018

Registered in Merimen:

19/5/18 by m4p

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 71624

Name of Insured:

CTP

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

19/05/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Abdul Ghanim Abdul Han

Driver Tel No.:

9673045

(V/L: YES / NO)

Claim No.:

Policy No.:

MUM001

Make / Model:

H. Sonata

Place of Accident:

PASUL AS OR 1

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKC 3374E



INSRS:

WSP:

Tel:

Liability:

RMKS:

AA Um
(Amk)

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

OI reas-ended to TP.

DV sent

Hce pass to Merimen

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed/ Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

3987.59

Loss of Rental (LOR):

S\$

390.00

(

2 days)

X#130.00

Loss of Use (LOU):

S\$

(

x

days)

Loss of Income (LOI):

S\$

(

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

Total:

S\$

4385.34

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4385.34

Name 1:

Ah Um Motor Company

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Survivor

Pam

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKC 3374E

at Workshop m/s AH Lim motor

of Antepoint # 01-09

Insured: 111 / TP

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No SKC 3374E Yr Regn 2011 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make MERCEDES Benz E250 c.c 1796

Colour BLUE A/C Insured / Std / NI / NA

Sp. Reading 166832 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No W00 2120 472A4 47224

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size: F: 245/40ZR18

R: 245/40ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 17/05/18 D.O.I. 22/05/18

Survey held at AH Lim motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐ Site Insp. (\$

1 S + RS 19

☐ Interview (\$

Photo:

☐ Tech. Invs (\$

Others:

☐ Weekend (\$

1

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
GST Reg No: M9-0009639-E

TP INSURER: India International Insurance Pte Ltd (HQ)

SURVEYOR COPY

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/05/2018
Vehicle Reg. No:	SKC3374E	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MERCEDES-BENZ E250, 1.8 (A)	Vehicle Reg. Date:	16/08/2011
Vehicle Colour:	BLUE		
Engine No:	27186030244920	Chassis No:	WDD2120472A447224
Odometer:	0 KM		
Paint Type:			
Nett Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Remarks:	PLS CALL WORKSHOP AT ANG MO KIO FOR SURVEY AS CAR IS NOT IN WORKSHOP YET		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS	Amount
Parts	3,763.40
Miscellaneous Items	10.00
Labour	2,060.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,833.40
+ GST 7.00% (S\$)	408.34
Nett Amount (S\$)	6,241.74

This claim is handled by: KEE MUI HONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 May 2018)
 Parts: 143 MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SKC3374E/19/05/2018 10:57
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	10.00	0.00	*1,550.00 FN DE
2	2		*REAR BUMPER SIDE RETAINERS LH & RH	10.00	0.00	*76.00 FN X
3	15		*REAR BUMPER CLIPS	10.00	0.00	*90.00 FN
4	1		*REAR BUMPER REINFORCEMENT	10.00	0.00	*750.00 FN
5	1		*REAR BUMPER CHROME MOULDING CENTER	10.00	0.00	*170.00 FN
6	2		*REAR BUMPER CHROME MOULDING SIDE LH & RH	10.00	0.00	*250.00 FN
7	2		*REAR BUMPER REVERSE SENSOR CENTER LH & RH	10.00	0.00	*520.00 FN
8	2		*REAR BUMPER REVERSE SENSOR SIDE LH & RH	10.00	0.00	*520.00 FN X
9	1		*REAR BOOT EMBLEM	10.00	0.00	*45.00 FN X
10	1		*REAR BOOT E250 LOGO	10.00	0.00	*75.00 FN X
11	1		*REAR BOOT 7G-TRONIC LOGO	10.00	0.00	*80.00 FN X
12	1		*C&C LOGO	0	0.00	*50.00 FS X
13	1		*REAR BUMPER REFLECTOR CENTER -CHECK PRICE	0	0.00	50 *FS CRA

F=Franchise part S=SpecNett N=NettItemDisc

Sub Total (S\$) 4,176.00

- Nett Item Discount on N Items (S\$) 412.60

Total Parts (S\$) 3,763.40

Ah Lim Motor Company/SKC3374E/19/05/2018 10:57. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00
2	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	60.00 X
3	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS (4PCS)	New	120.00 60
4	TO RESET REVERSE SENSOR	New	180.00 80
5	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	60.00 X

Ah Lim Motor Company/SKC3374E/19/05/2018 10:57. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
6	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR REAR BOOT; END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00 250
7	TO SPRAY REAR BOOT; REAR BUMPER; END PANEL	New	800.00 250
Gross Labour Cost (S\$)			2,060.00

Ah Lim Motor Company/SKC3374E/19/05/2018 10:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
3 days
P/P
22/05/18 @ 1500
Resurvey by part



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

PAET FINAL

M/S : ENG HWEE YONG
BLK 223 PASIR RIS ST 21
#08-132
SINGAPORE 510223

Claim No: MC0913102
No: MF0911179
Date: 30 Jul 2018
Policy No: 17-MX005514-R03
Veh Reg No: SKC3374E
Make/Model: M.BENZ E 250

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 17/05/2018
TP Veh Reg No: SHA7162U

Repair Cost to Vehicle No (For Finalization):SKC3374E

Description	Quantity	List Price S\$	Amount S\$
Nett			
1 REAR BUMPER	1 PC	1,550.00	
2 REAR BUMPER CLIPS	15 PC	90.00	
3 REAR BUMPER REINFORCEMENT	1 PC	750.00	
4 REAR BUMPER CHROME MOULDING CENTER	1 PC	170.00	
5 REAR BUMPER CHROME MOULDING SIDE LH & RH	2 PC	250.00	
6 REAR BUMPER REVERSE SENSOR CENTER LH & RH	2 PC	520.00	
		3,330.00	
	Less 10%	333.00	2,997.00
Special Nett			
7 REAR BUMPER REFLECTOR CENTER	1 PC	50.00	
		50.00	50.00
LABOUR			
8 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
9 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS (4PCS)	1 PC	60.00	
10 TO RESET REVERSE SENSOR	1 PC	80.00	
11 TO DISMANTLE ALL DAMAGED PARTS, TO CUT & WELD, TO KNOCK & REPAIR REAR BOOT, END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	250.00	
12 TO SPRAY REAR BOOT, REAR BUMPER, END PANEL	1 PC	250.00	
		680.00	680.00

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlilmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : ENG HWEE YONG
BLK 223 PASIR RIS ST 21
#08-132
SINGAPORE 510223

Claim No: MC0913102
No: MF0911179
Date: 30 Jul 2018
Policy No: 17-MX005514-R03
Veh Reg No: SKC3374E
Make/Model: M.BENZ E 250

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 17/05/2018
TP Veh Reg No: SHA7162U

Repair Cost to Vehicle No (For Finalization):SKC3374E

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 3,727.00
		Less Excess	S\$ 0.00
		Amount Before GST	S\$ 3,727.00
		Add GST @ 7%	260.89
		Total Amount Payable	S\$ 3,987.89

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED EIGHTY SEVEN AND CENTS EIGHTY NINE ONLY

The above vehicle was surveyed by LKK - RASUL on 22/05/2018

For AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 8903J

Vehicle Details

Vehicle No.: SKC3374E
Vehicle to be Exported: Yes
Intended De-registration Date: 17 May 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: E 250
Primary Colour: Blue
Manufacturing Year: 2011
Engine No.: 27186030244920
Chassis No.: WDD2120472A447224
Maximum Power Output: 150.0 kW (201 bhp)
Open Market Value: \$52,881.00
Original Registration Date: 16 Aug 2011
First Registration Date: 16 Aug 2011
Transfer Count: 0
Actual ARF Paid: \$52,881.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Aug 2021
PARF Rebate Amount: \$34,372.00

Intended COE Rebate Details

COE Expiry Date: 15 Aug 2021
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$56,889.00
COE Rebate Amount: \$18,267.00
Total Rebate Amount: \$52,639.00

The information contained herein is correct as at 17 May 2018

OK

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A

#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlmmc@singnet.com.sg

GST Reg No: M9-0009639-E

TP INSURER: India International Insurance Pte Ltd (HQ)

Singapore

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/05/2018
Vehicle Reg. No.:	SKC3374E	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MERCEDES-BENZ E250, 1.8 (A)	Vehicle Reg. Date:	16/08/2011
Vehicle Colour:	BLUE		
Engine No:	27186030244920	Chassis No:	WDD2120472A447224
Odometer:	0 KM		
Paint Type:			
Nett Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Remarks:	PLS CALL WORKSHOP AT ANG MO KIO FOR SURVEY AS CAR IS NOT IN WORKSHOP YET		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS	Amount
Parts	3,763.40
Miscellaneous Items	10.00
Labour	2,060.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,833.40
+ GST 7.00% (S\$)	408.34
Nett Amount (S\$)	6,241.74

This claim is handled by: KEE MUI HONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 May 2018)
Parts: 143 MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Ah Lim Motor Company/SKC3374E/19/05/2018 10:57
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	10.00	0.00	*1,550.00 FN <i>DS</i>
2	2		*REAR BUMPER SIDE RETAINERS LH & RH	10.00	0.00	*76.00 FN <i>X</i>
3	15		*REAR BUMPER CLIPS	10.00	0.00	*90.00 FN <i>ma</i>
4	1		*REAR BUMPER REINFORCEMENT	10.00	0.00	*750.00 FN <i>?</i>
5	1		*REAR BUMPER CHROME MOULDING CENTER	10.00	0.00	*170.00 FN <i>ma</i>
6	2		*REAR BUMPER CHROME MOULDING SIDE LH & RH	10.00	0.00	*250.00 FN <i>ma</i>
7	2		*REAR BUMPER REVERSE SENSOR CENTER LH & RH	10.00	0.00	*520.00 FN <i>ma</i>
8	2		*REAR BUMPER REVERSE SENSOR SIDE LH & RH	10.00	0.00	*520.00 FN <i>X</i>
9	1		*REAR BOOT EMBLEM	10.00	0.00	*45.00 FN <i>X</i>
10	1		*REAR BOOT E250 LOGO	10.00	0.00	*75.00 FN <i>X</i>
11	1		*REAR BOOT 7G-TRONIC LOGO	10.00	0.00	*80.00 FN <i>X</i>
12	1		*C&C LOGO	0	0.00	*50.00 FS <i>X</i>
13	1		*REAR BUMPER REFLECTOR CENTER -CHECK PRICE	0	0.00	*FS <i>CRA</i>

F=Franchise part. S=SpcNett. N=NettItemDisc

Sub Total (S\$)	4,176.00
- Nett Item Discount on N Items (S\$)	412.60
Total Parts (S\$)	3,763.40

Ah Lim Motor Company/SKC3374E/19/05/2018 10:57. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00 ✓
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 ✓
2	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	60.00 <i>X</i>
3	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS (4PCS)	New	128.00 <i>60</i>
4	TO RESET REVERSE SENSOR	New	180.00 <i>80</i>
5	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	60.00 <i>X</i>

Ah Lim Motor Company/SKC3374E/19/05/2018 10:57. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
6	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR REAR BOOT; END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00 250
7	TO SPRAY REAR BOOT; REAR BUMPER; END PANEL	New	800.00 250
Gross Labour Cost (S\$)			2,060.00

Ah Lim Motor Company/SKC3374E/19/05/2018 10:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
3 days
P/P
22/05/18 @ 1500
Resurvey by paint

Hsiao Tong (LKKAuto)

From: Zuhaidah Samsuri <aida@iii.com.sg>
Sent: Thursday, 10 January 2019 2:00 PM
To: SUR; assignments; muihong@ahlimmotor.com.sg; Hsiao Tong (LKKAuto)
Subject: RE: Claim Documents for our client SKC3374E accident with India Insured - SHA7162U on 17.05.2018

Hi Mui Hong,

Please liaise with LKK.

Hi LKK,

Please follow up with repairer.

Thanks.

Best Regards

Aida Samsuri

Motor Claims Dept

India International Insurance Pte Ltd

64 Cecil Street #04/#05 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 257 Fax: 6224 4174

Email: aida@iii.com.sg

Co. Reg Number: 198703792K

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]
Sent: Wednesday, 9 January, 2019 5:20 PM
To: Sherini Pillai <sherini@iii.com.sg>; sur@lkkauto.com; assignments@lkkauto.com; Motor Claim - III <motorclaim@iii.com.sg>
Cc: muihong@ahlimmotor.com.sg
Subject: Claim Documents for our client SKC3374E accident with India Insured - SHA7162U on 17.05.2018

This mail is associated with :

SKC3374E (MCT18050439)

[SHA7162U]

TP

ENG HWEE YONG

May 17 2018 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Ah Lim Motor Company

Dear Sherini,

Pls see attached the Claim Documents for our client SKC3374E accident with India Insured - SHA7162U on 17.05.2018 .

You had earlier confirm the above as a Liability Clear case for Direct Settlement. Pls advise if LKK or India will offer on the attached claim ?

I will also upload the claim documents to Merimen.

Pls do assist to offer.

Thanks

Mui Hong

This is an auto-generated email. Do not reply to this email.

Sent by : Kee Mui Hong (Ah Lim Motor Company)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	19 May 2018 10:39	Cim Veh Model Changed	(203661) MERCEDES-BENZ E250 1.8 (A).	[R] Kee Mui Hong
2	19 May 2018 10:39	Cim Created	Reg No: SKC3374E, Acct Date: 2018/05/17, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), Workshop: Ah Lim Motor Company (AMK)	[R] Kee Mui Hong
3	19 May 2018 10:57	Cim Submitted	5833.40.	[R] Kee Mui Hong
4	21 May 2018 08:46	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[I] Gabriel Wee
5	21 May 2018 08:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31	[I] Gabriel Wee
6	21 May 2018 08:46	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Gabriel Wee
7	21 May 2018 10:26	Assignment 1st Accessed		[A] CELINE FONG
8	21 May 2018 11:00	Label Added	(30651):Vehicle Not In.	[A] CATHERINE CHONG KAI LING
9	21 May 2018 21:15	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] HOW MEI KWAN
10	21 May 2018 21:15	Cim Dtl Modified	Insured Name: - -> COMFORT TRANSPORTATION PTE LTD.	[A] HOW MEI KWAN
11	21 May 2018 21:15	Cim Dtl Modified	Claimant's Name: - -> COMFORT TRANSPORTATION PTE LTD, Claimant's ID: - -> 9303821R.	[A] HOW MEI KWAN
12	24 May 2018 20:55	Label Removed	(30651):Vehicle Not In.	[A] HOW MEI KWAN
13	24 May 2018 20:55	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN
14	24 May 2018 20:55	Adj Adjuster Assigned	KENNETH KONG -> MOHD RASUL	[A] HOW MEI KWAN
15	24 May 2018 20:57	Adj Rpt Initiated		[A] HOW MEI KWAN
16	31 May 2018 16:07	Adj Mandate Request	Cur.Req:3945.09:PODS - Express Settlements Dear Sir / Madam, We advise liability as follows for Direct Settlement: Liability : 100% Remarks : BOLA - 27 (OI rear-end to TP.)	[A] THIN HLAING
17	31 May 2018 16:23	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31	[I] Sherini Pillai
18	31 May 2018 16:23	Adj Mandate Set	Approved:3945.09.	[I] Sherini Pillai
19	10 Jan 2019 16:06	Adj Mandate Request	Cur.Req:4385.34:PODS Liability: 100% Quantum: (a)CORw/GST: \$3,987.89 + (b)LO R(3days x \$130.00): \$390.00 + (c)LTA/GIA search fee: \$7.45 = Total: \$4,385.34 Vehicle Model: Mercedes Benz E250 (1796cc) 3 recommendation repair days For your approval	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

ACTIVITY

[21/05/2018 11:00] CATHERINE CHONG KAI LING:

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1809317	19/05/2018 10:39	Motor	Ah Lim Motor Company (AMK)	Ah Lim Motor Company (AMK)	SKC3374E		xx.xx
1814360	24/05/2018 20:57	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKC3374E	SHA7162U	10.70

Print Received Message


This mail is associated with :

SKC3374E (MCT18050439)
[SHA7162U]
TP
ENG HWEE YONG
May 17 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Ah Lim Motor Company

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/01/2019 09:24 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4385.34) - SKC3374E - Claim Handler: Sherini Pillai

Approved:4385.34.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1798903J



Name
ENG HWEE YONG

翁惠榮

Race
CHINESE

Date of Birth
08-11-1967

Sex
M

Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identification No. S1798903J

ENG HWEE YONG

Date of Birth 08 Nov 1967

Valid Until 08 Feb 2005




Hlp: 8186 8846

Email. sunnyblueskyday@yahoo.com

3019309



NRIC No. S1798903J



Blood Group Date of issue
O+ 11-04-1998

APT BLK 223 PASIR RIS STREET 21 #08-132
SINGAPORE 510223

NRIC No: S1798903J Date: 04/02/2008 No: 5907050

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	26 May 1968
Class 2A	Motorcycles between 201 cc and 400 cc	26 May 1968
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	21 Mar 1900

NP 425A

License No: S1798903J



Dry

Wg: No

Car: No

Total: 1

Tokio Marine Insurance Singapore Ltd.

(Company Reg. No.: 192300014M) (GST Reg No.: M2-0000023-4)

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

T: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: tmls@tokiomarine.com.sg W: www.tokiomarine.com

A member of the
Tokio Marine Group**TOKIO MARINE
INSURANCE GROUP**
FORM MX1**Certificate of Insurance****MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Policy No.: 17-MX005514-R03 (Private Motor Car)

1. **Index Mark and Registration Number of Vehicle** SKC3374E **Chassis No.:** WDD2120472A447224
2. **Name of Policyholder** MR ENG HWEE YONG
3. **Effective date of the Commencement of Insurance for the purposes of the Act** 16/08/2017
4. **Date of Expiry of Insurance** 15/08/2018
5. **Persons or Class of Persons entitled to drive***
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost or destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: 2324DDA

Insurance Plan:	Comprehensive Approved Workshop Plan
Limit for total loss or theft:	Prevailing Market Value
Policy Excess:	Own Damage Claims SGD 800
	Windscreen Excess SGD 100
Financial Interest:	MAYBANK

Tokio Marine Insurance Singapore Ltd.

Authorised Signature

Jo-an Tan
Quotigo Pte Ltd
Manager, Business Development
60 Paya Lebar Road
Paya Lebar Square #11-41
Singapore 409051
DID : 62881866 Mobile : 88380007
Email : joan@quotigo.com
Website: www.quotigo.com

User Name: Intermediaries from TM O

Printed 03/07/2017

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 8903J

Vehicle Details

Vehicle No.: SKC3374E
Vehicle to be Exported: Yes
Intended De-registration Date: 17 May 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: E 250
Primary Colour: Blue
Manufacturing Year: 2011
Engine No.: 27186030244920
Chassis No.: WDD2120472A447224
Maximum Power Output: 150.0 kW (201 bhp)
Open Market Value: \$52,881.00
Original Registration Date: 16 Aug 2011
First Registration Date: 16 Aug 2011
Transfer Count: 0
Actual ARF Paid: \$52,881.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Aug 2021
PARF Rebate Amount: \$34,372.00

Intended COE Rebate Details

COE Expiry Date: 15 Aug 2021
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$56,889.00
COE Rebate Amount: \$18,267.00
Total Rebate Amount: \$52,639.00

The information contained herein is correct as at 17 May 2018

OK

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

Our Ref : MC0913102

Your Ref : SHA7162U

Date : 09/01/2019

INDIA INTERNATIONAL INSURANCE P/L

64 CECIL STREET #04/#05

IOB BUILDING

SINGAPORE 049711

Dear Sir/Madam,

Request for Direct Settlement for Accident involving our client's vehicle SKC3374E and your Insured SHA7162U ON 17/05/2018 08:30 ALONG ALONG PASIR RIS DRIVE 1

We refer to the above matter.

Please assess through your Insured's (SHA7162U) report and our Client (SKC3374E) – ENG HWEE YONG's report as attached and advise whether there are possibilities of direct settlement.

Please find attached the following :

- 1) Final Bill
- 2) GIA Motor Accident Report form
- 3) Certificate of Insurance, IC and Driving Licence
- 4) LTA Search & Rental Invoice

The above vehicle was surveyed by Mr Rasul from LKK as appointed by INDIA on 22/05/2018.

We would quantify our claim as below:-

Cost of Repair : \$3,987.89

Rental Invoice : \$390.00(3 Day X \$130) Surveyor recommend 3 days

LTA Search : \$7.45

=====

Total : \$4,385.34

Kindly acknowledge and revert on the possibility of direct settlement within 14 days.

Thank You.

Yours faithfully,

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

Kee Mui Hong


Authorisation to Act

I, Eng Hwee Tony (the third party claimant) of B1K 223, PASIR RU ST 21 #09-132 SE 510223 (address), owner of SKC 3374E (Vehicle no) hereby authorise **Ah Lim Motor Company** (the workshop) to act for me in respect to my claim for repair costs and / or rental and /or loss of use (Claim) for my vehicle No. SKC 3374E that was damaged pursuant to the accident which occurred on 17/05/18 (date) along PASIR RU DRIVE 1 (location) involving vehicle Nos SMA 7162U (the Accident)

I further authorise the workshop to settle the above mentioned claim in a manner that they deem fit and the workshop is further authorised to receive the payment further to settlement of my claim with payment cheque/s made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle is concerned.

Dated this 17th day of MAY (month) 20 18 (year)


Signed by Third party claimant
Owner Veh No : SKC 3374E


Signed by the workshop

Personal data Protection Act 2012

I/ We acknowledge and consent to Ah Lim Motor Company collecting , using and disclosing and /or processing my/our personal data to Third Party service providers and/or Insurance company my / our personal data for the purpose of processing the claim and related insurance / claim matters.


Owner Signature

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18050439

Claimant Ref: MC0913102 (SKC 3374E)

We/I, Ah Lim Motor Company ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 3,987.89 (repair cost), S\$ 390.00 (loss of ~~use~~/rental), S\$ 7.45 (search fee), vehicle no. SKC 3374E that was damaged pursuant to the accident which occurred on 17/05/2018 (date) at Pasir Ris Drive 1 (location) involving vehicle no. SHA 7162U (insured vehicle). This is pursuant to the inspection conducted on 22/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ENG HWEE YONG ("the third party claimant") of vehicle no. SKC 3374E to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKC 3374E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,385.34 to Ah Lim Motor Company

Dated this 25 day of Jan 2019

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:



MRS

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568041
Tel: 8483 1244 Fax: 8483 8170

LKK Auto Consultants Pte Ltd

199607198R

51 Ubi Avenue 1

#01-25 Paya Ubi Ind. Park S(408933)

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : ENG HWEE YONG
BLK 223 PASIR RIS ST 21
#08-132
SINGAPORE 510223

Claim No: MC0913102
No: AL1900006
Date: 09 Jan 2019
Policy No: 17-MX005514-R03
Veh Reg No: SKC3374E
Make/Model: M.BENZ E 250

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 17/05/2018
TP Veh Reg No: SHA7162U

Tax Invoice-Final Repair Cost to Vehicle No :SKC3374E

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Nett			
1 REAR BUMPER	1 PC	1,550.00	
2 REAR BUMPER CLIPS	15 PC	90.00	
3 REAR BUMPER REINFORCEMENT	1 PC	750.00	
4 REAR BUMPER CHROME MOULDING CENTER	1 PC	170.00	
5 REAR BUMPER CHROME MOULDING SIDE LH & RH	2 PC	250.00	
6 REAR BUMPER REVERSE SENSOR CENTER LH & RH	2 PC	520.00	
		3,330.00	
	Less 10%	333.00	2,997.00
Special Nett			
7 REAR BUMPER REFLECTOR CENTER	1 PC	50.00	
		50.00	50.00
LABOUR			
8 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
9 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS (4PCS)	1 PC	60.00	
10 TO RESET REVERSE SENSOR	1 PC	80.00	
11 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR REAR BOOT, END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	250.00	
12 TO SPRAY REAR BOOT, REAR BUMPER, END PANEL	1 PC	250.00	
		680.00	680.00

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A,
#01-09 AMK Autopoint, Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST: M9-0009639-E RCB NO: 06470300B

M/S : ENG HWEE YONG
BLK 223 PASIR RIS ST 21
#08-132
SINGAPORE 510223

Claim No: MC0913102
No: AL1900006
Date: 09 Jan 2019
Policy No: 17-MX005514-R03
Veh Reg No: SKC3374E
Make/Model: M.BENZ E 250

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 17/05/2018
TP Veh Reg No: SHA7162U

Tax Invoice-Final Repair Cost to Vehicle No :SKC3374E

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 3,727.00
		Less Excess	S\$ 0.00
		Amount Before GST	S\$ 3,727.00
		Add GST @ 7%	260.89
		Total Amount Payable	S\$ 3,987.89

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED EIGHTY SEVEN AND CENTS EIGHTY NINE ONLY

The above vehicle was surveyed by LKK - RASUL on 22/05/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

E. & O. E.

AUTHORISED SIGNATURE

ACE AUTO

18, Ubi Road 4
#02-05 Ubi Car Mall
Singapore 408616 Reg no : 53029719A

To : An Lim Motor Company
10, Ang Mo Kio Industrial park 2A
#01-09 AMK Autopoint
Singapore 568047

Invoice No A4100

Date 26/May/2018

Vehicle no SJP1420L

Make / Model Honda Stream 1.8A

Rent to : Eng Hwee Yong - SKE3374E

Account : Ah Lim Motor Company

Rental Ref 4100

		No.of da	Rate	Total
Duration	From : 24/05/2018 9.00am	3	\$ 130.00	\$ 390.00
	To : 26/05/2018 5.30pm			
	Grand Total			\$ 390.00

ACE AUTO

Ace Auto


18 Ubi Road 4, #02-07 Singapore 408616
Tel: 6483 6143 Fax: 6483 6170
Registration No. 53029719 A

\$150.00 - 312

RENTAL AGREEMENT / INVOICE

Hirer's Name ENG NWE EYONG	Date of Birth	Passport / Nric No.	Nationality
Address Buk 273 #67-132 Pukin Ris St	Occupation F. I.	Driving Licence No.	Date of Licence Obtained
Postal Code 510273	Contact No.	Mobile Phone No. 81868846	Open Work Ind. No. 81863374-1
Driver Name	Date of Birth	Passport / Nric No.	Nationality
Address	Occupation	Driving Licence No.	Date of Licence Obtained
Postal Code	Contact No.	Mobile Phone No.	


Date 24/05/18	Time 9 am	Mileage 126206 KM	
Date 26/5/18	Time 5.30 PM	Mileage / KM	<p>Pay _____ for every quarter tank petrol if the petrol is less than the check out amount.</p>

Date 26/5/18	Time 5.30 PM	Mileage / / KM	 <p>Pay _____ for every quarter tank petrol if the petrol is less than the check out amount.</p>
-----------------	-----------------	-------------------	--

VEHICLE NO.	SJP 1420 L	MODEL	Honda Civic A 1.8 D
-------------	------------	-------	---------------------

- This vehicle is restricted to SINGAPORE use only.
- **BE WARNED :** Hirer / Driver shall be fully responsible for all consequences including all outstanding summons and all costs incurred to & by the owner for any invalid entry in Malaysia.
- No refund will be given for vehicle that returns early.
- The hirer shall be liable to pay the first \$ 1000 for damage to vehicle plus loss of earnings while damaged vehicle is under repair.
- Third Party Liability is \$ 1500 any accident.
- Hirer shall pay all parking fines & traffic summons, incurred during the period of rental.
- Extension:- One day's advance notice is required otherwise No extension will be allowed.
- Vehicle should be returned at the same time as collection except on Saturday where return time is before 10am.
- Vehicle returned after office hour will be charged to the next working day.
- Hourly extension:- Refer to prevailing rates.
- Please check water & engine oil daily as preventive maintenance.

	UNIT		RATE (\$)	TOTAL (\$)
RATE PER DAY		@		
RATE PER WEEK		@		
RATE PER MONTH		@		
GRAND TOTAL				
DEPOSIT				
EXTENSION ____ DAYS				
TOTAL PAYABLE AMOUNT				
DEPOSIT REFUNDABLE	S\$			
CHANGED OVER FROM VEH.			DATE	



I/We have read and agree to the terms and conditions of the rental agreement above and as set overleaf.
I/We declare that all information given on this form is true and accurate.

Hirer's Signature

Driver's Signature

for ACE Auto

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 19 May 2018 / 10:12:46

Receipt Date/Time : 19 May 2018 / 10:12:46

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180519-000302

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SHA7162U As at 17 May 2018/08:30:00 Insurance Co: INDIA INT'L INS PTE LTD			
1	Insurance Enquiry - SHA7162U Enquiry Fee 20180519101136856704	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20180519101148921	Direct Debit: eNETS Debit (Internet Banking)		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement





















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 May 2018 Sendback Est	19 May 2018 10:57 \$55,833.40	21 May 2018 08:46 Edit Adj Rpt	\$53,727.00 Edit Estimates	\$53,727.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	ENG HWEE YONG , ID: S1798903J								
Vehicle Reg. No.:	SKC3374E	Date of Loss:	17/05/2018 00:00 - :59 [81 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18050439	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA7162U	Policy No. (Claimant):	17-MX005514-R03						
		Excess:							
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 31/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (11/01/2019): Alert - Adj Mandate Approved (\$54385.34) - SKC3374E - Claim Handler: Sherini Pillai... III_SG (31/05/2018): Alert - Adj Mandate Approved (\$53945.09) - SKC3374E - Claim Handler: Sherini Pillai... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKC3374E (MCT18050439)
[SHA7162U]
TP
ENG HWEE YONG
May 17 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Ah Lim Motor Company

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	19/05/18 10:57	Repairer Estimates	Load HTML	
Photos/Images			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/01/19 15:34	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	10/01/19 15:34	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
4	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
5	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
6	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
7	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
8	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
9	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
10	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
11	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
12	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
13	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
14	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
15	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
16	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
17	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
18	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
19	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
20	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
21	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
22	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
23	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
24	10/01/19 15:34	General View	Load JPG	<input checked="" type="checkbox"/>
25	10/01/19 15:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	10/01/19 15:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	10/01/19 15:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	10/01/19 15:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	10/01/19 15:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	10/01/19 15:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	10/01/19 15:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	10/01/19 15:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	10/01/19 15:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	10/01/19 15:34	Reinspection Photo	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	10/01/19 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	10/01/19 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	10/01/19 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	10/01/19 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	10/01/19 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	10/01/19 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	10/01/19 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	10/01/19 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	19/05/18 11:05	Certificate of Insurance	 Load PDF	
2	19/05/18 11:05	Copy of Claimant's Identity Card	 Load PDF	
3	19/05/18 11:05	Log card (if available)	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 08:45	Singapore Accident Statement	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/05/18 16:57	TP ESTIMATE - MARKED	 Load PDF	
2	27/05/18 16:57	TP GIA REPORT	 Load PDF	
3	10/01/19 16:02	TP LOD	 Load PDF	
4	10/01/19 16:02	Workshop Invoice	 Load PDF	
5	10/01/19 16:02	Rental Receipt	 Load PDF	
6	10/01/19 16:02	LTA	 Load PDF	
7	28/01/19 08:54	DISCHARGE VOUCHER	 Load PDF	
8	28/01/19 08:54	AUTHORISATION TO ACT FORM	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/II18009250/R1PA3

Date: 28/01/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No : SKC3374E

Insured Vehicle No : SHA7162U

Date of Loss: 17/05/2018

Nature of Claim: TP

Claim No: MCT18050439

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC3374E

Make & Model: MERCEDES-BENZ E250, 1.8 (A)

Engine No: 27186030244920

Reg. Date: 16/08/2011 (Man. Year: 2011)

Chassis No: WDD2120472A447224

Colour: Blue

Odometer: 166832 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40ZR18

Rear Tyre Size: 245/40ZR18

Front Left Side: Nexen 6 mm

Rear Left Side: Nexen 6 mm

Front Right Side: Nexen 6 mm

Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,763.40	3,047.00	716.40	19.04
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	2,060.00	680.00	1,380.00	66.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,833.40	3,737.00	2,096.40	35.94
Approved Total (Overridden) (S\$)		3,727.00		
(S\$)	5,833.40	3,727.00	2,106.40	36.11
+ GST 7.00/7.00% (S\$)	408.34	260.89	147.45	36.11
Nett Amount (S\$)	6,241.74	3,987.89	2,253.85	36.11
+ Car Rental (3.0 x S\$130.00/day) (S\$)		390.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,385.34		

INSPECTION

Date of Assignment: 21/05/2018 Present Location:

Ah Lim Motor Company (AMK)

Date Inspected: 22/05/2018 Inspected At:

Ah Lim Motor Company (AMK)

10 Ang Mo Kio Industrial Park 2A, #01-09

AMK Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2019)
Parts: 143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKC3374E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER REFLECTOR CENTER (SN)	Cracked	-	*50.00 FS
2	1		*REAR BUMPER	Deformed	1,550.00 FN	*1,550.00 FN
3	2		*REAR BUMPER SIDE RETAINERS LH & RH	Not Necessary	76.00 FN	*- FN
4	15		*REAR BUMPER CLIPS	Necessary	90.00 FN	*90.00 FN
5	1		*REAR BUMPER REINFORCEMENT	Dented	750.00 FN	*750.00 FN
6	1		*REAR BUMPER CHROME MOULDING CENTER	Necessary	170.00 FN	*170.00 FN
7	2		*REAR BUMPER CHROME MOULDING SIDE LH & RH	Necessary	250.00 FN	*250.00 FN
8	2		*REAR BUMPER REVERSE SENSOR CENTER LH & RH	Necessary	520.00 FN	*520.00 FN
9	2		*REAR BUMPER REVERSE SENSOR SIDE LH & RH	Not Necessary	520.00 FN	*- FN
10	1		*REAR BOOT EMBLEM	Not Necessary	45.00 FN	*- FN
11	1		*REAR BOOT E250 LOGO	Not Necessary	75.00 FN	*- FN
12	1		*REAR BOOT 7G-TRONIC LOGO	Not Necessary	80.00 FN	*- FN
13	1		*C&C LOGO	Not Necessary	50.00 FS	*- FS
14	1		*REAR BUMPER REFLECTOR CENTER -CHECK PRICE	REPEATED	0.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc

Sub Total (\$\$)	4,176.00	3,380.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	412.60	333.00
Total Parts (\$\$)	3,763.40	3,047.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	40.00
2	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	60.00	0.00
3	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS (4PCS)	New	120.00	60.00
4	TO RESET REVERSE SENSOR	New	180.00	80.00
5	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	60.00	0.00
6	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR REAR BOOT; END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00	250.00
7	TO SPRAY REAR BOOT; REAR BUMPER; END PANEL	New	800.00	250.00
Gross Labour Cost (S\$)			2,060.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >