

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047
Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
GST Reg No: M9-0009639-E

TP INSURER: India International Insurance Pte Ltd (HQ)

SURVEYOR COPY

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/05/2018
Vehicle Reg. No.:	SKC3374E	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MERCEDES-BENZ E250, 1.8 (A)	Vehicle Reg. Date:	16/08/2011
Vehicle Colour:	BLUE		
Engine No:	27186030244920	Chassis No:	WDD2120472A447224
Odometer:	0 KM		
Paint Type:			
Nett Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Remarks:	PLS CALL WORKSHOP AT ANG MO KIO FOR SURVEY AS CAR IS NOT IN WORKSHOP YET		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS

Parts	3,763.40
Miscellaneous Items	10.00
Labour	2,060.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,833.40
+ GST 7.00% (\$\$)	408.34
Nett Amount (\$\$)	6,241.74

This claim is handled by: KEE MUI HONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 19 May 2018)**Parts:** 143 **MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)****Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Ah Lim Motor Company/SKC3374E/19/05/2018 10:57**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	10.00	0.00	*1,550.00 FN DE
2	2		*REAR BUMPER SIDE RETAINERS LH & RH	10.00	0.00	*76.00 FN X
3	15		*REAR BUMPER CLIPS	10.00	0.00	*90.00 FN MA
4	1		*REAR BUMPER REINFORCEMENT	10.00	0.00	*750.00 FN ?
5	1		*REAR BUMPER CHROME MOULDING CENTER	10.00	0.00	*170.00 FN MA
6	2		*REAR BUMPER CHROME MOULDING SIDE LH & RH	10.00	0.00	*250.00 FN MA
7	2		*REAR BUMPER REVERSE SENSOR CENTER LH & RH	10.00	0.00	*520.00 FN MA
8	2		*REAR BUMPER REVERSE SENSOR SIDE LH & RH	10.00	0.00	*520.00 FN X
9	1		*REAR BOOT EMBLEM	10.00	0.00	*45.00 FN X
10	1		*REAR BOOT E250 LOGO	10.00	0.00	*75.00 FN X
11	1		*REAR BOOT 7G-TRONIC LOGO	10.00	0.00	*80.00 FN X
12	1		*C&C LOGO	0	0.00	*50.00 FS X
13	1		*REAR BUMPER REFLECTOR CENTER -CHECK PRICE	0	0.00	*- FS CRA

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	4,176.00
- Nett Item Discount on N Items (\$\$)	412.60
Total Parts (\$\$)	3,763.40

Ah Lim Motor Company/SKC3374E/19/05/2018 10:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	OD/TP Case (Insurer)	10.00 ✓
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 ✓
2	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	60.00 X
3	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS (4PCS)	New	120.00 60
4	TO RESET REVERSE SENSOR	New	180.00 80
5	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	60.00 X

Ah Lim Motor Company/SKC3374E/19/05/2018 10:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
6	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR REAR BOOT; END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00 250
7	TO SPRAY REAR BOOT; REAR BUMPER; END PANEL	New	800.00 250
Gross Labour Cost (S\$)			2,060.00

Ah Lim Motor Company/SKC3374E/19/05/2018 10:57. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
3 days
P/P
22/05/18 @ 1000
Resurvey by paint