

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA	XA INSURANCE PTE LTD		Ref : CC4/ASM18009258/Uea3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA LOH		Date: 27-05-2020 Code: ASM			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJV 1713K	Veh. Inspected	SKW 8094A	
	Policy No.	GA007442/1	Coverage (\$)	0.00	
	Claim No.	S8M00H4O	Excess (\$)	0.00	
	Assign From		Assign Date	30/05/2018	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA HRV (A)	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	MRHRU1830FP000469	Colour	BLACK	
	Odometer	31507	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	DUNLOP	6 mm	
	L/H Front Tyre	215/55 R17	DUNLOP	6 mm	
	R/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
	L/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	14/05/2018	Inspection Date	30/05/2018	
	Survey held at	d at KAH MOTOR CO SDN BERHAD			
		15 UBI ROAD 4 SINGAPORE 408610			
5a.					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. 3)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				