

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003889

AXA INSURANCE PTE LTD

8 Shenton Way #B1-01
AXA Tower (S) 068811

ATTENTION :

CONTACT : -

FAX NO: 68804838

DATE : 05/06/2018
ACCIDENT DATE : 21/04/2018
VEHICLE NO : SJJ2801X
CHASSIS/ENG.NO : JMYSTCY4A8U004753
VEHICLE MODEL : MIT.LANCER
CLAIM NO :
POLICY NO :
REMARK : 2801 AXA TP AGST
GT8892B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	815.00	20	652.00	<i>de</i> 652.00
2	6	PC	REAR BUMPER CLIPS	3.00	20	2.40	<i>new</i> 14.40
3	2	PC	REAR BUMPER SIDE RETAINER <i>LH, RH new</i>	13.00	20	10.40	20.80
4	2	PC	REAR BUMPER BRACKET <i>LH, RH - new</i>	18.00	20	14.40	28.80
5	1	PC	REAR BUMPER REINFORCEMENT	210.00	20	168.00	<i>?</i> 168.00
6	1	PC	REAR BUMPER TOW COVER	21.00	20	16.80	<i>new</i> 16.80
7	1	PC	REAR BUMPER REFLECTOR(RH)	22.00	20	17.60	<i>new</i> 17.60
8	1	PC	REAR END PANEL	506.00	20	404.80	<i>Ry</i> 404.80
9	1	PC	REAR END PANEL TOP GARNISH	149.00	20	119.20	<i>x</i> 119.20
10	1	PC	REAR END PANEL CLIPS	4.00	20	3.20	<i>x</i> 3.20
11	2	PC	REAR TAIL LAMP <i>LH-X, RH - new</i>	320.00	20	256.00	512.00
12	4	PC	REAR TAIL LAMP CLIPS <i>LH-X, RH - new</i>	6.00	20	4.80	19.20
13	2	PC	REAR TAIL LAMP PANEL	86.00	20	68.80	<i>x</i> 137.60
14	1	PC	REAR BOOT	693.00	20	554.40	<i>Ry</i> 554.40
15	1	PC	REAR BOOT EMBLEM	47.00	20	37.60	<i>new</i> 37.60
16	1	PC	REAR BOOT "LANCER " LOGO	52.00	20	41.60	<i>new</i> 41.60
17	1	PC	REAR BOOT "EX " LOGO	39.00	20	31.20	<i>new</i> 31.20
----- SUB-TOTAL:							2,779.20

JOYCE



PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003889

AXA INSURANCE PTE LTD

8 Shenton Way #B1-01
AXA Tower (S) 068811

ATTENTION :

CONTACT : -

FAX NO: 68804838

DATE : 05/06/2018
ACCIDENT DATE : 21/04/2018
VEHICLE NO : SJJ2801X
CHASSIS/ENG.NO : JMYSTCY4A8U004753
VEHICLE MODEL : MIT.LANCER
CLAIM NO :
POLICY NO :
REMARK : 2801 AXA TP AGST
GT8892B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** SPECIAL NETT PRICE **							
1	1	PC	REAR REVERSE SENSOR	180.00		180.00	180.00

							SUB-TOTAL 180.00
** WORK LABOUR **							
TO KNOCK, WELD , REMOVE AND REPLACE ABOVE PARTS				700.00		500 700.00	
TO PUTTY RESPRAY PAINTING ON AFFECTED AREAS				700.00		50 700.00	
TO CHECK WIRING				30.00		✓ 30.00	

							SUB-TOTAL 1,430.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjim 97495729
4 days
- WP
6/6/18 @ 1pm
Resurvey after repair
suw@lkkauto.com

JOYCE



PAGE: 2 of 2

SUB-TOTAL : S\$ 4,389.20
ADD 7% GST. S\$ 307.24
GRAND TOTAL : S\$ 4,696.44

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:
The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.