	ASS, REC. BY	Alteria
:a 74	From (Person Estimated Co.	
	To Inspect Ve at Workshop	StTP RES / OD RES / EVA / INV / MY / CS Shicle No: SIP 1907A Insured: FBG 6497 A
	Policy No:Sum Insured:	MSD/VMFT/17-985927 Claim No:
	Make of Veh (Client's Recor	
	CA / REV _ Date/Time	7 REP. / REV 24 HRS (مر) H.O.D. Endorsement. 2.36am (عدد 18 Person Contacted: عدد 18 OUT
	Date/Time	Action/Instruction () Estimate SJP 1907A - NA IINC18069241/Z4
	24/5/18	Perent this mainer pending estimate
30		Confirm LIS \$1.5K @ 4 days (Red & 8931.20, 86%)

Interview (\$

Tech. Invs (\$

Weekend (\$

Report Format:

Lump Sum / LB: (\$

1500

S+RS__SI

210

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	ROLL BURNETS	Affiliated to Federation Internation		MANAGEMENT OF THE PARTY OF THE
MSI	S INSURANCE (SI	NGAPORE) PTE LTD	Ref: CS/MSG18009	274/Ard3
	AFFLES QUAY 01 HONG LEONG	BLDG SINGAPORE 048581	Date: 22-05-2018 Code: MSG	
1.		Policy Particulars	- THIRD PARTY CLA	IM
	Insured Veh.	FBG 6497A	Veh. Inspected	SJP 1907A
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	22/05/2018
2.	AND SUPPLIES	Vehicle Partic	ulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	17.	Steering	
	Brakes		Modification	
	General			
3.		Condition	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Description	on of Damages	
5.	Membership The	Genera	Information	
	Accident Date	18/05/2018	Inspection Date	22/05/2018
	Survey held at	RELIABLE CARZ PTE LTD		
		8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a.		Re	emarks	
	A)THE INSPECTION	ON WAS CONDUCTED ON A"WIT	HOUT PREJUDICE" BAS E HAVE NOT AUTHORIS	SIS. SED REPAIRS.

No results.

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status		
Main	21 May 2018		22 May 2018 10:39 Assign					granding against	ssignmer Case	nt
	Main	Re	ference		Claim Details		Documer	its] [Show All
CLAIM SU	BFOLDER DE	TAILS			CU-CONTRACTOR CONTRACTOR CONTRACT	[Create	d by insurer]	NAME OF THE OWNER, WHEN	Scampetry 1	
Insured:	FUNG KO	K VUI, ID: S737	4721Z			7				
Main Claimant:	RENT A C	AR LEASING PTE	LTD, Co. Reg	. No.: 2015	29642E					
Vehicle Reg No.:	SJP190	7A			Date of Loss:		018 00:00 - :59 ths and 20 Days	From LTA R	Reg Date (Man Yr)]
Claim Type	: TP				Policy/Cover Note No.:	100 miles (100 miles (FT/17-985927 e: 30/09/2017 - 2	9/09/2018	3	
Vehicle Reg No. (Insured):	FBG6497	A			Policy No. (Claimant):					
					Excess:					
Repairer:	Reliable (Carz Pte Ltd (HQ) 8 Kaki Bukit Av	re 4, #05-50), 415875 Kaki B	lukit - Tel:				
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (F	HQ) - Tel: +	65 6827 7888	. [Handled	by Christina Wo	ng - 6643	1311]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Imm.Adv	rice due	23/05/2018]			
Adj Asg. Remarks:	Non-Repor	ting. Unable to co	mment on liabili	ty. W/s agre	ed on LKK as SJI	E.				
ASSOCIA	TED MAIL RE	CEIVED						View All	Compos	e Case Ma
There are r	no mail for this	case.								
	OCIATED TAS	ve=				View A	II Search Tasks	Create N	1	Complet

Print Sent Message

This mail is associated with:

*SJP1907A (MSC/V/18-000711) [FBG6497A]

TP

RENT A CAR LEASING PTE LTD May 18 2018 12:00AM [FUNG KOK VUI] Reliable Carz Pte Ltd

From

LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 24/05/2018 15:42 PM.

То

christina_wong@sg.msig-asia.com

CC

sur@lkkauto.com

Subject

SJP1907A [FBG6497A]

Dear Christina,

Please be informed that we have inspected the vehicle SJP 1907A on 22/05/2018.

We are still pending estimate from repairer.

Thank you.

Jannice

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or witholding of material facts may allow insurance companies to regudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCID	ENIT	CTAT	EM	ENT
ACCID	- 1	SIVI	34	

Date Of Report

21/05/2018 10:47

Date Of Accident

18/05/2018 16:30

Exact Location Of Accident

PIE (CHANGI AIRPORT)

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SJP1907A

Insured/Policyholder

Name Of Registered Owner

RENT A CAR LEASING PTE LTD

Co Reg No

201529642E

Email Address

NOEMAIL

Mobile Phone No

Alternative Phone No

OFFICE-89999999

Vehicle Particulars

Manufacturer

HONDA

Model

AIRWAVE 1.5M A

Exact Purpose for which vehicle was being used at

time of accident

COMMERCIAL

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

THIRD PARTY FIRE AND/OR THEFT

Type Of Coverage

NO

Fleet Policy Policy Number

5092383531

Cover Note Number

Driver

YASIN BIN MOHD ZAIN

NRIC No Date Of Birth

Name of Driver

S1314512A

Occupation

26/05/1958 OUTDOOR

13/07/1988

Date Of Driving Pass

29 YEARS AND 10 MONTHS

Driving Experience Gender

MALE

Mobile Number

(LOCAL) +65-96197339

Fax Number

Contact Number

OFFICE-96197339

EMail Address

NOFMAIL

Address

BLK 43 CIRCUIT ROAD #02-685

370043

Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

OTHER - HIRER

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

100

GENDER: : FEMALE

Passenger 2

NAME:

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station Police Station Name

TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY

Police Station Address

ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

REFER TO POLICE REPORT - T/20180518/2144.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO FOOTAGE WITH TRAFFIC POLICE

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBG6497A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Page 2 of 31





T/20180518/2144

1 of 4

Report No. T/20180518/2144

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

REPORT	OF A	TRA	FFIC	ACCIDENT	

Vide Report No .: Station Diary No.: Date/Time Report Made: G/20180518/0153 18/05/2018 19:06 Informant's Particulars Name of Informant: Address: 43 CIRCUIT RD HDB-GEYLANG SINGAPORE 370043 Yasin Bin Mohd Zain ID Type / ID No .: Contact No.: Mobile: 96197339 Home/Office: NRIC NO / S1314512A Nationality: Email: SINGAPORE CITIZEN Type of Informant: Date of Birth: Sex: Age: 59 26/05/1958 Driver Male Institution / School Name: Language: Race: English Malay Driving Licence Information: Occupation: GRAB DRIVER Class: 2B,3 Date of Expiry:

DEPORT OFFICE

	1	lent	D-1-75	Type of Leasting	
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/05/2018 16:30	Type of Location Straight Road	
	EXPRESSWAY	ne 2 turning left to Chan	gi Airport.	oad Speed Limit:	
vveaulet.				oad Speed Limit.	
		Dry		oad Speed Limit.	
Sunny		5207	Т	raffic Volume:	
		Dry	1.000		

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
FBG6497A	Motorcycle				Slightly Damaged	0
SG5920A	Bus/Coach/Mi nibus				No Damage	0
SJP1907A	Car				Seriously Damaged	2

Details of Person Involved		
Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	






3 of 4

Report No. T/20180518/2144

Police Station Of Origin:
- Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT



REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$1314512A

YASIN BIN MOHD ZAIN



MALAY



YOU ARE LICE USED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

FASS DATE

Class 3 Motorcycles and exceeding 290 cc Class 3 Motor Cars and Motor Tractors the weight of wheth unladen does not exceed 2500 kilograms

27 Nov 1964 13 Jul 1968

17-06-1991 APT BLK 43 CIRCUIT ROAD #02-885 SINGAPORE 370043 NRIC No.: S1314512A Date: 22-07-2002 No.: 1256391

NP 428A

eBao									Gene	ralClaim
Hello, NAC_PAYA_UST_80	0601		111111111111111111111111111111111111111	of Statement			Change Lan	guage ,	Change Passwo	rd · Log Out
My Desktop Notice of Loss	Policy N	o No.(For Motor)	S3P1907A			Date of Acc	tident	18/05/	2018 16 30	3
					1	Search				
	Select	Policy No.	Policyholder Name	Palicyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	0	5092383531	RENT A CAR LEASING PTE LTD	2015296426	GPC	Third Party, Fire & Theft	53P1907A	S1P1907A	03/07/2017	01/07/2018
					E	Continue				


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID:	9642E	od alle
Vehicle Details		2000
Vehicle No.:	SJP1907A	
Vehicle to be Exported:	Yes	
Intended De-registration Date:	22 May 2018	
Vehicle Make:	HONDA	
Vehicle Model:	AIRWAVE 1.5M A	
Primary Colour:	Black	
Manufacturing Year:	2008	
Engine No.:	L15A5160339	
Chassis No.:	GJ11208732	
Maximum Power Output:	81.0 kW (108 bhp)	
Open Market Value:	\$14,718.00	
Original Registration Date:	02 Jul 2008	
First Registration Date:	02 Jul 2008	
Transfer Count:	2	
Actual ARF Paid:	\$14,718.00	
Intended PARF Repate Details		447
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	01 Jul 2018	
PARF Rebate Amount:	\$7,359.00	
Intended COE Rebate Details		All the
COE Expiry Date:	01 Jul 2018	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$14,101.00	
COE Rebate Amount:	\$152.00	
Total Rebate Amount:	\$7,511.00	

The information contained herein is correct as at 22 May 2018





Model ▼ Price ▼ ② Depreciation ▼ ② Reg Date ▼ ② Eng Cap ▼ ② Mileage ▼ ② Veh Type ▼ ② Status ▼ ③ For old advertisements, view Expired ads « Back (1 2) Next » 20 ▼ results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagens, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used airwave, airwave, Singapore, used airwave Singapore, used airwave, used airwave, used vehicles Singapore or even buy used airwave. Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car bunches and new car promotions. Visit our partner sites for job openings for Singapore Jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results,

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com 🛐 🗿 💆













About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2018 sgCarMart. All rights reserved.





RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875 Contact No.: +65 8166 9797 Fax No.: +65 6385 1751

Conta	ct No.: +65 8166 9/9/	Fax No., +03	0303 1/31		
10 M N 12 FEE 12		A LI LICAIDA AIRIA/AVE	TPMS 169		
Vehicl	e No.: SJP 1907A	Model: HONDA AIRWAVE	1		
OTV	DESCRIPTION		Jane	А	MOUNT (S\$)
QIT	DESCRIPTION List Items			_	
4	List Items: Rear bumper Reforme	d			1123.00 -
1	Rear bumper retainer R	H M			48.50 -
1	Rear bumper bracket Ri	No me			65.30 ×
1	Tailgate assy Penis				1435.00
1	Tailgate chrome mouldi	ing Z M ~			585.40 👉
1	Tailgate outer garnish				483.40 🐣
1		um			287.40
1	Tailgate emblem "AIRW	AVE" NIM-			48.50
1	Tailgate inner board up	per AU **	5091.70		303.30 ×
1	0	attered	39 /11 14		1830.00
1	Rear windscreen mould	ling NEC	399170 319336		68.70
1	Tailgate lamp RH	nur	3		323.00
1	Rear fender RH	duttand			1099.80
1	Rear fender glass RH	Shalled of			550.00 ×
1	Rear fender inner trim	RH XIII MOD		-	8689.00
			ì	ess 20 %	(1737.80)
			,	Subtotal	6951.20
				Subtotal	0931.20
	Special Nett Items:				
1	Tailgate glass sealant	3 New			80.00 60
1	Rear fender glass RH se	ealant J	- 4 -		80.00 40
1	Rear bumper clip (set)	Nen	360		60.00 30.
1	Reverse sensor	um			250.00 ×
1	Rear windscreen sealar	nt foam XXII			.40. 00 − ≟°
1	Rear windscreen glass	solar film M			450.00-200
				Subtotal	960.00
	Labour Charges:				
	To remove and refix re	ar windscreen			180.00 / 20
	To remove and refix re				120,00-40
Le e	To apply undercoating	pel amorata de producto de casa de producto	1120)	60.00 ×
the	To transfer tailgate me	S			180.00 ×
	To remove and refix re	ar fender glass RH			
• Thed by	T . 1 . 1 . 1	d refix above parts	total 46 (3)	70	800:00 300
No idega	To spray painting on a	ffected area	.10. 1.5K		1000.00-600
Supplem subject	entary nemissi must be resolveyed an tito final approval from Insurance Con	npany	total: 46733 LIS: 1.5K OH DO	Subtotal	2520.00
			0 H O	13	
Acknowled Signature:	iged by Repairer FSTIMATE PARTS	AND LABOUR GRAND	TOTAL SS	/	10431.20
Signature:	ESTIMATE PARTS	ALL LABOUR GRAND			389 ESTA COSTONIA (1987)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18009274/ARD3N2

Date:

MSD/VMFT/17-

985927

FBG6497A

02/07/2018

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte.

Claimant

Vehicle No: Date of Loss: SJP1907A

18/05/2018

Policy No: Insured Vehicle

No:

Nature of Claim:

Claim No:

MSC/V/18-000711

L15A5160339

GJ11208732

245047 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJP1907A

Make & Model: Reg. Date:

HONDA AIRWAVE, 1.5 M (A) 02/07/2008 (Man. Year: 2008)

Black 1496 cc

Engine Capacity: Market Value/New Car

Price:

Colour:

Sum Insured (S\$):

N/A

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Engine No:

Odometer:

Chassis No:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

185/60R15

Rear Tyre Size: Rear Left Side:

185/60R15

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,911.20	3,553.36	4,357.84	55.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,120.00	1,400.00	55.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,431.20	4,673.36	5,757.84	55.20
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	10,431.20	1,500.00	8,931.20	85.62

INSPECTION

Date of Assignment:

22/05/2018

Date Inspected:

22/05/2018

Inspected At:

Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50

Singapore 415875

Estimated Period of Repair:

4.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jul 2018)

Parts: M1-MPV HONDA AIRWAVE 1.5 M (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJP1907A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,123.00 FL	*1,123.00 FL
2	1		*REAR BUMPER RETAINER RH	Necessary	48.50 FL	*48.50 FL
3 4	1		*REAR BUMPER BRACKET RH *TAILGATE ASSY	Not Necessary Repair	65.30 FL 1,435.00 FL	*-FL
5 6	1		*TAILGATE CHROME MOULDING *TAILGATE OUTER GARNISH	Not Necessary Not Necessary	585.40 FL 483.40 FL	*-FL
7 8	1		*TAILGATE LAMP RH *TAILGATE EMBLEM AIRWAVE	Not Necessary Necessary	287.40 FL 48.50 FL	*- FL *48.50 FL
9 10	1		*TAILGATE INNER BOARD UPPER *TAILGATE GLASS	Not Necessary Shattered	303.30 FL 1,830.00 FL	*- FL *1,830.00 FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	68.70 FL	*68.70 FL
12	1		*TAILGATE LAMP RH	Cracked	323.00 FL	*323.00 FL
13 14	1		*REAR FENDER RH *REAR FENDER GLASS RH	Repair Shattered	1,099.80 FL 550.00 FL	*- FL *550.00 FL
15 16	1		*REAR FENDER INNER TRIM RH *TAILGATE GLASS SEALANT	Not Necessary Necessary	437.70 FL 80.00 FS	*-FL
17 18	1		*REAR FENDER GLASS RH SEALANT *SET REAR BUMPER CLIP	Necessary Necessary	80.00 FS 60.00 FS	*40.00 FS
19	1		*REVERSE SENSOR	Not Necessary 250.00 FS		
20	1		*REAR WINDSCREEN SEALANT FOAM	Necessary	40.00 FS	*30.00 FS
21 F=Fra	1 nchise ;	oart. S=SpcN	*REAR WINDSCREEN GLASS SOLAR FILM lett. L=ListItemDisc.	Necessary	450.00 FS	*200.00 FS
			- List Item Discount on L Items	Sub Total (S\$) 20.00/20.00% (S\$)	9,649.00 1,737.80	4,351.70 798.34
				Total Parts (S\$)	7,911.20	3,553.36

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	180.00	120.00
2	TO REMOVE AND REFIX REVERSE SENSOR SYSTEM	New	120.00	40.00
3	TO APPLY UNDERCOATING	New	60.00	02
4	TO TRANSFER TAILGATE MECHANISM	New	180.00	
5	TO RMEOVE AND REFIX REAR FENDER GLASS RH	New	180.00	60.00
6	TO JACKING, REMOVE AND REFIX ABOVE PARTS	New	800.00	300.00
7	TO SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	600.00
	Gross Labour Cost (S\$)		2,520.00	1,120.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >