



Pte Ltd

TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
3RD PARTY CLAIM ESTIMATION

China Taiping Insurance (Singapore) Pte Ltd
 105 Cecil Street #19-00
 The Octagon
 Singapore 069534

Vehicle number	SLE3830H
Make / Model	MAZDA/3
Chassis number	JM6BM42A8G0340276
Accident date	17 Ma7 2018
Reference	1805-29

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR LH FENDER <i>Dental</i>	592.30 ✓
1	REAR WINDSCREEN <i>huc</i>	488.20 ✗
1	REAR WINDSCREEN MOULDING <i>huc</i>	120.00 ✓
		1200.50
	Less 20%	240.10
	Subtotal	960.40
	Balance C/F	
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	
1	WINDSCREEN SEALANT <i>huc</i>	40.00
	Subtotal	150.00 <i>40/-</i>
	Balance C/F	1110.40
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	
1	REMOVE, RENEW AND REFIT NEW WINDSCREEN	200.00 <i>120/-</i>
	Subtotal	200.00
	Grand total	1310.40

729.84

ryan

Lkk Auto

[Signature]