

CC CASE OWNER:

Joint

CC 4/EQ1800 9280, 11/6/18

LKK:

IDAC:

Surveyor:

MARINS

DOI:

ASSIGNMENT

21/5/18

Date / Time:

21/5/18

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

GX 2232A

Name of Insured:

SWEET LIAN FASHION

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

16/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO: Driver Name / Age:

UM KUI BIN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

01MS1100164(07)

Policy No.:

01MS1100164(07)

Make / Model:

NISSAN

Place of Accident:

ADMIRALTY RD.

OI GIA REPORT: YES / NO

YES

TP GIA REPORT: YES / NO

YES

Insured Liability:

%

Final? Yes / No

JSH 4946



INSRS:

WSP:

Tel:

Liability:

RMKS:

Eratia



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

21/5/18
vian

Receive PIR from P.

exp was changed by T.P undercarriage driving.

LOD

After repair photo

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

9/10/18
10/10/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

21/5/18

Sent By:

Dre

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 2,000.00

(4 days)

Reduction: 62%

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

21.1.2019

Confirm with:

Lee Lee

Email ☒ Call ☐

Final Liability:

SS 100

(Agreed / Assessed)

BOLA S/N No.: NIL

If NO or B 28, Ass. Lia:

Repair Cost:

SS 2,000.00

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 110.00

(510.00 x 6 days)

Loss of Income (LOI):

SS -

(5 x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

Total:

SS 2,110.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

SS 2,110.00

Name 1:

Eratia Motor Trading Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

Tp

3) Survey fee:

\$400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ18009280/Uwb3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Date : 22-05-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 2232A	Veh. Inspected	JSH 4956
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	18/05/2018	Inspection Date	22/05/2018
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQ118009280/Uwb3

Date: 23.05.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

JSH4956

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.05.2018 at the premises of M/s Erofia Motor Trading Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,318.70
Revised Estimate Amount	: S\$	2,072.10
"Check" Items Amount	: S\$	553.50
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front Portion & N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Chan Chin Keat

Accident Date : 16-May-18

Vehicle No : JSH 4956

Vehicle Model : Yamaha YZF R25

Estimated Repair Costs

Qty	Description List Items		Amount S(\$)
1	Windshield	not attached	155.00
1	Top fairing	new	285.00
1	Front fender	new	90.00
2	Fork inner tubes	2	440.00
2	Fork outer tubes	2	480.00
1	Fork under bracket	1	225.00
1	Front brake disc	1	360.00
1	Front rim shaft	1	48.00
1	Front rim bearing	1	38.00
1	Side mirror -L/H	2	78.00
1	Headlamp	1	380.00
1	Lamp stay	1	90.00
1	Handle bar -L/H	2	125.00
1	Handle bar end	2	35.00
1	Hand grip (1 set)	1	48.00
1	Clutch lever	1	45.00
1	Front signal	1	68.00
1	Headlamp outer garnish	1	158.00
1	Side panel -L/H	2	135.00
1	Side outer fairing -L/H	2	225.00
1	Side inner fairing	1	185.00
1	Centre inner fairing	1	145.00
1	Lower fairing	1	190.00
1	Front footrest -L/H	1	50.00
1	Front footrest bracket	1	90.00
1	Gear pedal	1	45.00
1	Rear footrest -L/H	1	60.00
1	Rear footrest bracket	1	155.00
1	Rear tailboard	1	105.00
1	Rear fender	1	85.00
1	Fuel tank side cover	1	215.00
			4,833.00
		Less 10%	483.30
			4,349.70

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Chan Chin Keat

Accident Date : 16-May-18

Vehicle No : JSH 4956

Vehicle Model : Yamaha YZF R25

Estimated Repair Costs

<u>Special Nett Items</u>			
1	Number plate (1 set)	RM \$ 10	28.00
2	Fork oils	RM \$	30.00 ✓
2	Fork oil seals	RM \$	56.00 ✓
1	Steering cone (1 set)	RM \$	95.00 ✓
1	ERP IU	RM \$	170.00 X
1	Swing arm slider (1 set)	RM \$	80.00 ✓
		\$	459.00

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service.	\$ 35	50.00
2	To check wiring and reset headlamp focusing.	\$ 11 X	80.00
3	To provide labour.	\$ 320	380.00
		\$	510.00

Grand Total \$ 5,318.70

25/5-1

Dollars: Five Thousand Three Hundred Eighteen And Seventy Cents Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

EQ

Name : Chan Chin Keat

Accident Date : 16-May-18

Vehicle No : JSH 4956

Vehicle Model : Yamaha YZF R25

Estimated Repair Costs

Qty	Description		Amount S(\$)
	<u>List Items</u>		
1	Windshield	not added	155.00 ✓
1	Top fairing	✓	285.00 ✓
1	Front fender	✓	90.00 ✓
2	Fork inner tubes	✓	440.00 ✓
2	Fork outer tubes	✓	480.00 ✓
1	Fork under bracket	✓	225.00 ✓
1	Front brake disc	✓	360.00 ✓
1	Front rim shaft	✓	48.00 ✓
1	Front rim bearing	✓	38.00 ✓
1	Side mirror -L/H	✓	78.00 ✓
1	Headlamp	✓	380.00 ✓
1	Lamp stay	✓	90.00 ✓
1	Handle bar -L/H	✓	125.00 ✓
1	Handle bar end	✓	35.00 ✓
1	Hand grip (1 set)	✓	48.00 ✓
1	Clutch lever	✓	45.00 ✓
1	Front signal	✓	68.00 ✓
1	Headlamp outer garnish	✓	158.00 ✓
1	Side panel -L/H	✓	135.00 ✓
1	Side outer fairing -L/H	✓	225.00 ✓
1	Side inner fairing	✓	185.00 ✓
1	Centre inner fairing	✓	145.00 ✓
1	Lower fairing	✓	190.00 ✓
1	Front footrest -L/H	✓	50.00 ✓
1	Front footrest bracket	✓	90.00 ✓
1	Gear pedal	✓	45.00 ✓
1	Rear footrest -L/H	✓	60.00 ✓
1	Rear footrest bracket	✓	155.00 ✓
1	Rear tailboard	✓	105.00 ✓
1	Rear fender	✓	85.00 ✓
1	Fuel tank side cover	✓	215.00 ✓
		S	4,833.00
		Less 10%	483.30
		S	4,349.70

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Chan Chin Keat

Accident Date : 16-May-18

Vehicle No : JSH 4956

Vehicle Model : Yamaha YZF R25

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	net	\$ 10	28.00
2	Fork oils	net	\$	30.00
2	Fork oil seals	net	\$	56.00
1	Steering cone (1 set)	net	\$	95.00
1	ERP IU	11	\$	170.00
1	Swing arm slider (1 set)	cu)	\$	80.00
				<u>\$ 459.00</u>

S/No.

Labour

1	To provide towing service.	\$ 35	50.00
2	To check wiring and reset headlamp focusing.	\$ 11X	80.00
3	To provide labour.	\$ 300	380.00
		<u>\$</u>	<u>510.00</u>

Grand Total

\$ 5,318.70

Dollars: Five Thousand Three Hundred Eighteen And Seventy Cents Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Catherine Chong (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Tuesday, 22 May, 2018 11:10 AM
To: assignments
Cc: SUR
Subject: FW: Our ref:DM18HO01264/JT: Request Pre-repair inspection for accident involving GX2232A and JSH4956 on 16 May 2018
Attachments: GX2232A.PDF; JSH4956 - DOC.PDF

Dear all,

Attach both parties' report and estimate.

Please arrange to attend to this PRS as SJE.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

22052018 @ 12:01pm
LeeLee veh in
marus

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Erofia Motor - LeeLee Tan [mailto:erofia@singnet.com.sg]
Sent: Tuesday, May 22, 2018 11:07 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: RE: Our ref:DM18HO01264/JT: Request Pre-repair inspection for accident involving GX2232A and JSH4956 on 16 May 2018

Dear Janet

Kindly arrange LKK Auto Consultants Pte Ltd

Thank you

Regards
LeeLee Tan
Erofia Motor Trading Pte Ltd
Tel: 67527740
Fax: 67528669

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]

Sent: 22 May, 2018 10:16 AM

To: erofia@singnet.com.sg; EQI PRS <EQIPRS@eqinsurance.com.sg>

Subject: Our ref:DM18HO01264/JT: Request Pre-repair inspection for accident involving GX2232A and JSH4956 on 16 May 2018

Without Prejudice
Save As To Costs

Dear Lee Lee

For Pre repair survey request, please email to eqiprs@eqinsurance.com.sg

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify ti

From: Erofia Motor - LeeLee Tan [<mailto:erofia@singnet.com.sg>]

Sent: Tuesday, May 22, 2018 10:11 AM

To: EQI PRS <EQIPRS@eqinsurance.com.sg>

Subject: Request Pre-repair inspection for accident involving GX2232A and JSH4956 on 16 May 2018

Dear Sir

Attached necessary documents for your arrangement of pre-repair inspection for

Motorcycle No: JSH4956

Workshop:

Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62

AutoBay @ Kaki Bukit

Singapore 417883

Tel: 67527740

Thank you

Regards

LeeLee Tan

Erofia Motor Trading Pte Ltd

Tel: 67527740

Fax: 67528669

Poh Kin (LKKAUTO)

From: Erofia Motor - LeeLee Tan <erofia@singnet.com.sg>
Sent: Thursday, 31 January 2019 12:44 PM
To: Poh Kin (LKKAUTO)
Subject: RE: RTA involving vehicle nos. GX 2232A and JSH 4956 on 16/05/2018
Categories: clear

Without Prejudice

Dear Poh Kin

My client does not agreed to the offer on loss of use

For an amicable settlement, we propose close case at S\$2,120.00 All-in for both cost of reair and loss of use

Kindly confirm acceptance

Thank you

Regards
LeeLee Tan
Erofia Motor Trading Pte Ltd
Tel: 67527740
Fax: 67528669

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: 31 January, 2019 11:17 AM
To: erofia@singnet.com.sg
Subject: RTA involving vehicle nos. GX 2232A and JSH 4956 on 16/05/2018
Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/EQ18009280/Uwb3
Your Ref: JSH 4956

Dear Lee Lee,

We refer to the above matter.

Purely towards an amicable settlement, we offer settlement at global sum of **\$2,100.00**(all in) on this matter.

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Thursday, 31 January 2019 11:17 AM
To: 'erofia@singnet.com.sg'
Subject: RTA involving vehicle nos. GX 2232A and JSH 4956 on 16/05/2018

Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/EQI18009280/Uwb3
Your Ref: JSH 4956

Dear Lee Lee,

We refer to the above matter.

Purely towards an amicable settlement, we offer settlement at global sum of **\$2,100.00**(all in) on this matter.

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Erofia Motor - LeeLee Tan [<mailto:erofia@singnet.com.sg>]
Sent: Thursday, 31 January 2019 10:32 AM
To: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Subject: LOD for JSH4956



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6259
www.police.gov.sg

Our Ref : TP/IP/28977/2018
Date : 27 June, 2018

CHAN CHIN KEAT
BLK 1002 TOA PAYOH INDUSTRIAL PARK
#01-1467
SINGAPORE 319074

Dear Sir/Madam

**ACCIDENT INVOLVING GX2232A AND JSH4956 ON 16/05/2018 AT 0800 HRS, ALONG
ADMIRALTY ROAD**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of GX2232A had committed an offence of Inconsiderate Driving under Section 65(b) of the Road Traffic Act Chapter 276. Action has been initiated against the said driver for the said offence.
3. If you have any queries, please contact the Investigation Officer, Tan Chin Yong at telephone 65476178.

Yours faithfully

Juremah Ahmad SSI(2)
For Head, Traffic Investigation
Traffic Police
Singapore Police Force

Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67527740 Fax: 67528669
E-Mail: erofia@singnet.com.sg
Co Registration No: 201202259N

Our Ref: EMT1318/18/lt/JSH4956

WITHOUT PREJUDICE

Your reference: To Be Advised

BY HAND TO LKK

13 June 2018

EQ Insurance Co Ltd
5 Maxwell Road #17-00
Tower Block MND Building
Singapore 069110

Attn: Officer-In-Charge (Motor Claims Department)

Dear Sir/Madam

Re: ACCIDENT INVOLVING GX2232A AND JSH4956 ON 16 MAY 2018

We are instructed by our client Chan Chin Keat to claim damages against your insured GX2232A in connection with a road traffic accident on 16 May 2018 at about 08.00hours along Admiralty Road with our client's motorcycle registration number JSH4956

As a result of the accident, our client's motorcycle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1.	Cost of Repair as per surveyor's recommendation	S\$ 2,000.00
2.	Loss of Use (6 days X S\$20.00/day) Repair & PRI	S\$ 120.00
	Total to Claim	<u>S\$ 2,120.00</u>

Attached final repair bill for your early process of our claim

Thank you

Yours faithfully
Erofia Motor Trading Pte Ltd

Teo Hwa Heng





Auto
Consultants
Pte Ltd

51 UBI AVE L, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/EQ118009280/Uwb3

10 October 2018

Swee Chan Fashion

Blk 1014 Geylang East Ave 3

#04-226

Singapore 389729

Dear Sir/Madam,

ACCIDENT INVOLVING GX 2232A AND JSH 4956 ON 16/05/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau

Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67527740 Fax: 67528669
Co Registration No: 201202259N


AUTHORISATION TO ACT

I/We, Chan Chin Keat ("the third party claimant") of
24 In Anggerik 25 Taman Johor Jaya 81100 Johor (address), owner of
ISH 4956 (vehicle no.) hereby authorize Erofia Motor Trading Pte Ltd ("the
workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of
use ("claim") for my vehicle no. ISH 4956. That was damaged pursuant to the
accident which occurred on 16 05 2018 (date)
Along Admiralty Road (location) involving vehicle no/s
GX 2232 A ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deemed fit and the workshop is further authorized to receive payment further to settlement of my
claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the
other vehicle/s is concerned.

Dated this 20 (day) of 05 (month) 20 18 (year)


Signed by "the third party claimant"
(With company stamp if applicable)


Signed by "the workshop"
(With company stamp)

Provide always that this discharge of my
claim for damages relating to the damage to
my vehicle shall not prejudice or affect or
preclude me from making a further claim for
general and special damages for my personal
injuries sustained in the same accident.

EROFIA MOTOR TRADING PTE LTD (201202259N)

1 Kaki Bukit Ave 6 #02-62
Singapore 417883
Tel: 67527740 Fax: 67528669
H/P: 90696165 (Mr Teo)

INVOICE

Number	Date	Page
059/18 (JSH4956)	13-Jun-18	1

VEHICLE NO: JSH4956
MAKE/MODEL: YAMAHA YZFR25
NAME: CHAN CHIN KEAT
ADDRESS: 24 JALAN ANGGERIK 25
TAMAN JOHOR JAYA
81100 JOHOR BAHRU JOHOR MALAYSIA

ACCIDENT INVOLVING GX2232A AND JSH4956 ON 16 MAY 2018

FINAL REPAIR BILL AS PER SURVEYOR'S RECOMMENDATION

S\$ 2,000.00

SUB-TOTAL: S\$ 2,000.00

SINGAPORE DOLLARS: TWO THOUSAND ONLY

TOTAL : S\$ 2,000.00

EROFIA MOTOR TRADING PTE LTD





**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6359
www.police.gov.sg

Our Ref : TP/IP/28977/2018
Date : 27 June, 2018

CHAN CHIN KEAT
BLK 1002 TOA PAYOH INDUSTRIAL PARK
#01-1467
SINGAPORE 319074

Dear Sir/Madam

**ACCIDENT INVOLVING GX2232A AND JSH4956 ON 16/05/2018 AT 0800 HRS, ALONG
ADMIRALTY ROAD**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of GX2232A had committed an offence of Inconsiderate Driving under Section 65(b) of the Road Traffic Act Chapter 276. Action has been initiated against the said driver for the said offence.
3. If you have any queries, please contact the Investigation Officer, Tan Chin Yong at telephone 65476178.

Yours faithfully

Juremah Ahmad SSI(2)
For Head, Traffic Investigation
Traffic Police
Singapore Police Force



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 01/03/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GX 2232A (Insd Veh)	Your Ref. No. : DM18HO01264/JT
	JSH 4956 (TP Veh)	Our Ref. No. : CC4/EQI18009280/Ufb3q2
Date of Accident	16/5/2018	

Liability	100%	
Final Repair Cost	: \$ 2,000.00	
Loss of Use	: \$ 120.00	6 days
Rental (If any)	: \$	days
Others:	: \$	
	: \$	
	2,120.00	
Final Settlement Sum	: \$ 2,120.00	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	EROFIA MOTOR TRADING PTE LTD	: \$ 2,120.00
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI18009280/Ufb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 01-03-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 2232A	Veh. Inspected	JSH 4956
Policy No.	DMCPHQ18-000825	Coverage (\$)	0.00
Claim No.	DM18HO01264/JT	Excess (\$)	0.00
Assign From	JANET	Assign Date	22/05/2018

2. Vehicle Particulars & Condition

Make & Model	YAMAHA YZF-R25	c.c	250
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	PMYRG1510H0010953	Colour	BLUE
Odometer	18842	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110-70-17	BRIDGESTONE	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	160-60-17	BRIDGESTONE	7 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/05/2018	Inspection Date	22/05/2018
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JSH 4956

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	WINDSHEILD	CRACKED	155.00	155.00
1	TOP FAIRING	CRACKED	285.00	285.00
1	FRONT FENDER	CUT	90.00	90.00
2	FORK INNER TUBES	TO REPAIR SEE LABOUR	440.00	-
2	FORK OUTER TUBES	TO REPAIR SEE LABOUR	480.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	225.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	360.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	48.00	-
1	FRONT RIM BEARING	NOT NECESSARY	38.00	-
1	SIDE MIRROR -L/H	CUT	78.00	78.00
1	HEADLAMP	BROKEN	380.00	380.00
1	LAMP STAY	CRACKED	90.00	90.00
1	HANDLE BAR -L/H	BENT	125.00	125.00
1	HANDLE BAR END	SCRATCHED	35.00	35.00
1	SET HAND GRIP	NOT NECESSARY	48.00	-
1	CLUTCH LEVER	SCRATCHED	45.00	45.00
1	FRONT SIGNAL	BROKEN	68.00	68.00
1	HEADLAMP OUTER GARNISH	CRACKED	158.00	158.00
1	SIDE PANEL -L/H	CUT	135.00	135.00
1	SIDE OUTER FAIRING -L/H	CUT	225.00	225.00
1	SIDE INNER FAIRING	TWISTED	185.00	185.00
1	CENTRE INNER FAIRING	TO REPAIR SEE LABOUR	145.00	-
1	LOWER FAIRING	TO REPAIR SEE LABOUR	190.00	-
1	FRONT FOOTREST -L/H	NOT NECESSARY	50.00	-
1	FRONT FOOTREST BRACKET	NOT NECESSARY	90.00	-
1	GEAR PEDAL	BENT	45.00	45.00
1	REAR FOOTREST -L/H	NOT NECESSARY	60.00	-
1	REAR FOOTREST BRACKET	NOT NECESSARY	155.00	-

Report Ref No. CC4/EQ18009280/Ufb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILBOARD	TO REPAIR SEE LABOUR	105.00	-
1	REAR FENDER	NOT NECESSARY	85.00	-
1	FUEL TANK SIDE COVER	TO REPAIR SEE LABOUR	215.00	-
	LESS 10% DISCOUNT		-483.30	-209.90
			4,349.70	1,889.10
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE (SN)	NECESSARY	28.00	10.00
2	FORK OILS (SN)	NECESSARY	30.00	30.00
2	FORK OIL SEALS (SN)	NECESSARY	56.00	56.00
1	SET STEERING CONE (SN)	NECESSARY	95.00	95.00
1	ERP IU (SN)	NOT NECESSARY	170.00	-
1	SET SWING ARM SLIDER (SN)	CUT	80.00	80.00
			459.00	271.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF FORK INNER TUBES,FORK OUTER TUBES,CENTRE INNER FAIRING,LOWER FAIRING,REAR TAILBOARD AND FUEL TANK SIDE COVER.		380.00	320.00
			510.00	355.00
GRAND TOTAL			5,318.70	2,515.10

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	-----------------

Report Ref No. CC4/EQ118009280/Ufb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.