

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)11/5/2018
morning & repin
Hetz

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

21 MAY 2018

@ 6pm

Estimate No. : b1 47020	Page No. : 1 of 2
Date Estimated : 21/05/2018	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Chia Wee Jin Christopher 65 Jalan Leban Singapore 577602	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJT707X	DX82710	26/09/2012	528ia	0

DESCRIPTION	VALUE
Replace front M bumper and remove attachment etc include knock on accident dent	850 1,275.00
Spray painting front bumper	934 1,038.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
Sundries.	40.00
Body outer quoting sealant from outside workshop	150.00
Total Labour 1:	2,680.00

DESCRIPTION	QTY	PRIC	VALUE
GRILLE AIR INLET RH (M)	1	63.30	X63.30
COVERING TOWING FRT PRIMED (M)	1	55.70	X55.70
COVERING RH (M)	1	46.65	X46.65
FRT TRIM COVER BUMPER PRIMERED (M S	1	1,533.10	Rx 1,533.10
BUMPER RIVET	2	0.50	? 1.00
SET MOUNTS PDC SENSOR FRT (M)	1	31.65	? 31.65
EMBLEM GROMMET	2	0.80	wei 1.60
BMW EMBLEM	1	69.50	wei 69.50
Total Parts :			1,802.50

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 47020**
Date Estimated : **21/05/2018**
Prepared By : **Chua Kee Sin**

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJT707X	DX82710	26/09/2012	528iA	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 11/6/18 09:11am Excess S\$ _____

Surveyor's Name Tanpin Sign [Signature]

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tanpin@pml.com.sg

No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	2,680.00
Parts	:	1,802.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	313.78
Grand Total	:	4,796.28

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **