



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

19/05/2018

AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
AXA TOWER #27-01
SINGAPORE 068811

Attention :- XA009

Page # :- 1

Veh # :- SBT961Y

Veh Model :- T/COROLLA 1.6

Estimate# :- CK417461

Claim # :-

ACC. Date :- 17/05/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	BONNET (REPAIR)	1 PC		Ry
2.	HEADLAMP ASSY RH	1 PC	2,795.00	cut 2,795.00
3.	FRONT BUMPER	1 PC	485.00	de 485.00
4.	FRONT BUMPER LOWER GARNISH RH - CHECK	1 PC		
5.	FRONT BUMPER RETAINER RH	1 PC	81.70	nei 81.70
6.	FRONT BUMPER CLIPS	10 PC	5.00	nei 50.00
7.	FRONT FENDER RH	1 PC	781.20	bt 781.20
8.	FRONT FENDER COWLING RH	1 PC	200.90	de 200.90
9.	FRONT FENDER CORNER GARNISH RH	1 PC	56.00	nei 56.00
10.	FRONT FENDER COWLING CLIPS	10 PC	5.00	nei 50.00
11.	FRONT FENDER EMBLEM - VVTI RH	1 PC	45.00	nei 45.00
12.	FRONT FENDER INNER PANEL RH	1 PC	450.00	Ry 450.00
13.	FRONT CHASSIS MEMBER RH (REPAIR)	1 PC		
14.	FRONT SPORT RIM RH	1 PC	1,645.10	de 1,645.10
15.	FRONT KNUCKLE BEARING RH	1 PC	95.90	bt 95.90
16.	FRONT KNUCKLE HUP RH	1 PC	220.00	bt 220.00
17.	FRONT KNUCKLE ARM RH	1 PC	521.50	?
18.	FRONT SHOCK ABSORBER RH	1 PC	398.50	?
19.	FRONT SHOCK ABSORBER TOP MOUNTING RH	1 PC	125.70	bt 125.70
20.	FRONT LOWER ARM RH	1 PC	536.00	bt 536.00
21.	FRONT LOWER ARM BALL JOINT RH	1 PC	95.90	bt 95.90
22.	FRONT DRIVE SHAFT RH	1 PC	1,301.00	?
23.	STEERING RACK & PINION	1 PC	1,621.30	?
24.	FRONT CROSS MEMBER - CHECK	1 PC		
25.	ENGINE MOUNTING RH	1 PC	375.00	?
26.	ENGINE MOUNTING REAR	1 PC	298.00	?
27.	ENGINE MOUNTING LH	1 PC	266.70	?
28.	ENGINE MOUNTING FRONT	1 PC	200.00	?
29.	FRONT DOOR PILLAR RH (REPAIR)	1 PC		
30.	FRONT DOOR RH	1 PC	1,100.00	bt 1,100.00
31.	FRONT DOOR MIRROR RH - CHECK	1 PC		
32.	FRONT DOOR STICKER RH	1 PC	50.00	?
33.	FRONT DOOR HINGE TOP RH	1 PC	95.50	?
34.	FRONT DOOR CHECKER RH - CHECK	1 PC		
35.	FRONT DOOR HINGE BOTTOM RH	1 PC	95.50	?
36.	REAR DOOR RH	1 PC	1,100.00	bt 1,100.00
37.	CENTER PILLAR RH (REPAIR)	1 PC		
38.	REAR DOOR STICKER	1 PC	60.00	nei 60.00
39.	REAR DOOR GLASS REGULATOR - CHECK	1 PC		
40.	REAR DOOR GLASSREGULATOR MOTOR - CHECK	1 PC		
LIST TOTAL S\$				15,196.40
25% DISCOUNT S\$				-3,799.10
				11,397.30
SPECIAL NET ITEMS :				
1.	FRONT TYRE RH MICHELIN 205/55A16	1 PC	250.00	cut 250.00
2.	FRONT DOOR SUN VISOR RH	1 SET	200.00	4 7 200.00



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

19/05/2018

AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
AXA TOWER #27-01
SINGAPORE 068811

Attention :- XA009

Page # :- 1 131579

Veh # :- SBT961Y

Veh Model :- T/COROLLA 1.6

Estimate# :- CK417461

Claim # :-

ACC. Date :- 17/05/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	SPECIAL NET TOTAL S\$			450.00
	LABOUR :			
	TOWING CHARGE			✓ 60.00
	TO CUT/WELD FRONT FENDER INNER PANEL RH ,			1000
	KNOCK AND STRAIGHTEN HEADLAMP PANEL, FRONT			800
	DOOR OILLAR RH, CENTER PILLAR RH, REAR FENDER			
	RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS			
	REALIGN ALL CONNECTION			1,200.00
	SPRAY PAINT BONNET SUPPORT PANEL, FRONT			
	BUMPER, FRONT FENDER RH, FRONT DOOR PILLAR RH			1200
	FRONT DOOR RH, ROCKER PANEL RH, REAR DOOR RH			1,600.00
	REAR FENDER RH			
	REMOVE & REPLACE FRONT UNDER CARRIAGE			
	SUSPENSION, FRONT CROSS MEMBER			? photo 200 380.00
	REMOVE & REPLACE FRONT DOOR INNER TRIM,			
	COVERING RH			✓ 50.00
	REMOVE & REPLACE ENGINE MOUNTING BRACKET			
	HOLDER			? photo 150.00
	REMOVE AND REPLACE FRONT AND REAR DOOR			60.
	MECHANISM AND CHECK LOCKING SYSTEM			100.00
	CHECK CHASSIS ALIGNMENT ON LASER LOCK MACHINE			repat./photo? 350.00
	CHECK WIRING & FOCUS HEADLIGHT			20. 40.00
	COMPUTER WHEEL ALIGNMENT			✓ 60.00
	RUST PROOF AFFECTED AREAS			60. 100.00
	LABOUR TOTAL S\$			4,090.00



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

19/05/2018

AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
AXA TOWER #27-01
SINGAPORE 068811

Page # :- 1 131579

Veh # :- SBT961Y

Veh Model :- T/COROLLA 1.6

Estimate# :- CK417461

Claim # :-

ACC. Date :- 17/05/18

Terms :- C.O.D Days

Remarks :-

Attention :- XA009

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 15,937.30

GST @ 7 % 1,115.61

AMOUNT DUE S\$ 17,052.91

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damage for survey
- Parts prices on a
- Third party settlement on a basis
- No illegal market
- Supplemental
- is subject to final

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495449
WP
21/5/18 @ 645
Resurvey before paint
sur @ lkkauto.com