

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

AXA INSURANCE SINGAPORE PTE LTD
 8, SHENTON WAY #27-01
 AXA TOWER, SINGAPORE 068811.
 MOTOR CLAIM FAX NO. 68804838

Attention : Motor Claim Department

Contact : 63387288/18008804741 68804070 Fax No. : 63382522

Estimate : ES004377

Date : 21/05/2018
 Vehicle Num. : SJZ 6230 H
 Make/Model : MAZDA 3
 Chassis/Eng# :
 Accident Date : 14/03/2018
 Claim No. :
 Reference : KC/TP6230/1805-03
 Policy No. :

QTY	Quantity	Particular	Unit Price	Amount S\$
1.	1 PC	LIST ITEMS :		
2.	2 PCS	REAR BUMPER		1,049.80 ✓
3.	1 PCS	REAR BUMPER RETAINER	37.00	74.00 X
4.	1 PC	REAR BUMPER REFLECTOR	59.20 RH-AL	118.40 X
5.	1 PC	REAR BUMPER REINFORCEMENT		529.60
6.	1 PC	REAR END PANEL		409.30
7.	1 PC	REAR END PANEL GARNISH		193.30
7.	1 SET	REAR NUMBER PLATE LAMP		155.60 ?
		List Total S\$:		2,530.00
		20.00% Discount S\$:		506.00
				2,024.00
1.	1 SET	SPECIAL NETT ITEMS :		
2.	1 PC	REVERSE SENSOR		280.00 220.00 ?
		REAR NUMBER PLATE		50.00 35.00 ?
		Special Nett Total S\$:		330.00
		LABOUR :		
		TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.		480.00 300
		TO SPRAY & PAINT ON REAR ACCIDENT PORTION.		580.00 400
		TO ANTI-RUST REAR AFFECTED AREAS.		60.00 40

CONTINUE / ...

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

AXA INSURANCE SINGAPORE PTE LTD
 8, SHENTON WAY #27-01
 AXA TOWER, SINGAPORE 068811.
 MOTOR CLAIM FAX NO. 68804838

Attention : Motor Claim Department

Contact : 63387288/18008804741 68804070 Fax No. : 63382522

Estimate : ES004377

Date : 21/05/2018
 Vehicle Num. : SJZ 6230 H
 Make/Model : MAZDA 3
 Chassis/Eng# :
 Accident Date : 14/03/2018
 Claim No. :
 Reference : KC/TP6230/1805-03
 Policy No. :

Quantity	Particular	Unit Price	Amount S\$
----------	------------	------------	------------

TO CHECK WIRING FUNCTIONS.

60.00

TO DISMANTLE & REFIX REVERSE SENSOR.

80.00

Labour Total S\$:

1,260.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
Hp 90010068
3 days
4/3
22/05/18 @ 1210
Resurvey after repair

SingDollars : Three Thousand Six Hundred Fourteen Only

Total S\$: 3,614.00

KUM CHEW MOTOR WORKSHOP