

**MG SOLUTION PTE LTD**

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO : AXA INSURANCE SINGAPORE PTE LTD DATE : 21/05/2018

ATTENTION : MOTOR CLAIMS DEPT

JOB TYPE : TP CLAIM

ESTIMATE REPORT :

**VEHICLE DETAILS**

VEHICLE NO : SJS8480B

MODEL : HONDA FREED 1.5G A

CHASSIS NO

**ACCIDENT DETAILS**      DATE : 13-May-18  
    TIME : 12:10HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**CLAIM DETAIL : PARTS**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR SLIDING DOOR RH / <i>free</i>	1	\$ 1,320.00	\$ 1,320.00
2	REAR SLIDING DOOR MOTOR RH <i>3 Jammed</i>	1	\$ 980.00	\$ 980.00
3	REAR BUMPER <i>X R</i>	1	\$ 1,055.00	\$ 1,055.00
4	REAR FENDER RH <i>Repair X</i>	1	\$ 1,255.30	\$ 1,255.30
5	REAR WHEEL HUP LH <i>X NN</i>	1	\$ 260.00	\$ 260.00
6	REAR WHEEL HUP BEARING LH / <i>MC</i>	1	\$ 222.00	\$ 222.00
7	REAR SHOCK ABSORBER LH <i>X NN</i>	1	\$ 530.00	\$ 530.00
8	REAR AXLE <i>X</i>	1	\$ 1,800.00	\$ 1,800.00

TOTAL PRICE \$ 7,422.30

LESS 20% \$ 1,484.46

SUB TOTAL PRICE \$ 5,937.84 *2861.60***SPECIAL NETT ITEMS**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS / <i>MC</i>	1	\$ 20.00	\$ 20.00
2	FRONT FENDER SEALANT <i>X NN</i>	2	\$ 60.00	\$ 120.00
3	TYRE RIM ( 1 SET) / <i>CA</i>	1	\$ 800.00	\$ 800.00
4	WHEEL TYRE <i>X NN</i>	1	\$ 350.00	\$ 350.00

TOTAL \$ 1,290.00 *300*

## CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	600	
3	WIRING CHECK	\$ 250.00	30	
4	FOUR WHEEL ALIGNMENT	\$ 120.00	60	
5	TO REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 250.00	X	NN
6	TO PRESS <sup>Rear</sup> FRONT WHEEL BEARING	\$ 150.00	50	
7	TO TRANSFER REAR DOOR MECHANISM	\$ 150.00	60	

TOTAL

\$3,120.00

## ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,227.84

TOTAL LABOUR COST : \$ 3,120.00

TOTAL REPAIR COST : \$ 10,347.84

## APPROVED DETAILS

SURVEYOR : Eno Qianp

CONTACT NO : 82880282

FAX : 2861.60

PART BY PART / LUMP SUM : L/S

NO OF DAYS :

5 Days.

After repair photos.

22/5/18

+ 320.00

+ 1300.00

4481.60

- 20% 896.32

3585.28

Lump Sum

\$ 3585

5 days