

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 28 May 2018

Preliminary Advice

Vehicle No	: SLK5145H	Accident Date	: 16/05/2018
Make	: JAGUAR XF	Policy No.	: DMHCSN1745941700
Assignment Date	: 23/05/2018	Excess	: S\$3,000.00
Date of Inspection	: 23/05/2018	Est. Duration of Repair	: -
Inspection At	: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412 SINGAPORE 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear, front portion & chassis frame affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair :S\$		

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 70,000.00
COE / PARF Rebate	:S\$ 61,320.00
Salvage Value	:S\$
Margin for Repair	:S\$ 8,680.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :