

AIG SINGAPORE PTE LTD78 Shenton Way
#07-16
Singapore 079120**ESTIMATE**VEHICLE NO. : SGS6938Y
CHASSIS NO : MR053HY4204218998
MAKE / MODEL : TOYOTA VIOS 1.5E A
DATE OF ACCIDENT : 16th MAY 2018 @ 1205hrs

YOUR INSURED VEHICLE NUMBER : S1913CD

<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>Price</u>	<u>Total Price</u>
FRONT BUMPER	1	\$ 550.00	\$ 550.00
RH FRONT FENDER	1	\$ 200.00	\$ 200.00
RH FRONT WHEEL HOUSING	1	\$ 300.00	\$ 300.00
RH FRONT WHEEL HOUSING COVER	1	\$ 40.00	\$ 40.00
RH FRONT WHEEL HOUSING CLIP	10	\$ 3.00	\$ 30.00
RH FRONT FENDER LAMP	1	\$ 30.00	\$ 30.00
RH FRONT DOOR ASSY	1	\$ 898.00	\$ 898.00
RH FRONT DOOR OUTER PANEL	1	\$ 500.00	\$ 500.00
RH FRONT DOOR PROTECTOR	1	\$ 60.00	\$ 60.00
RH FRONT DOOR WINDOW REGULATOR	1	\$ 150.00	\$ 150.00
RH FRONT DOOR WINDOW MOTOR	1	\$ 178.00	\$ 178.00
RH FRONT DOOR REMOTE LOCK	1 SET	\$ 258.00	\$ 258.00
RH FRONT PILLAR	1	\$ 275.00	\$ 275.00
RH REAR DOOR ASSY	1	\$ 898.00	\$ 898.00
RH REAR DOOR OUTER PANEL	1	\$ 500.00	\$ 500.00
RH REAR DOOR PROTECTOR	1	\$ 60.00	\$ 60.00
RH REAR DOOR WINDOW REGULATOR	1	\$ 150.00	\$ 150.00
RH REAR DOOR WINDOW MOTOR	1	\$ 178.00	\$ 178.00

Total Parts \$ 5,255.00**LABOUR CHARGES**TO SPRAY PAINT ON THE AFFECTED AREAS
TO REPAIR,REMOVE & REPLACE ALL THE DAMAGE ITEMS

	\$ 2,000.00
	\$ 2,500.00
Total Labour	\$ 4,500.00

Sub Total \$ 9,755.00

Prepared By : -

Lynn Ahmad

Motorway Car Care Centre Pte Ltd

TEL: 6571 9625

FAX : 6278 5535

EMAIL: lynn@motorway.com.sg

WEBSITE: www.motorway.com.sg