



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHONG CHEE HOE
BLK 627 PASIR RIS DRIVE 3 #12-330
SINGAPORE 510627

Attention : THE OWNER
Contact : 98331225

Estimate : ES006363

Date : 28/05/2018
Vehicle Num. : SLU45T
Make/Model : BMW 520I-2012
Chassis/Eng# : WBAXG12030DX51130/A9200304N20
Accident Date : 21/05/2018
Claim No. :
Reference :
Policy No. :

*Not Withheld
1/1 day & ?
Resurvey After Paint
4 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|-------------------------------|--|--|
| 1. | 1 | NETT ITEMS : | | |
| 2. | 1 | REAR DOOR R/H | | |
| 3. | 1 | REAR DOOR SURROUND RUBBER R/H | | |
| 4. | 1 | REAR SPORT RIM | | |
| | | REAR WHEEL BEARING R/H | | |

Red/way
1,660.00 ✓
nd 215.00 50%
980.00 ✓
481.00 ?

3,336.00
166.80

3,169.20

Nett Total S\$:
5.00% Discount S\$:

LABOUR :
RUST PROOFING TREATMENT
TRANSFER R/H REAR DOOR COMPONENTS TO NEW DOOR
SPRAY PAINT DAMAGED AREA AFFECTED
COMPUTER WHEEL ALIGNMENT
KNOCK OUT DENT ON R/H REAR FENDER.CHANGE R/H REAR DOOR
CHANGE R/H REAR WHEEL BEARING

nn 100.00 X
250.00 80%
800.00 40%
120.00 60%
750.00 40%
150.00 ?

2,170.00

Labour Total S\$:

SingDollars : Five Thousand Three Hundred Thirty-Nine & Cents Twenty Only

COMPLETE VMS PTE LTD

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 5,339.20

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun