

SERVICE ESTIMATE

82163 - C00001 SL: SERVICE SALES - PC

Mr Christopher Gill
22 Newton Road
#06-09

Singapore 307990

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 04/06/2018

WIP No. : 62197

Veh.In/Out:

*Tel.No. : -

Reg.No. : SKT7324J

Reg.date : 06/09/2010

Mileage : 0

Chassis No: YV1AS6050A1131845

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Christopher Gill

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BOOT LID, REAR EMBLEM,REAR BUMPER, REAR BRACKET,REAR LOWER SPOILER,ETC	0	3200.00	0		3,200.00 S	2400.
-----	---	---	---------	---	--	------------	-------

800	TO PUTTY SPRAY PAINT ON REAR BOOT LID,REAR BUMPER,REAR LOWER SPOILER,ETC	0	2800.00	0		2,800.00 S	2100
-----	--	---	---------	---	--	------------	------

802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00 S ✓	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S ✓	

BUMPER COVER REAR S8	1.0 EA	1454.80			1,454.80 S de ✓
BUMPER SPOILER REAR	1.0 EA	434.30			434.30 S de ✓
TOW COVER REAR S80 -	1.0 EA	73.90			73.90 S RY ✓
BUMPER BRACKET LHR C	1.0 EA	35.70			35.70 S ne ✓
V030655125/BUMPER BR	1.0 EA	35.70			35.70 S ne ✓
BUMPER BRACKET LHR S	1.0 EA	71.70			71.70 S ne ✓

L-5200
R-5319.3
? 1326.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97425749
"wp"
12/6/18
Resurvey before paint
5 days
sur @ Mwantan.com

SERVICE ESTIMATE

82163 - C00001 SL: SERVICE SALES - PC

Mr Christopher Gill

22 Newton Road

#06-09

Singapore 307990

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 04/06/2018

WIP No. : 62197

Veh.In/Out:

*Tel.No. : -

Reg.No. : SKT7324J

Reg.date. : 06/09/2010

Mileage : 0

Chassis No: YV1AS6050A1131845

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Christopher Gill

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET RHR S	1.0 EA	73.90			73.90	S nli
	BUMPER BRACKET REAR	1.0 EA	104.30			104.30	S nli
	BUMPER RAIL (BEAM) R	1.0 EA	1326.50			1,326.50	S ?
	BOOT REAR S80 07-	1.0 EA	2619.90			2,619.90	S bt
	EMBLEM <VOLVO> REAR	1.0 EA	92.00			92.00	S nli
	EMBLEM <2.5T> XC90/8	1.0 EA	84.00			84.00	S nli
	BLIND RIVET 4.0*21MM	10.0 EA	3.00			30.00	S nli
	BUMPER CLIP	10.0 EA	4.80			48.00	S nli
	BUMPER INSTALLING MT	1.0 EA	83.40			83.40	S nli
	ADHESIVE TUBE CHEMIC	2.0 EA	75.80			151.60	S nli

Gross Total. 13,419.70

Labour Total 6,700.00
Parts Total 6,719.70
Package Total 0.00

Net..... 13,419.70
GST @ 7.0% 939.38
Total..... 14,359.10
Paid..... 0.00
Please Pay.. 14,359.10

GST: S=StdRated; O=OutOfScope; Z=ZeroRated