

SERVICE ESTIMATE

82163 - C00001 SL: SERVICE SALES - PC

Mr Christopher Gill

22 Newton Road

#06-09

Singapore 307990

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 04/06/2018

WIP No. : 62197

Veh.In/Out:

*Tel.No. : -

Reg.No. : SKT7324J

Reg.date. : 06/09/2010

Mileage : 0

Chassis No: YV1AS6050A1131845

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Christopher Gill

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

302	TO REPLACE REAR BOOT LID, REAR EMBLEM,REAR BUMPER, REAR BRACKET,REAR LOWER SPOILER,ETC	0	3200.00	0		3,200.00	S
-----	---	---	---------	---	--	----------	---

2400 2160

300	TO PUTTY SPRAY PAINT ON REAR BOOT LID,REAR BUMPER,REAR LOWER SPOILER,ETC	0	2800.00	0		2,800.00	S
-----	--	---	---------	---	--	----------	---

2400 1890

502	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S

225.00

BUMPER COVER REAR SB	1.0 EA	1454.80				1,454.80	S
BUMPER SPOILER REAR	1.0 EA	434.30				434.30	S
TOW COVER REAR SBO -	1.0 EA	73.90				73.90	S
BUMPER BRACKET LHR C	1.0 EA	35.70				35.70	S
V030655125/BUMPER BR	1.0 EA	35.70				35.70	S
BUMPER BRACKET LHR S	1.0 EA	71.70				71.70	S

1091.10
de ✓
R
R
R
R
R
R

L-5200
R-5319.3
? 1326.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97425749

12/6/18
Resurvey before paint
5 days
surc lkkantago.com

SERVICE ESTIMATE

82163 - C00001 SL: SERVICE SALES - PC

Mr Christopher Gill

22 Newton Road

#06-09

Singapore 307990

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page, 2

Inv.date : 04/06/2018

WIP No. : 62197

Yeh.In/Out:

*Tel.No. : ~

Reg.No. : SKT7324J

Reg.date : 06/09/2010

Mileage : 0

Chassis No: YV1AS6050A1131845

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Christopher Gill

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	BUMPER BRACKET RHR S	1.0 EA	73.90				
	BUMPER BRACKET REAR	1.0 EA	104.30				
	BUMPER RAIL (BEAM) R	1.0 EA	1326.50				
	BOOT REAR S&O 07-	1.0 EA	2619.90				
	EMBLEM <VOLVO> REAR	1.0 EA	92.00				
	EMBLEM <2.5T> XC90/8	1.0 EA	84.00				
	BLIND RIVET 4.0*21MM	10.0 EA	3.00				
	BUMPER CLIP	10.0 EA	4.80				
	BUMPER INSTALLING MT	1.0 EA	83.40				
	ADHESIVE TUBE CHEMIC	2.0 EA	75.80				

73.90 \$ ~~net~~ ^{svl}
 104.30 \$ ~~net~~ ^{svl} 18-23
 1,326.50 \$ ~~net~~ ^{svl}
 2,619.90 \$ ~~net~~ ^{svl} 1964.93
 92.00 \$ ~~net~~ ^{svl}
 84.00 \$ ~~net~~ ^{svl}
 30.00 \$ ~~net~~ ^{svl}
 48.00 \$ ~~net~~ ^{svl}
 83.40 \$ ~~net~~ ^{svl}
 151.60 \$ ~~net~~ ^{svl}

Gross Total. 13,419.70

Labour Total 8,700.00

Parts Total 6,719.70

Package Total 0.00

Net..... 13,419.70

GST @ 7.0% 939.38

Total..... 14,359.10

Paid..... 0.00

Please Pay.. 14,359.10

GST: S=StdRated; O=OutOfScope; Z=ZeroRated