

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : **b1 47037**
Date Estimated : **22/05/2018**
Prepared By : **Gary Poh Chai Hoon**

Page No. :

REPAIR FOR -
Kemral Durgadas Shetty
Blk 305 Bukit Batok Street 31
#08-89

- ACCOUNT - 148376
Great American Insurance Company
3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190

Singapore 650305

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SFM7739S	NS37629	30/07/2014	316iA/4	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR PDC HOLDER SET *	23.10	1.00		23.10
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

Total Labour :	231.00
Total Parts :	76.15
Total Labour & Parts :	307.15