



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Buss.Reg.No.: 52888887X

Attn: Adrian

QUOTATION

No : QT-000138

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Xiao Tong

Your Ref. : SLN245U
 Vehicle No. : SFK8448K
 Make & Model : BMW 116D
 Chasis No. : WBA1V720X0V944674
 Engine No. : 39599887B37D15A
 Accident Date : 23-05-2018
 Policy No. : SD17V05753/VPC2/R00
 Date : 03-07-2018
 Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	FENDER (L/H/R) <i>Dented</i>	1.0 PCS	601.00	601.00 ✓
2	FENDER INNER GARNISH (L/H/R) <i>torn</i>	1.0 PCS	115.00	115.00 ✓
3	SIDE SKIRT (L/H) <i>Repair</i>	1.0 PCS	298.55	298.55 ✗
4	DOOR (L/H/R) <i>Dented</i>	1.0 PCS	1,157.10	1,157.10 ✓
5	DOOR INNER TRIM BOARD (L/H/R) <i>new</i>	1.0 PCS	1,043.05	1,043.05 ✗
6	DOOR INNER TRIM BOARD CLIP	8.0 PCS	5.25	42.00 ✗
7	DOOR WEATHER STRIP (L/H/R) <i>new</i>	1.0 PCS	65.45	65.45 ✓
8	DOOR FRAME BEADING (L/H/R) <i>new</i>	1.0 PCS	109.80	109.80 ✗
9	GARNISH (DOOR FRAME) (L/H/R) <i>delivered</i>	1.0 PCS	131.65	131.65 ✓
10	DOOR INNER LOCK (L/H/R) <i>Damaged</i>	1.0 PCS	341.85	341.85 ✓
11	DOOR CATCH (L/H/R)	1.0 PCS	76.25	76.25 ✗
12	DOOR HINGE (L/H LOWER) <i>new</i>	1.0 PCS	63.15	63.15 ✗
13	DOOR HINGE (L/H UPPER)	1.0 PCS	63.15	63.15 ✗
14	DOOR ANTI SPLASH FOAM (L/H/R) <i>new</i>	1.0 PCS	58.60	58.60 ✗
15	WINDOW REGULATOR (L/H/R) <i>Damaged</i>	1.0 PCS	254.05	254.05 ✓
16	WINDOW REGULATOR MOTOR (L/H/R) <i>new</i>	1.0 PCS	344.05	344.05 ✗
17	SPORT RIM (L/H/R) <i>at</i>	1.0 PCS	802.80	802.80 ✓
18	SHOCK ABSORBER (L/H/R)	1.0 PCS	274.15	274.15 ✗
19	LOWER ARM (L/H/R)	1.0 PCS	288.55	288.55 ✗
20	UPPER ARM (L/H/R) (SHORT)	1.0 PCS	320.60	320.60 ✗
21	UPPER ARM (L/H/R) (LONG)	1.0 PCS	140.90	140.90 ✗
22	LOWER LINK (REAR) (L/H) (SHORT)	1.0 PCS	85.50	85.50 ✗
23	LOWER ARM (REAR) (R/H) (LONG)	1.0 PCS	266.35	266.35 ✗
24	KNUCKLE (REAR) (L/H)	1.0 PCS	1,173.20	1,173.20 ✗
25	WHEEL BEARING (L/H/R)	1.0 PCS	156.55	156.55 ✗
26	Discount 5 %			-413.67

3468.50

3255.45



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Buss.Reg.No.: 52888887X

Attn: Adnan

QUOTATION

No : QT-000138

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Your Ref. : SLN245U
 Vehicle No. : SFK8448K
 Make & Model : BMW 116D
 Chassis No. : WBA1V720X0V944674
 Engine No. : 39599887B37D15A
 Accident Date : 23-05-2018
 Policy No. : SD17V05753/VPC2/R00
 Date : 03-07-2018
 Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
27	SubTotal (L)			7,859.63
28	SEALANT <i>new</i>	1.0 BTL	35.00	35.00 ✓
29	TYRE (L/H/R) <i>x 2 new</i>	1.0 PCS	380.00	380.00 *
30	SubTotal (S)			415.00
31	PANEL BEATING & REPLACING OF THE ABOVE	1.0 X	700	1,200.00
32	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X	700	1,000.00
33	TO PROVIDE UNDER TURFCODE	1.0 X	50	120.00
34	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0 X	60	180.00
35	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1.0 X	150.00	150.00
36	TO CHECK UNDERCARRIAGE AND REPAIR DAMAGED PARTS	1.0 X	300.00	300.00
37	TO COMPUTERISE ADJUST WHEEL ALIGNMENT	1.0 X	80	150.00
38	SubTotal (L)			3,100.00

(AK)

total 5035.45
A/S: AK
06 days

LKK Auto Consultants hence notify the Repairer of the following:
 SINGAPORE DOLLAR ELEVEN THOUSAND THREE HUNDRED SEVENTY FOUR AND CENTS
 SIXTY THREE ONLY

E. & O.E

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Customer's Signature/Co. Stamp

ZERO GRAVITY

Total	S\$	11,374.63
Discount	S\$	0.00
Net Total	S\$	11,374.63

Terms: C.O.D.

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.