LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building 78 Shenton Way #07-16 Singapore 079120

51 Ubi Ave 1 #01-25
6 Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina Date: 11 Jul 2018

Preliminary Advice

Vehicle No : SJA6263U **Accident Date** : 21/05/2018 Make : AUDI Q3 Policy No. : 1800000505 **Assignment Date** : 25/05/2018 **Excess** : S\$800.00 : 25/05/2018 Date of Inspection Est. Duration of Repair : 5 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,204.00
Revised Amount	:S\$	24,846.50
Check Items (Estimated)	:S\$	1,669.00
Total	:S\$	26,515.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 160,000.00

 COE / PARF Rebate
 :S\$ 71,322.00

Salvage Value :S\$

Margin for Repair :S\$ 88,678.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: SUPPLEMENTARY AMOUNT \$ 3,578.00.