

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FWD

Estimate : ES000137

Attention : Motor Claim Department

Date : 26/05/2018
 Vehicle Num. : SLN 7280X (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 25/05/2018
 Claim No. :
 Reference :
 Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

| | | | | |
|----|---|--------------------------------|--|--------|
| | | LIST ITEMS : | | |
| 1. | 1 | REAR BUMPER ✓ Deform. | | 500.00 |
| 2. | 1 | REAR BUMPER TOW COVER ✓ MS | | 100.00 |
| 3. | 1 | REAR LOWER BUMPER ✓ Deform. | | 560.00 |
| 4. | 1 | REAR BOOTLID OUTER GARNISH X | | 680.00 |
| 5. | 1 | REAR EXTENSION FILLER RH ✓ CRK | | 220.00 |
| 6. | 1 | REAR BUMPER TAIL LAMP RH X | | 600.00 |
| 7. | 1 | REAR BUMPER REINFORCEMENT ✓ PT | | 340.00 |
| 8. | 1 | REAR BUMPER RETAINER RH X | | 120.00 |

| | |
|-----------------------|----------|
| List TotalS\$: | 3,120.00 |
| 25.00% Discount S\$: | 780.00 |

2,340.00

| | | | | |
|----|---|------------------------------------|--|--------|
| | | SPECIAL NETT ITEMS : | | |
| 1. | 1 | REAR BUMPER CLIP ✓ NDC | | 50.00 |
| 2. | 1 | REAR BOOTLID OUTER GARNISH CLIPS X | | 50.00 |
| 3. | 1 | REVERSE SENSOR ✓ DMG | | 280.00 |

| | |
|--------------------------|--------|
| Special Nett Total S\$: | 380.00 |
|--------------------------|--------|

| | | |
|--|---|--------|
| LABOUR : | | |
| TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS. | X | 380.00 |

| | | |
|---|---|--------|
| TO REMOVE & REINSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS. | X | 380.00 |
|---|---|--------|

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FWD

Estimate : ES000137

Attention : Motor Claim Department

Date : 26/05/2018
 Vehicle Num. : SLN 7280X (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 25/05/2018
 Claim No. :
 Reference :
 Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|--|------------|-------------------|
| | | LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIR INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE ITEMS. | 400 | 900.00 |
| | | PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER / OUTER) | 450 | 800.00 |
| | | Labour Total S\$: | | 2,460.00 |

Sebastian.
 28/5/18.
 - Lump Sum Repair.
 - Photo After Paint

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E.

Total S\$:

5,180.00

=====

for WORLD AUTO PTE LTD