

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

LUMENS AUTO PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

25th MAY 2018

Accident date: 24th MAY 2018

Estimated repair cost for vehicle no: SJL3515E Toyota Corolla Altis 1.6 A, 08

S/n	Qty	Items	U/price	Amount
1	1	Front headlamp-LH		\$717.20
2	1	Front Bumper		\$659.50
3	1	Front Bumper Side Bracket		\$121.25
4	8	Front bumper clips	\$12.90	\$103.20
5	1	Front bumper fog lamp-LH		\$381.20
6	1	front bmper fog lamp cover -LH		\$156.00
7	1	Front Fender -LH		\$707.40
8	1	front fender inner garnish		\$127.20
9	8	front fender inner garnish clips	\$12.90	\$103.20
10	1	Front L/H Fender Signal Lamp		\$43.55
11	1	Front L/H Lower Arm		\$287.72
12	1	Front L/H Knuckle Arm		\$281.85
13	1	Front L/H Knuckle Arm Bearing		\$161.40
14	1	front sport rim -LH		\$480.00
15	1	front tyre -LH		\$380.00
16	1	front L/H door		\$1,071.50
17	1	Front L/H Door Side Mirror		\$381.20
18	1	Front LH door glass		\$450.00
19	1	Front L/H Door Protector		\$161.40
20	1	Front L/H Door protector Molding		\$123.05
21	1	Front L/H door inner lock		\$289.90
22	1	Front L/H door inner trim board		\$372.40
23	1	Front L/H Door Inner Gear Motor Assy		\$372.40
24	1	Rear L/H Door		\$1,081.40
25	1	Rear L/H Door Protector		\$131.25

26	1	Rear L/H Door Protector Molding	\$121.10
----	---	---------------------------------	----------

Subtotal :- \$9,266.27

Labour charges

To remove & install cushion \$120.00

TO Remove & install LH front & rear door \$220.00

tuff Kote \$120.00

To wheel alignment computer \$120.00

To remove & re-fix front undercarriage \$250.00

To Check Wiring System \$60.00

Panel beating \$1,000.00

Spray painting \$1,000.00

subtotal:- \$2,890.00

Total:- \$12,156.27