

13/03/2003

ASS. REC. BY:

REF:

CS/msh18009660/Ksb

Special Instruction:

SUIVAJOY

Munimen

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSH

Date/Time:

28052018 4:10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJB 8815E

Insured:

SKB 7377B

at Workshop m/s

Chiu Hoon

Tel:

of

Blk 10 Amk Ind Park JA #01-15

Policy No:

A9079237RMY

Claim No:

559473

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24052018

CA / REV / REP. / REV 24 HRS Wp

30052018

H.O.D. Endorsement:

Date/Time:

28052018 4:49pm

Person Contacted:

Grad

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJB 8815E -X

SKB 7377B -X

04/06/18

@ 09:55 a.m. revised IA to Christina Wong via munimen.

22/6

1/1 Aug 8 3:50 email & confirmed

| | |
|-----|-----|
| | |
| | |
| N/S | O/S |
| | |

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--------------------------------|---------|---------------|------------|--|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 28 May 2018 | | 28 May 2018 16:10 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | ONG BOON HAN (WANG WENHAN), ID: S7334066G | | | | | | | | |
| Main Claimant: | SONG CHOY TUCK, ID: S1734247I | | | | | | | | |
| Vehicle Reg. No.: | SJB8825E | Date of Loss: | 24/05/2018 19:00 - :59 [123 Months and 29 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 559473 | Policy/Cover Note No.: | A29079237QMY (Comprehensive) Coverage: 26/04/2018 - 25/04/2019 | | | | | | |
| Vehicle Reg. No. (Insured): | SKB7377B | Policy No. (Claimant): | | | | | | | |
| | | Excess: | S\$1,000.00 | | | | | | |
| Repairer: | Chew Goon Motor (AMK) Bldg 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626 | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/05/2018] | | | | | | | | |
| Adj Asg. Remarks: | Liability is down. TP agree to use LKK Auto Consultants as the SJE. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|--------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 42471 |
| Vehicle Details | |
| Vehicle No.: | SJB8825E |
| Vehicle to be Exported: | Yes |
| Intended De-registration Date: | 25 May 2018 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | WISH 1.8 A |
| Primary Colour: | Grey |
| Manufacturing Year: | 2007 |
| Engine No.: | 1ZZ2994441 |
| Chassis No.: | ZNE100387920 |
| Maximum Power Output: | 97.0 kW (130 bhp) |
| Open Market Value: | \$16,998.00 |
| Original Registration Date: | 25 Jan 2008 |
| First Registration Date: | 25 Jan 2008 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$18,698.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Forfeited |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 24 Jan 2023 |
| COE Category: | B - Car (1601cc & above) |
| COE Period(Years): | 5 |
| PQP Paid: | \$26,136.00 |
| COE Rebate Amount: | \$24,379.00 |
| Total Rebate Amount: | \$24,379.00 |
| Message | |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 25 May 2018

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 04 Jun 2018

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|--------------|
| Insured Vehicle No | : SKB7377B | Accident Date | : 24/05/2018 |
| TP Vehicle No | : SJB8825E | Assignment Date | : 28/05/2018 |
| Make | : TOYOTA WISH | Est. Duration of Repair | : 5 days |
| Date of Inspection | : 30/05/2018 | | |
| Inspection At | : Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 7,458.68 |
| Revised Amount | :S\$ | 5,245.80 |
| Check Items (Estimated) | :S\$ | 409.80 |
| Total | :S\$ | 5,655.60 |

| | |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|--|--|
| Date Of Report | 25/05/2018 10:22 |
| Date Of Accident | 24/05/2018 20:00 |
| Exact Location Of Accident | JUNCTION OF WEST COAST RD & CLEMENTI AVE 2 |
| Country/State of Loss | SINGAPORE |
| DETAILS OF OWN VEHICLE | |
| Vehicle Registration Number | SJB8825E |
| Insured/Policyholder | |
| Name Of Registered Owner | SONG CHOY TUCK |
| NRIC No | S1734247I |
| Email Address | 1966JOHNSONG@GMAIL.COM |
| Mobile Phone No | (LOCAL) +65-91003384 |
| Alternative Phone No | OTHERS-91003384 |
| Vehicle Particulars | |
| Manufacturer | TOYOTA |
| Model | WISH-1.8 (A) |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | ERGO INSURANCE PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMPC18S006380 |
| Cover Note Number | |
| Driver | |
| Name of Driver | SONG CHOY TUCK |
| NRIC No | S1734247I |
| Date Of Birth | 15/03/1966 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 20/09/1990 |
| Driving Experience | 27 YEARS AND 8 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-91003384 |
| Fax Number | |
| Contact Number | OTHERS-91003384 |
| EEmail Address | 1966JOHNSONG@GMAIL.COM |

| | |
|---|---------------------------|
| Address | BLK 440 FAJAR RD, #04-450 |
| Postcode | 670440 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|---|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 5 |
| Passenger 1 | NAME: : IRENE ENG GENDER: : FEMALE |
| Passenger 2 | NAME: : RACHEL SONG GENDER: : FEMALE |
| Passenger 3 | NAME: : CHESTER CHEAH GENDER: : MALE |
| Passenger 4 | NAME: : RANDELL CHEAH GENDER: : MALE |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

STOP AT GIVEWAY TO CHECK TRAFFIC, BEHIND WAS WAITING AS WELL, SUDDENLY KNOCK BY BEHIND CAR.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--------------|
| Vehicle Registration Number | SKB7377B |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | ONG BOON HAN |

| | |
|-------------------------------------|-----------|
| NRIC/Passport Number | S7334066G |
| Contact Number | 97660604 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.


(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

NHIC/PIN No.

Sketch Plan #2

SKETCH PLAN



A. SJB 8825E

B: SCB 7377B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Stop At Give Way to clear traffic. Behind was waiting
all well. Suddenly knock by Behind car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/PIN No.: _____

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S17342471**

Name: **SONG CHOY TUCK**

Birth Date: **15 Mar 1966**

Issue Date: **23 Apr 2014**

002296986C

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S17342471**

Name: **SONG CHOY TUCK**

Race: **CHINESE**

Date of Birth: **15-03-1966**

Sex: **M**

Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars ≤ 3000kg with ≤ 7 passengers, exclusive of the driver; and other motor vehicles ≤ 2500kg

EFFECTIVE DATE 20 Sep 1990

Licence No: **S17342471**

NP 428A

1812629

NRIC No: **S17342471**

1812629

APT BLK 440 FAJAR ROAD #04-450
SINGAPORE 670440

NRIC No: **S17342471** Date: **19-03-2002** No: **4127903**

ERGO

CERTIFICATE OF INSURANCE
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

G621
#1510-68

| | |
|--|------------------------------|
| CERTIFICATE NO. DMPC18S006380 | C18073761 |
| Type of CI: Private Vehicle | |
| Cover: Comprehensive | A000609 LQ BUSINESS PTE. LTD |
| 1) Registration No. of Vehicle: | SJB8825E |
| 2) Name of Policyholder: | SONG CHOY TUCK |
| 3) Commencement Date of Insurance: | 21/03/2018 |
| 4) Expiry Date of Insurance: | 20/03/2019 |
| 5) Persons or Classes of Persons entitled to drive | |
| 1) SONG CHOY TUCK | |
| 2) Any other person who is driving on the Policyholder's order or permission | |
| Excess (Section 1) : S\$700.00 | |
| Unnamed Drivers(Section 1) : Additional : S\$500.00 | |
| Non-Auth Workshops(Section 1) : Additional : S\$300.00 | |
| Windscreen : S\$100.00 | |
| Young & Inexp Drivers(Section 1) : S\$3,000.00 | |
| 6) Name of Finance Company/Hire Purchase Owner: GV CREDIT PTE LTD | |
| 7) Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage. | |
| 8) Limitations as to Use | |
| (1) Use only for social domestic and pleasure purposes | |
| (2) Use for Policyholder's business | |
| This Policy does not cover | |
| (1) Use for hire or reward, racing, pace-making, reliability trial or speed-testing | |
| (2) Use for the carriage of goods other than samples in connection with any trade or business | |
| (3) Use for any purpose in connection with the Motor Trade | |
| Limitations rendered Inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings (for Items 7 & 8). | |



WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

A000609/20/03/2018 11:12:22

Counter-signed by
LQ BUSINESS PTE. LTD
LQ BUSINESS PTE LTD
UEN NO. 201700648N
180B BENCOOLEN STREET
#04-02, THE BENCOOLEN
SINGAPORE 189648
Tel: 6333-4136 Fax: 6334-5238

For and on behalf of
ERGO Insurance Pte. Ltd.

AUTHORIZED SIGNATURE

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **MSIG Insurance (S) Pte Ltd**

Accident Date : 24.05.2018

Not Notarised
C/L Rep 83950/405d
Resurvey After Paint

6/6/18

5 days Third Party

Policy No: _____

Date: 26.05.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

| 数量 Quantity | 货 名 DESCRIPTION | 单 价 Unit Price | 银 Amount 额 \$ cts. |
|---|--------------------------------|-------------------|-----------------------|
| Estimate Cost of Repair to "Toyota Wish" Reg. No. SJB8825E Claiming Against Your Insured Veh. No. SKB7377B | | | |
| 1pc | Tailgate <i>1210.50</i> | | 1,277.00 ✓ |
| 1pc | Tailgate Glass Moulding Top | | 125.10 ✓ |
| 2pcs | Tailgate Glass Mouldings Side | 78.10 | 156.20 ✓ |
| 1pc | Tailgate Central Lock | | 142.00 ✓ |
| 1pc | Tailgate Emblem | | 83.00 ✓ |
| 1pc | Tailgate Outer Chrome Moulding | | 265.70 X |
| 1pc | Tailgate Lock | <i>136.50 SN</i> | 432.00 ✓ |
| 1pc | Tailgate Weatherstrip | | 273.00 <i>50 SN</i> |
| 10pcs | Tailgate Trim Board Clips | 7.21 | 72.10 X |
| 1pc | Tailgate Stopper LH | | 21.50 ✓ |
| 1pc | Taillamp Assy LH | | 316.70 ✓ |
| 1pc | Taillamp Gasket LH | | 28.20 ✓ |
| 1pc | Rear Bumper <i>500.30</i> | | 1,120.00 ✓ |
| 10pcs | Rear Bumper Clips | 5.71 | 57.10 ✓ |
| 2pcs | Rear Bumper Brackets | 65.20 | 130.40 ✓ |
| 1pc | Rear Bumper Reflector LH | | 53.40 ✓ |
| 1pc | End Panel | | 437.50 ✓ |
| 1pc | End Panel Garnish | | 238.00 ✓ |
| 1pc | Rear Fender Trim Board LH | | 416.00 ✓ |
| Less 25% | | | 5,644.90 |
| | | | 1,411.23 |
| | | | 4,233.68 |
| 1pc | Tailgate Glass Sealant | | 50.00 SN ✓ |
| 1pc | Tailgate Glass Sealer | | 30.00 SN ✓ |
| 1pc | Tailgate Glass Fastener | | 50.00 SN ✓ |
| 1pc | Rear Bumper Reverse Sensor | | 280.00 SN ✓ |
| 1pc | Rear Number Plate | | 45.00 SN X |
| To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc | | | 120.00 <i>50</i> |
| To Dismantle / Refit Tailgate Fittings / Ancillary Accessories | | | 150.00 <i>60</i> |
| To Dismantle / Refit Tailgate Glass | | | 160.00 <i>120</i> |
| To Dismantle / Transfer Rear Spare Tyre Panel Inner Trims Boards / Garnish and Rear Fenders Inner Trims Boards / Garnish to Facilitate Repair | | | 80.00 <i>60</i> |
| | | | 5,198.68 |
| | | | C/F |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

C/M

20/5/18

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **MSIG Insurance (S) Pte Ltd**

Third Party

Policy No: _____

26.05.2018

Date: _____

Accident Date : 24.05.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

| 数量 Quantity | 货 名 DESCRIPTION | 单 价 Unit Price | 银 Amount 额 \$ cts. |
|----------------|--|-------------------|-----------------------|
| | Estimate Cost of Repair to "Toyota Wish" Reg. No. SJB8825E Claiming Against Your Insured Veh. No. SKB7377B | | |
| | | B/F | 5,198.68 |
| | To Supply End Panel Joint Sealant <i>nm</i> | | 60.00 <i>30sn</i> |
| | To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel | | 100.00 <i>60</i> |
| | Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Spare Tyre Panel, Floor Panel Etc. Cnt, Weld End Panel and Parts Replacement | | 1,200.00 <i>600</i> |
| | To Respray Affected Areas | | 900.00 <i>600</i> |
| | | Total : | <u>7,458.68</u> |

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 28 May 2018 | | 28 May 2018 16:10 Edit Adj Rpt | S\$4,050.00 Edit Estimates | S\$4,050.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|-------------|------------------|----------------------|------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|-------------|------------------|----------------------|------------------|--------------------------|

CLAIM SUBFOLDER DETAILS [Created by Insurer]

| | | | |
|-----------------------------|---|------------------------|---|
| Insured: | ONG BOON HAN (WANG WENHAN) , ID: S7334066G | | |
| Main Claimant: | SONG CHOY TUCK , ID: S17342471 | | |
| Vehicle Reg. No.: | SJB8825E | Date of Loss: | 24/05/2018 19:00 - :59 [123 Months and 29 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 559473 | Policy/Cover Note No.: | A29079237QMY (Comprehensive) Coverage: 26/04/2018 - 25/04/2019 |
| Vehicle Reg. No. (Insured): | SKB7377B | Policy No. (Claimant): | |
| | | Excess: | S\$1,000.00 |
| Repairer: | Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626 | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 27/06/2018] | | |
| Adj Asg. Remarks: | Liability is down. TP agree to use LKK Auto Consultants as the SJE. | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)






























There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

*SJB8825E (559473)
[SKB7377B]
TP
SONG CHOY TUCK
May 24 2018 7:00PM
[ONG BOON HAN (WANG WENHAN)]
Chew Goon Motor

| Upload Documents Upload Photos Compose New Letter | | | View View in Browser | |
|---|-----------------|---|--|-------------------------------------|
| Assessment Reports | | | 1 per page <input type="checkbox"/> <input checked="" type="checkbox"/> | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 04/06/18 09:59 | Adjuster Immediate Advice |  Load HTM | <input type="checkbox"/> |
| Photos/Images | | | 3 per page <input type="checkbox"/> <input checked="" type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 04/06/18 10:02 | General View Right |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 04/06/18 10:02 | Odometer Reading |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 04/06/18 10:02 | Chassis Number |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 22/06/18 11:09 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 22/06/18 11:09 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 22/06/18 11:09 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 22/06/18 11:09 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 22/06/18 11:10 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 22/06/18 11:10 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page <input type="checkbox"/> <input checked="" type="checkbox"/> | |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 28/05/18 09:44 | SKB7377B GIA Rpt |  Load PDF | <input type="checkbox"/> |
| 2 | 28/05/18 09:45 | SJB8825E GIA Rpt |  Load PDF | <input type="checkbox"/> |
| 3 | 28/05/18 09:46 | Email frm TP on PRI & to appoint LKK as SJE |  Load PDF | <input type="checkbox"/> |

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18009660/KSBQ2

Date: 25/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A29079237QMY

Claimant Vehicle No : SJB8825E

Insured Vehicle No :

SKB7377B

Date of Loss: 24/05/2018

Nature of Claim:

TP

Claim No: 559473

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJB8825E

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2994441

Reg. Date: 25/01/2008 (Man. Year: 2007)

Chassis No: ZNE100387920

Colour: Metallic Grey

Odometer: 150880 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Rovelo 9 mm

Rear Left Side:

Rovelo 9 mm

Front Right Side: Rovelo 9 mm

Rear Right Side:

Rovelo 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 4,748.67 | 3,542.02 | 1,206.65 | 25.41 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,710.00 | 1,550.00 | 1,160.00 | 42.80 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,458.67 | 5,092.02 | 2,366.65 | 31.73 |
| Approved Total (Overridden) (S\$) | | 4,050.00 | | |
| (S\$) | 7,458.67 | 4,050.00 | 3,408.67 | 45.70 |
| + GST 7.00/7.00% (S\$) | 522.11 | 283.50 | 238.61 | 45.70 |
| Nett Amount (S\$) | 7,980.78 | 4,333.50 | 3,647.28 | 45.70 |

INSPECTION

Date of Assignment: 28/05/2018

Date Inspected: 30/05/2018 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|----------------------------|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 25 Jun 2018) |
| Parts: M1-MPV | TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJB8825E) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk * |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|--------------------|-------------|--------------|
| 1 | 1 | | *TAILGATE | Bent | 1,277.00 FL | *1,210.50 FL |
| 2 | 1 | | *TAILGATE GLASS MOULDING TOP | Necessary | 125.10 FL | *125.10 FL |
| 3 | 2 | | *TAILGATE GLASS MOULDING SIDE | Necessary | 156.20 FL | *156.20 FL |
| 4 | 1 | | *TAILGATE CENTRAL LOCK | Serviceable | 142.00 FL | *- FL |
| 5 | 1 | | *TAILGATE EMBLEM | Necessary | 83.00 FL | *83.00 FL |
| 6 | 1 | | *TAILGATE OUTER CHROME MOULDING | Serviceable | 265.70 FL | *- FL |
| 7 | 1 | | *TAILGATE LOCK | Dented | 432.00 FL | *432.00 FL |
| 8 | 1 | | *TAILGATE WEATHERSTRIP (50%) | Dented / Distorted | 204.75 FS | *136.50 FS |
| 9 | 10 | | *TAILGATE TRIM BOARD CLIPS | Not Necessary | 72.10 FL | *- FL |
| 10 | 1 | | *TAILGATE STOPPER LH | Missing | 21.50 FL | *21.50 FL |
| 11 | 1 | | *TAILLAMP ASSY LH | Scratched | 316.70 FL | *316.70 FL |
| 12 | 1 | | *TAILLAMP GASKET LH | Necessary | 28.20 FL | *28.20 FL |
| 13 | 1 | | *REAR BUMPER | Buckled | 1,120.00 FL | *500.30 FL |
| 14 | 10 | | *REAR BUMPER CLIPS | Necessary | 57.10 FL | *57.10 FL |
| 15 | 1 | | *REAR BUMPER BRACKETS | N/S Dented | 130.40 FL | *65.20 FL |
| 16 | 1 | | *REAR BUMPER REFLECTOR LH | Cracked | 53.40 FL | *53.40 FL |
| 17 | 1 | | *END PANEL | Buckled | 437.50 FL | *437.50 FL |
| 18 | 1 | | *END PANEL GARNISH | Mtg Cracked | 238.00 FL | *238.00 FL |
| 19 | 1 | | *REAR FENDER TRIM BOARD LH | Cracked | 416.00 FL | *416.00 FL |
| 20 | 1 | | *TAILGATE GLASS SEALANT | Necessary | 50.00 FS | *40.00 FS |
| 21 | 1 | | *TAILGATE GLASS SEALER | Necessary | 30.00 FS | *30.00 FS |
| 22 | 1 | | *TAILGATE GLASS FASTENER | Not Necessary | 50.00 FS | *- FS |
| 23 | 1 | | *REAR BUMPER REVERSE SENSOR | Cracked | 280.00 FS | *200.00 FS |
| 24 | 1 | | *REAR NUMBER PLATE | Serviceable | 45.00 FS | *- FS |
| 25 | 1 | | *END PANEL JOINT SEALANT | Necessary | 60.00 FS | *30.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 6,091.65 | 4,577.20 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 1,342.98 | 1,035.18 |
| Total Parts (\$\$) | 4,748.67 | 3,542.02 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|---|----------|------------|----------|
| <u>Labour Items</u> | | | | |
| 1 | TO CONDUCT ELECTRICAL CHECK ,REPLACE REVERSE SENSORS ,MODULE REWIRING ETC | New | 120.00 | 50.00 |
| 2 | TO DISMANTLE /REFIT TAILGATE FITTINGS /ANCILLARY ACCESSORIES | New | 150.00 | 60.00 |
| 3 | TO DISMANTLE /REFIT TAILGATE GLASS | New | 160.00 | 120.00 |
| 4 | TO DISMANTLE /TRANSFER REAR SPARE TYRE PANEL INNER TRIMS BOARDS /GARNISH AND REAR FENDERS INNER TRIMS BOARDS /GARNISH TO FACILITATE REPAIR | New | 80.00 | 60.00 |
| 5 | TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL | New | 100.00 | 60.00 |
| 6 | LABOUR CHARGE -PANEL BEATING ,REPAIRING OF REAR CHASSIS MEMBER ,INNER PANEL ,SPARE TYRE PANEL ,FLOOR PANEL ETC .CNT ,WELD END PANEL AND PARTS REPLACEMENT | New | 1,200.00 | 600.00 |
| 7 | TO RESPRAY AFFECTED AREAS | New | 900.00 | 600.00 |
| Gross Labour Cost (\$\$) | | | 2,710.00 | 1,550.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >