

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002535

Date : 18/07/2018

Vehicle Num. : YN4659D

Make/Model : MITSUBISHI FEB 21-2013

Chassis/Eng# : FEB21CA00010/4P10A99269

Accident Date : 24/05/2018

Claim No. :

Reference : SJK1594U

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT DOOR, LHS		2,001.44 <i>bt</i>
2.	2	DOOR HINGE	264.10	528.20 <i>Ry</i>
3.	1	DOOR WEATHERSTRIP		368.10 <i>X</i>
4.	1	AIR INTAKE DUCT		75.80 <i>am</i>
5.	1	DOOR LOCK		639.41 <i>Ry</i>
6.	1	BUMPER CORNER, LHS		353.71 <i>unt</i>
7.	1	STEP GARNISH		496.03 <i>unt</i>
8.	1	MUDGUARD		341.30 <i>unt</i>
9.	1	MUDFLAP		138.91 <i>X</i>
10.	1	DOOR GARNISH		195.20 <i>at</i>
List Total S\$:				5,138.10
25.00% Discount S\$:				1,284.53
				3,853.57
LABOUR :				
TO PANEL BEAT/REPAIR LH BODY				500
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS				650.00
, SPRAY PAINTING				300
, TO APPLY TUFF KOTE				450.00
				30
				100.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002535

Date : 18/07/2018

Vehicle Num. : YN4659D

Make/Model : MITSUBISHI FEB 21-2013

Chassis/Eng# : FEB21CA00010/4P10A99269

Accident Date : 24/05/2018

Claim No. :

Reference : SJK1594U

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LOSS OF USE : 4 DAYS @ \$ 120/DAY

Labour Total S\$:

1,200.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97475749
 'wp'
 Repairing after repair
 19/7/18 @ 1pm
 3 days
 suv@lkkauto.com

Total S\$: 5,053.57

=====

SIN SHENG ENGINEERING SERVICES