

INS. CASE OWNER:

Jawar

CC 6, LOR 1800

4704

Uwas 9.

IDAC:

Surveyor:

MARCUS

DOI:

30/5/18

Date / Time:

30/5/18

Registered in Merimen:

30/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLF 544H

Name of Insured:

LRF PL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

27/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

937083501854

Policy No.:

0999994764

Make / Model:

7. AX10

Place of Accident:

Upper Changi Rd North

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLN 19344



INSRS:

WSP:

Tel:

Liability:

RMKS:

Pegasus



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

6/6

SLN 19344. X;

SLF 544H. cc/Email: 6224073/Highway, 003 22/1/18

6/6 0002. file pass to handler follow up.

11/8/18.

Email letter to 02

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

2086.50

Loss of Rental (LOR):

S\$

200.85

(

3 days) x

66.95

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

2294.84

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

2294.84

Name 1:

Pegasus Engineering & Trading Pte Ltd.

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

RECEIVED 24 AUG 2018

COPY SENT 24/8/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18009704/Uwa3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 30-05-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 5414H	Veh. Inspected	SLN 1934H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	30/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/05/2018	Inspection Date	30/05/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 7200G

Vehicle Details

Vehicle No.: SLN1934H

Vehicle to be Exported: No

Intended De-registration Date: 30 May 2018

Vehicle Make: TOYOTA

Vehicle Model: VIOS 1.5E CVT

Primary Colour: Grey

Manufacturing Year: 2017

Engine No.: 2NRX142079

Chassis No.: MHFB29F3502009309

Maximum Power Output: 79.0 kW (105 bhp)

Open Market Value: \$12,946.00

Original Registration Date: 26 Apr 2017

First Registration Date: 26 Apr 2017

Transfer Count: 0

Actual ARF Paid: \$7,946.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Apr 2027

PARF Rebate Amount: \$5,959.00

Intended COE Rebate Details

COE Expiry Date: 25 Apr 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$52,000.00

COE Rebate Amount: \$46,308.00

Total Rebate Amount: \$52,267.00

The information contained herein is correct as at 30 May 2018

OK

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216
Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer : <i>Not Affect</i>
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn :
Tel :
Fax :

1/s 1950
4 day
teleph. 30/5/18

Quotation No : QO18/05-1247	Quotation Date : 23/05/2018	Terms : 30 DAYS
Vehicle No : SLN1934H	Chassis No : MHFB29F3502009309	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLF5414H, DATE OF ACCIDENT: 22.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID <i>no/ant 762.47</i>	1	1,662.4000	1,662.40
2	BOOTLID E BADGE <i>nee</i>	1	39.4000	39.40
3	BOOTLID VIOS BADGE <i>nee</i>	1	44.1000	44.10
4	BOOTLID CENTRE EMBLEM BADGE <i>nee</i>	1	59.8000	59.80
5	REAR END PANEL <i>n</i>	1	456.4000	456.40 X
6	REAR END PANEL INNER TRIM <i>17</i>	1	234.3000	234.30 X
7	REAR BUMPER <i>no/ant n</i>	1	504.9000	504.90
8	REAR BUMPER REINFORCEMENT	1	323.0000	323.00 X
9	REAR BUMPER CLIPS <i>nee</i>	6	4.3000	25.80
10	REAR BUMPER REFLECTOR <i>17</i>	2	130.8000	261.60 X
11	REAR BUMPER SIDE RETAINER <i>015 ant</i>	2	115.1000	230.20 1pc
12	REAR BUMPER SIDE HOLDER <i>17</i>	2	22.5000	45.00 X
13	REAR LAMP RH <i>17</i>	1	375.8000	375.80 X
14	LESS 20% (ITEM 1 - 13) <i>25%</i>	1	-852.5400	-852.54
15	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	800.0000	400 800.00
16	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	850.0000	680 850.00
17	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	120.0000	60 120.00
18	TO RUST-PROOFING OF THE AFFECTED AREAS	1	80.0000	30 80.00
19	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	50 120.00
20	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	20 60.00

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : WEE TZE FAH

Tel :

Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :

Tel :

Fax :

Quotation No : QO18/05-1247

Quotation Date : 23/05/2018

Terms : 30 DAYS

Vehicle No : SLN1934H

Chassis No : MHFB29F3502009309

Third Party Insurer :

Model : VIOS

Date of Accident :

Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLF5414H, DATE OF ACCIDENT: 22.05.2018

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
21	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	1	120.0000	60 120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey it on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	5,560.16
GST(7.00%)	389.21
Total (SGD)	5,949.37

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-041221G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1986 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.Z.400
Cars for Hire

COMMERCIAL VEHICLE - FLEET
Comprehensive

Certificate No. A 29069766 MKF

Excess: SGD2,000

1. Index Mark and Registration Number of Vehicle

SLN1934H

2. Name of Policyholder

Grab Rentals Pte. Ltd.

3. Effective Date of the Commencement of Insurance for the purposes of the Act

01/02/2018

4. Date of Expiry of Insurance

31/01/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use for the carriage of passengers or goods in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

(1) Use for racing pace-making reliability trial or speed-testing.

(2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

Chief Executive Officer

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Wednesday, 1 August, 2018 2:31 PM
To: 'eyap@lioncityrentals.com.sg'; 'insurance@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO)
Subject: ACCIDENT INVOLVING SLF 5414H AND SLN 1934H ON 22/05/2018

Our Ref: CC6/LCR18009704/Uwa3

01 August 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLF 5414H AND SLN 1934H ON 22/05/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM: OWNER OF VEHICLE NUMBER SLN1934H

ACCIDENT INVOLVING 8LF5414H

ALONG/AT Upper Changi Road North ON 22.05.2018

We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident.

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to PEGASUS ENGINEERING & TRADING PTE LTD.

Name : Grab Rentals Pte Ltd

Co Reg No : 201617200G

Address : 18 Sin Ming Lane #01-08 Midview City Singapore 573960

Contact : 6655 0005

Date : 25.07.2018

Signature



Owner

RELEASE VOUCHER
(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)

"We/I, Pegasus Engineering & Trading Pte Ltd (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 2,086.50 (repair cost), S\$ 200.85 (loss of rental/use), S\$ 7.49 (disbursement), for vehicle no. SLN 1934H that was damaged pursuant to the accident which occurred on 22/05/2018 (date) along UPPER CHANGI RD NORTH (location) involving vehicle no/s SLF 5414H.

This is pursuant to the inspection conducted on 30/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GRAB RENTALS PTE LTD (the third party claimant") of vehicle no. SLN 1934H make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLN 1934H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 24 (day) of Aug (month) 2018 (year)

C/CS



Signed by AIG appointed surveyor



[Signature]

Chopped & Signed by "the workshop"

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Vehicle Model : Toyota Vios 1.5E CVT
Vehicle No : SLN1934H
Chassis No : MHFB29F3502009309

GST / ROC Company No : 201101753C

Third Party Insurer : AIG
Insured's Veh No : SLF5414H
Date of accident : 22.05.2018

Tax Invoice No : IV18/06-1075
Invoice Date : 25.06.2018

Pages : 1 of 1

DESCRIPTION	AMOUNT
TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR.	\$ 1,950.00
Sub Total	\$ 1,950.00
GST (7.00%)	\$ 136.50
Total	\$ 2,086.50

Cheques should be made payable to **PEGASUS ENGINEERING & TRADING PTE LTD**

PEGASUS ENGINEERING & TRADING PTE LTD


Authorised Signature (Company Stamp)

If you have enquiries concerning this invoice, please contact Mr. Alvin or Mr. Wee at Tel: (65) 6858 1846
Mailing Address : Pegasus Engineering@Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216
E-mail : claims@pegasusengrg.com.sg



Our Ref: GR-ACC-2017-02

01 June 2017

Pagasus Engineering & Trading Pte Ltd
No. 51 Defu Lane 10
Singapore 539216

Mailing Address
18 Sin Ming Lane,
#01-08 Midview City,
Singapore 573960
Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$ 79.95
02	Mazda 3 1.5 (A) Sedan	\$ 66.95
03	Nissan Qashqai 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.95
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$66.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,


Tay Chee Wee
Grab Rental Pte Ltd

GRAB Singapore

Enquire Vehicle & Owner Information (Vehicle No. SLF5414H As At 22 May 2018 / 18:45:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: PET(CARINE)SLN1934H

Current Owner Details

Owner ID Type: Company

Owner ID: 201624597K

Owner Name: LCRF PTE LTD

Registered Address Type: Private Residential (non-Condo Apt / non-House)

Registered Block/House No.: 60

Registered Street Name: ANSON ROAD

Registered Unit No.: # 11 - 01

Registered Building Name: MAPLETREE ANSON

Registered Postal Code: 079914

Current Vehicle Details

Vehicle No.: SLF5414H

Make Description/Model: TOYOTA / COROLLA AXIO HYBRID 1.5G CVT D/AIRBAG

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 May 2018 Edit Reg		30 May 2018 00:00 Edit Adj Rpt	S\$1,950.00 Edit Estimates	S\$1,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF Pte Ltd, Co. Reg. No.: 201624597K								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLN1934H	Date of Loss:	22/05/2018 18:00 - :59 [12 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9370835018SG	Policy/Cover Note No.:	0999994764 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLF5414H	Policy No. (Claimant):	A29069766MKF						
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (LCR) - Tel: ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (06/06/2018): Re: No OI GIA Report AIG_SG (31/05/2018): No OI GIA Report AIG_SG (31/05/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLN1934H (9370835018SG)
[SLF5414H]**

TP




















GRAB RENTALS PTE LTD

May 22 2018 6:00PM

[LCRF Pte Ltd]

Pegasus Engineering & Trading Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
Letters/Correspondences						1 per page <input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown			Edit	<input type="checkbox"/>
Photos/Images						3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	30/05/18 16:09	Chassis Number			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
2	30/05/18 16:09	Odometer Reading			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
3	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
4	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
5	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
6	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
7	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
8	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
9	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
10	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
11	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
12	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
13	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
14	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
15	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
16	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
17	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
18	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
19	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
20	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
21	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
22	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
23	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
24	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
25	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
26	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
27	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
28	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
29	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
30	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
31	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
32	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
33	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
34	30/05/18 16:09	General View			Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	30/05/18 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
36	30/05/18 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
37	30/05/18 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
38	30/05/18 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/05/18 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
40	30/05/18 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
41	30/05/18 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
42	30/05/18 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
43	30/05/18 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/06/18 10:47	TP ESTIMATE - MARKED	 Load PDF	
2	05/06/18 11:06	TP GIA REPORT	 Load PDF	
3	07/06/18 11:33	Email non reporting letter ACCIDENT INVOLVING SLF 5414H AND SLN 1934H ON 22.05.2018 1045 Hrs ALONG U	 Load PDF	
4	01/08/18 14:35	Email letter to OI ACCIDENT INVOLVING SLF 5414H AND SLN 1934H ON 22.05.2018	 Load PDF	
5	27/08/18 08:37	WORKSHOP INVOICE	 Load PDF	
6	27/08/18 08:37	AUTHORISATION TO ACT FORM	 Load PDF	
7	27/08/18 08:37	Release Voucher	 Load PDF	
8	27/08/18 08:37	RENTAL RECEIPT	 Load PDF	
9	27/08/18 08:37	LTA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	01/08/18 09:10	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLF5414H (Insd veh)	Model:	TOYOTA VIOS 1.5 E (A)
	SLN1934H (TP veh)		
Date of Accident:	22/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	5,949.37
Final Repair Cost	:	\$	2,086.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	200.85 3 days
LTA / GIA Search Fee	:	\$	7.49
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,294.84

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Pegasus Engineering & Trading Pte Ltd	:	\$ 2,294.84
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

27 Aug
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18009704/UWA3Q2

Date: 27/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994764

Claimant Vehicle No : SLN1934H

Insured Vehicle No : SLF5414H

Date of Loss: 22/05/2018

Nature of Claim:

TP

Claim No: 9370835018SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN1934H

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 2NRX142079

Reg. Date: 26/04/2017 (Man. Year: 2017)

Chassis No: MHFB29F3502009309

Colour: Grey

Odometer: 65261 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16

Rear Tyre Size: 195/50 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,410.16	1,163.68	2,246.48	65.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,300.00	850.00	39.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,560.16	2,463.68	3,096.48	55.69
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	5,560.16	1,950.00	3,610.16	64.93
+ GST 7.00/7.00% (S\$)	389.21	136.50	252.71	64.93
Nett Amount (S\$)	5,949.37	2,086.50	3,862.87	64.93
+ Car Rental (3.0 x S\$66.95/day) (S\$)		200.85		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,294.84		

INSPECTION

Date of Assignment: 30/05/2018

Date Inspected: 30/05/2018 Inspected At:

Pegasus Engineering & Trading Pte Ltd
(HQ)

51 DEFU LANE 10
Singapore 539216

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	1,662.40 FL	*762.47 FL
2	1		*BOOTLID E BADGE	Necessary	39.40 FL	*39.40 FL
3	1		*BOOTLID VIOS BADGE	Necessary	44.10 FL	*44.10 FL
4	1		*BOOTLID CENTRE EMBLEM BADGE	Necessary	59.80 FL	*59.80 FL
5	1		*REAR END PANEL	Repair	456.40 FL	*- FL
6	1		*REAR END PANEL INNER TRIM	Not Necessary	234.30 FL	*- FL
7	1		*REAR BUMPER	Dented / Deformed	504.90 FL	*504.90 FL
8	1		*REAR BUMPER REINFORCEMENT	Repair	323.00 FL	*- FL
9	6		*REAR BUMPER CLIPS	Necessary	25.80 FL	*25.80 FL
10	2		*REAR BUMPER REFLECTOR	Not Necessary	261.60 FL	*- FL
11	1		*REAR BUMPER SIDE RETAINER	O/S Bent	230.20 FL	*115.10 FL
12	2		*REAR BUMPER SIDE HOLDER	Not Necessary	45.00 FL	*- FL
13	1		*REAR LAMP RH	Not Necessary	375.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,262.70	1,551.57
- List Item Discount on L Items 20.00/25.00% (\$\$)	852.54	387.89

Total Parts (\$\$)	3,410.16	1,163.68
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	800.00	400.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	850.00	680.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS TRIMMINGS,GARNISH AND OTHER ,TO ENABLE REPAIR	New	120.00	60.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	80.00	30.00
5	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
7	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	120.00	60.00
Gross Labour Cost (S\$)			2,150.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >