



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

EQ INSURANCE

DATE : 01-06-2018

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

VEHICLE NO. : SFY3877P

ACCIDENT DATE : 26-05-2018 14:30

THIRD PARTY REF. : GBC931C

ATTN: EQ INSURANCE

ESTIMATE COST OF REPAIR TO VEHICLE SFY3877P HONDA CIVIC 1.6 VTI (A)

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR WINDSCREEN MOULDING / MC	72.00
2	1	REAR BOOT COVER / BT	350.00
3	1	REAR BOOT REFLECTOR LH - CRA	55.00
4	1	REAR BOOT CENTRE EMBLEM - MC	18.00
5	1	REAR BOOT RUBBER / Tri	38.00
6	1	REAR LAMP LH - CRA	85.00
7	1	REAR LAMP LOWER BRACKET LH / CRA BT.	5.00
8	1	REAR FENDER LH / MC	480.00
9	1	REAR BUMPER / BE	145.00
10	1	REAR BUMPER SIDE RETAINER LH / MC	12.00
11	2	REAR BUMPER SIDE CLIP@\$15.00 / MC.	30.00
12	1	REAR BUMPER LOWER SPOILER - CRA	380.00
13	10	REAR BUMPER CLIP@\$1.50 / MC.	15.00
14	1	REAR CIVIC EMBLEM /	25.00
15	1	REAR VTI EMBLEM / MC.	19.00
			1,729.00
ADD 20 %			345.80
TOTAL (A)			2,074.80

SPECIAL NETT ITEMS

1	1	REAR WINDSCREEN GUM / MC	40.00
2	1	REAR REVERSE SENSOR / MC ?	200.00
TOTAL (C)			240.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00
---	---	------------------------	-------



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SFY3877P
ACCIDENT DATE : 26-05-2018 14:30
THIRD PARTY REF. : GBC931C

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
2	1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	100.00
3	1	TO REMOVE/REFIT REAR FENDER INNER GARNISH, CUSHION , CARPET AND ETC	220.00
4	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	1100.00
5	1	SPRAYPAINTING CHARGES	1000.00
TOTAL (D)			2,450.00
ESTIMATE TOTAL			4,764.80

Guo Qiang - 82880282

05/6/18

(lump sum repair.

After repair photos.

5 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: