

ASS. REC. BY:

REF: CS/EG118009761/Tlv32

Special Instruction:

Surveyor

Fei Li

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of

EGI

Date/Time:

30/5/2018 @ 11:33am

Estimated Cost:

Bill to:

OD / (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 9698C

Insured:

SLU 9421G

at Workshop m/s

Tan Chong Motor

Tel:

67038914

of

913 Bukit Timah Road

Policy No:

Claim No:

DSMPC1800936 / RH / P1

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/05/2018

CA / REV / REP. / REV 24 HRS

up

05.062018 @ 4pm

H.O.D. Endorsement:

Date/Time:

12.26pm @ 30/5/18

Person Contacted:

Lawrence

Vehicle IN / (OUT)

Date/Time	Action/Instruction (✓) Estimate
	GBE 9698C -x
	SLU 9421G -x
6/6/18	Email preli revised to fei Li
16/7/18	Final fig \$ 3959.12 (Red 725.64, 6490) confirmed by email

Taufik

REF: EGT

ASSIGNMENT

From: \_\_\_\_\_ Date: **05062018**

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **GBE 9698C**

at Workshop m/s: **Tan Chong**

of: **911 Bukit Timah Rd**

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition) **4pm**

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: **6** days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **GBE 9698C** Yr Regn: **2016** **May**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **Nissan NV200** C.C: **1597**

Colour: **Grey** A/C: Insured / Std / NI / NA

Sp. Reading: **20149** T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **VM 200 88300**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or

Brake: **Inorder** / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or **16.5 / 80R17**

Tyre Size F: \_\_\_\_\_ R: \_\_\_\_\_


BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear
R/Bal. <b>6</b> mm		R/Bal. <b>6</b> mm
L/Bal. <b>6</b> mm		L/Bal. <b>6</b> mm
D.O.A.		D.O.I. <b>5/6/18 @ 1640</b>

Survey held at: **Tan Chong Bkt Timah**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or **Frt N/S, U/C**

The U/C / Chassis frame / Body Structure affected due to collision



Date / Time	Action / Instruction
RECEIVED 16 JUL 2018	

Date/Time. File Pass to?  : Preli. Report

1)  : Final Report

Date/Time. File Return to? **16/7 - typist**

Report Format: **TP**

Lump Sum / I.B.F. (\$) **3959.12**

Days Of Repair: **6** **16/7/18 Taufik**

Resurvey No. of Trip: **1**

Survey Fee: **350**

Transportation: \_\_\_\_\_

S+RS: \_\_\_\_\_

Photos: \_\_\_\_\_

Other: \_\_\_\_\_

TOTAL: **350**

Add Fee:  Site Insp (\$)  Interview (\$)  Tech. Invs (\$)  Weekend (\$)

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 6 June 2018 11:38 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR  
**Subject:** RE: SLU9421G / TP : GBE9698C/LKK / DOA : 12/05/2018 (DSMPC1800936)  
**Attachments:** PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle GBE 9698C  
Date of survey: 5/6/2018  
Number of days:5 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Wednesday, 30 May 2018 12:28 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: SLU9421G / TP : GBE9698C/LKK / DOA : 12/05/2018 (DSMPC1800936)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Wednesday, 30 May 2018 11:33 AM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** OI : SLU9421G / TP : GBE9698C/LKK / DOA : 12/05/2018 (DSMPC1800936)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **TAN CHONG MOTOR SALES PTE LTD**,

ADDRESS : 913 BUKIT TIMAH ROAD  
SINGAPORE 589622

PERSON TO CONTACT : LAWRENCE TEO @ 6703 8914 / 6466 7711

ERGO OFFICER-IN-CHARGE : ROHAINI

***Note: To survey on DIRECT SETTLEMENT basis. Obtain estimate and please advise the consistency of damages to third party vehicle and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are estimate, insured and third party SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: DSMPC1800936/RH/pl  
Our ref: CS/EGI18009761/T1vd3 DATE: 6/5/2018

The Motor Claims Department  
M/s: ERGO INSURANCE PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. GBE 9698C**


We thank you for your instruction on 30/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 5/6/2018 at the premises of M/s TAN CHONG MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$10,984.76
Revised Estimate Amount	: S\$2,931.04
"Check" Items Amount	: S\$5,888.72
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the front n/s portion and undercarriage



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automobile Assessor

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Wednesday, 30 May 2018 11:33 AM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : SLU9421G / TP : GBE9698C/LKK / DOA : 12/05/2018 (DSMPC1800936)  
**Attachments:** SLU9421G - SAS.pdf; GBE9698C - SAS.pdf; GBE9698C - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **TAN CHONG MOTOR SALES PTE LTD**,

ADDRESS : 913 BUKIT TIMAH ROAD  
SINGAPORE 589622

PERSON TO CONTACT : LAWRENCE TEO @ 6703 8914 / 6466 7711

ERGO OFFICER-IN-CHARGE : ROHAINI

**Note: To survey on DIRECT SETTLEMENT basis. Obtain estimate and please advise the consistency of damages to third party vehicle and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.**

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Date: 30.05.2018  
 Our Reference: DSMPC1800936/RH/pl  
 Your Reference: GBE 9698C

Sent via Fax   
 or  
 Email  lawrenceteo@tanchong.com

To: TAN CHONG MOTOR SALES PTE LTD

**Pre-Repair Survey (PRS) Acknowledgement**

Vehicle For Inspection: GBE 9698C  
 Insured's Vehicle: SLU 9421G  
 Date Of Accident: 12.05.2018

We acknowledge receipt of your request for PRS on: 28.05.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- Your request for inspection does not have your client's GIA report, kindly forward a copy.
- We acknowledge your interest for direct settlement, we will assess & revert soon.
- Our Insured's driver has not reported the accident to us todate.
- Others: We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE - ROHAINI

Prepared by: Pei Li      6829 9194      claims@ergo.com.sg  
 Signature: [Signature]      FAX : 6829 9247

**Assessor use only:**  
 Assignment Date: \_\_\_\_\_  
 Assignment Time: \_\_\_\_\_

**Workshop use only:**  
**Assessor attended workshop on:**  
 Date: \_\_\_\_\_  
 Time: \_\_\_\_\_  
 Inspector: \_\_\_\_\_

Remarks:  
 Vehicle not available at the appointed date and time.  
 Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.  
 Note: Our inspection is on a without admission to liability basis.



# CERTIFICATE OF INSURANCE

TOLL 0944K

## NISSAN COMMERCIAL AUTO PROTECTOR COMMERCIAL VEHICLE

Name of Policyholder : ES ASIA TECHNOLOGIES LLP  
 Period of Insurance : 03 May 2018 To 02 May 2019  
 Engine No. : HR16055974D  
 Chassis No. : VM20088300

Vehicle No. : GBE9698C  
 Policy No. : 2100464024-02  
 Endorsement No. :  
 Issued Date : 06 Apr 2018

### ABOUT THE COVER

Make/Model : NISSAN NV 200 PETROL  
 Engine Capacity/Tonnage : 0.8 Tonnage  
 Driver Restriction : NA  
 Sum Insured : Market Value  
 Off Peak Car : No  
 First Year of Registration : 2016  
 Insuring with COE/PARF : Yes

#### Person or Classes of Persons Entitled to Drive\* :

- 1) Any person who is driving on the Policyholder's order or with their permission.
- 2) This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

#### Limitation as to use\* :

- 1) Use in connection with the Policyholder's business.
- 2) Use for the carriage of passenger (other than for hire or reward) in connection with the Policyholder's business.
- 3) Use for social, domestic or pleasure purposes. This Policy does not cover a) use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing; and b) use whilst drawing a trailer except the towing of anyone disabled using a mechanically propelled vehicle. c) use for any purpose in connection with Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

Section 1  
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2  
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Tan Chong Motor Sales Add: 913 Bt Timah Road Singapore 589623 64694091 64694092 64694093
2. TC AutoClinic Add: No.1, Sixth Lok Yang Road Singapore 628098 62622212
3. Tan Chong Motor Sales Add: 17 Lor 8 Toa Payoh Singapore 319254 63570753 63570754
4. Autolution Industrial Add: 19 Ubi Road 4 Singapore 408623 64909666
5. TC AutoClinic Add: 25 Leng Kee Road Singapore 159097 67038511 67038512 67038513

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: TAN CHONG CREDIT PTE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

6500610426

TAN CHONG CREDIT PTE LTD-YKM  
 011 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE  
 SINGAPORE 589622 ANSP-MOTOR  
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*Manile*

AIG Asia Pacific Insurance Pte. Ltd.  
 AUTHORISED REPRESENTATIVE Cally-VV Tsai

7/7/1986 passed date

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S6816070G



Name

ENG CHAN KOON



翁章坤

Race

CHINESE

Date of Birth

Sex

01-06-1968

M

Country of Birth

SINGAPORE



2486317



NRIC No. S6816070G





Blood Group Date of issue

A+ 15-10-1994

Address

APT BLK 224 CHOA CHU KANG CENTRAL  
#04-263  
SINGAPORE 2368





**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**  
6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-18-077941

Date of Request: 22/05/2018

Your Ref No: Online Purchase

Tan Chong Motor Sales Pte Ltd  
911, Bukit Timah Road  
Singapore 589622

Dear Sir/Madam,

Enquiry Date 22/05/2018  
Enquiry By Eric Koh Yong Lang  
TP Vehicle No. SLU9421G  
Accident Date 12/05/2018

#### Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLU9421G	ERGO Insurance Pte. Ltd.	19/12/2017-26/05/2019	6829 9199
SLU9421G	MSIG Insurance (Singapore) Pte. Ltd.	06/09/2017-05/09/2018	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**  
6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-18-077941

Date of Request: 22/05/2018

Your Ref No: Online Purchase

Tan Chong Motor Sales Pte Ltd  
911, Bukit Timah Road  
Singapore 589622

Dear Sir/Madam,

Enquiry Date 22/05/2018  
Enquiry By Eric Koh Yong Lang  
TP Vehicle No. SLU9421G  
Accident Date 12/05/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

GIRO  Cash  Cheque

SC

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/05/2018 10:24
Date Of Accident	12/05/2018 19:00
Exact Location Of Accident	BLK 217 PETIR ROAD 670217
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE9698C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ES ASIA TECHNOLOGIES LLP
Co Reg No	T10LL0944K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97324973
Alternative Phone No	OFFICE-97324973

### Vehicle Particulars

Manufacturer	NISSAN
Model	NV200-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100464024-02
Cover Note Number	

### Driver

Name of Driver	ENG CHAN KOON
NRIC No	S6816070G
Date Of Birth	01/06/1968
Occupation	INDOOR
Date Of Driving Pass	07/07/1986
Driving Experience	31 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97324973
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 224 CHOA CHU KANG CENTRAL  
#04-263

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER ATTACH

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLU9421G

Vehicle Make/Model/Colour KIA CERATO FORTE

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver LEONARD ONG WEI XIANG

NRIC/Passport Number S9832133J

Contact Number 97906442

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 2

Passenger 1  
NAME: : JIMSON HENG YI XIONG  
GENDER: : MALE

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 14 MAY 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:


TAN LHOONG MOTOR SALES PTE LTD  
913 BUKIT TIMAH ROAD  
SINGAPORE 599623  
TEL : 6466 7771 FAX : 6469 7472

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 12 MAY 2018, MY VAN WAS PARKED IN THE CARLOT (OPEN AIR CARPARK). AT AROUND 1900, THE BLACK KIA (SLU 9421 G) MOUNTED THE SIDE CURB OPP BLK 217 AND WITHOUT BRAKING. THE VEHICLE COLLIDED WITH MY VAN. THE IMPACT WAS SO BIG THAT MY VAN REAR SHIFTED UP TO THE CURB.

Location: BLK 217 PETIR ROAD 670217.

CAR INSURANCE COMPANY: ERGO INSURANCE PTE LTD.

DRIVER: LEONARD ONG WEI XIANG

NRIC: S9832133J

HP: 97906442


VEHICLE: SLU 9421 G KIA CERATO FORTE 2.0A SX

CAR OWNER SON: JIMSON HENG YI XIONG

NRIC: S9548117E

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
  
 Policyholder's Signature  
 Date & Time: 14/05/18 10:20

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

TAN CHONG MOTOR SALES PTE LTD  
 913 BUKIT TIMAH ROAD  
 SINGAPORE 689629  
 TEL: 6466 7711 FAX: 6469 7472

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

I, Leonard Ong Wei Xiang, S9832133J admitted that I drove the car, plate number SLN A421 G and hit onto GBE 9698C on 12 May 2018 around 1900 at BK 217 Petir Road. I will take responsibility and payment for this accident and promise to cover the full maintenance and service cost including the lost of use under the amount for renting the car for the period that the van is deemed unusable.

Leul 12/5/2018

Leonard Ong Wei Xiang  
S9832133J

Chan 12/5/2018

Eng Chan Koon  
S6816070G

Ja 12/5/2018

Simon Hong Yi Xiang  
S9548117E

Typo

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

120144  
28/05/18

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/LAW/0185/2018  
DATE : 22-MAY-2018

ERGO INSURANCE PTE LTD  
5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
S(038985)  
TEL : 68299199  
FAX : 68299247/9248  
ATTN : CLAIM MANAGER

OWNER'S NAME : ES ASIA TECHNOLOGIES LLP  
ADDRESS : 21 WOODLANDS CLOSE  
#07-06  
PRIMZ BIZHUB S(737854)  
TELEPHONE NO : 97324973

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : TP-SLU9421G  
VEHICLE NO : GBE9698C  
MODEL CODE : NV200 DX 1.6 A  
MODEL/YEAR : NV200  
ENGINE NO : HR16056051D  
CHASSIS NO : VM20088300  
MILEAGE : 1 KM  
DATE IN : 22/05/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : LAWRENCE  
ACCIDENT DATE : 12/05/2018

**DIRECT SETTLEMENT**  
**OWNER CLAIMING LOSS OF USE / RENTAL**  
**CAR AT WORKSHOP / CAR NOT AT WORKSHOP**  
**KINDLY REVERT TO ME ASAP**  
**EMAIL : lawrenceteo@tanchong.com**  
**H/P : 94568832 FAX : 64697472**

Tanjin 9749374.  
WP  
5/6/18 @ 1640.  
Repairing new parts  
sure@hkauto.com  
5 days.  
  
FK/18.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBE9698C

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	✓ ✓
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	120 ✓
3	RRSCM	REMOVE/REFIX SUSPENSION CROSS MEMBER	120.00	? X
4	RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE LH FRONT	480.00	? X
5	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	✓ ✓
6	WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	✓ ✓
7	ZZ/001	REPAIR LH SUPPORT, LH FRONT FENDER AND RENEW FRONT BUMPER	1800.00	975 1170
8	ZZ/002	S/PAINT LH HEADLAMP FINISHER, LH SUPPORT, LH FRONT FENDER, RADIATOR GRILLE	1600.00	500.725
9	ZZ/003	CODNUCT WHEEL BALANCING LH FRONT STEEL RIM	15.00	? X
TOTAL LABOUR CHARGES			4626.00	

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBE9698C

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN		✓ 200	100.00
2 ORNAMENT-FRONT	62889-WB60A	59.70	? X nn	
3 PROTECTOR-FR, LH FENDER	63843-JX31A	70.00	5? X nn	
4 GRILLE-RADIATOR	62310-JX00B	338.00	? X nn	
5 BRKT-BPR SIDE, L	62225-JX00A	20.90	ner - ✓	
6 CLIP APRON \$1.20 EA X 20	01553-05933	24.00	ner - ✓	
7 BRKT-APRON LWR	62663-5LG0A	210.00	? X nn	
8 ARMATURE ASSY-F	62030-JX01A	559.00	bt - ✓	
9 ENERGY ABSORBER	62090-JX52B	265.10	de - ✓	
10 BUMPER-FRONT LH FINISHER HEADLAMP	62025-JX06A	329.30	? ✓ de	
11 FACE-FR BUMPER	62022-JX00A	487.30	de - ✓	
12 GEAR&LINKAGE	48001-JX00C			1428.00 ? X nn
13 MEMBER	54400-3LR1A			302.50 ? X nn
14 ROD-STABILIZER	54618-JX00A	32.30	? X	} nn X
15 LINK COMPL, LH	54501-1FU0B	200.50	? X	
16 LINK COMPL, LH UPPER	54525-ED001	106.00	? X	
17 CAP-STRUT MTG	54330-ED000	8.00	? X	
18 INSULATOR-STRUT MTG	54321-JX00A	87.30	? X	
19 BRG STRUT MTG	54325-ED02A			126.10 ? X
20 BUMPER ASSY-BOU	54050-AZ100			38.20 ? X
21 STRUT KIT-FRONT	E4303-JX05A			252.80 ? X
22 SPDL-KNU LH	40015-ED000			357.20 ? X
23 HUB ASSY-ROAD W	40202-JX00A			329.70 ? X
24 SFT ASSY-DRIVE	39101-JX01B			861.70 ? X
25 LAMP ASSY-LH	26060-JX31A	405.80	? ✓	

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBE9698C

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		3203.20	0.00	3796.20
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		640.64	0.00	0.00
GRAND TOTAL		2562.56	0.00	3796.20
OVERALL TOTAL		6358.76		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBE9698C

-----

TOTAL LABOUR CHARGES	4626.00
TOTAL SPARE PARTS CHARGES	6358.76
	-----
GRAND TOTAL	10984.76 *
	-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/LAW/0185/2018  
DATE : 22-MAY-2018

ERGO INSURANCE PTE LTD  
5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
S(038985)  
TEL : 68299199  
FAX : 68299247/9248  
ATTN : CLAIM MANAGER

OWNER'S NAME : ES ASIA TECHNOLOGIES LLP  
ADDRESS : 21 WOODLANDS CLOSE  
#07-06  
PRIMZ BIZHUB S(737854)  
TELEPHONE NO : 97324973

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : TP-SLU9421G  
VEHICLE NO : GBE9698C  
MODEL CODE : NV200 DX 1.6 A  
MODEL/YEAR : NV200  
ENGINE NO : HR16056051D  
CHASSIS NO : VM20088300  
MILEAGE : 1 KM  
DATE IN : 22/05/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : LAWRENCE  
ACCIDENT DATE : 12/05/2018

DS

Lawrence

Chick

Revised

#100 X 06

= #600 fast

= #642/-

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBE9698C

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	120.00
3	RRSCM	REMOVE/REFIX SUSPENSION CROSS MEMBER	120.00	.00
4	RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE LH FRONT	480.00	.00
5	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	100.00
6	WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	103.00
7	ZZ/001	REPAIR LH SUPPORT, LH FRONT FENDER AND RENEW FRONT BUMPER	1800.00	1170.00
8	ZZ/002	S/PAINT LH HEADLAMP FINISHER, LH SUPPORT, LH FRONT FENDER, RADIATOR GRILLE	1600.00	725.00
9	ZZ/003	CODNUCT WHEEL BALANCING LH FRONT STEEL RIM	15.00	.00
TOTAL LABOUR CHARGES			4626.00	2266.00

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBE9698C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	SUNDRIES	NPN			20.00	OK
2	ORNAMENT-FRONT	62889-WB60A	59.70			X
3	PROTECTOR-FR, LH FENDER	63843-JX31A	70.00			X
4	GRILLE-RADIATOR	62310-JX00B	338.00			X
5	BRKT-BPR SIDE, L	62225-JX00A	20.90			OK
6	CLIP APRON \$1.20 EA X 20	01553-05933	24.00			OK
7	BRKT-APRON LWR	62663-5LG0A	210.00			X
8	ARMATURE ASSY-F	62030-JX01A	559.00			OK
9	ENERGY ABSORBER	62090-JX52B	265.10			OK
10	FACE-FR BUMPER	62022-JX00A	487.30			OK
11	GEAR&LINKAGE	48001-JX00C			1428.00	X
12	MEMBER	54400-3LR1A			302.50	X
13	ROD-STABILIZER	54618-JX00A	32.30			X
14	LINK COMPL, LH	54501-1FU0B	200.50			X
15	LINK COMPL, LH UPPER	54525-ED001	106.00			X
16	CAP-STRUT MTG	54330-ED000	8.00			X
17	INSULATOR-STRUT MTG	54321-JX00A	87.30			X
18	BRG STRUT MTG	54325-ED02A			126.10	X
19	BUMPER ASSY-BOU	54050-AZ100			38.20	X
20	STRUT KIT-FRONT	E4303-JX05A			252.80	X
21	SPDL-KNU LH	40015-ED000			357.20	X
22	HUB ASSY-ROAD W	40202-JX00A			329.70	X
23	SFT ASSY-DRIVE	39101-JX01B			861.70	X
24	LAMP ASSY-LH <i>plus</i>	26060-JX31A	405.80			OK
25	BUMPER-FRONT LH FINISHER HEADLAMP <i>plus</i>	62025-JX06A	329.30			OK

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBE9698C

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		2091.40	0.00	20.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		418.28	0.00	0.00
GRAND TOTAL		1673.12	0.00	20.00
OVERALL TOTAL		1693.12		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO GBE9698C

---

NETT ITEM	2091.40
LESS 20.00%)	-418.28
NETT AMOUNT	1673.12
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	20.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	20.00
TOTAL LABOUR CHARGES	2266.00
TOTAL SPARE PARTS CHARGES	1693.12
TOTAL CHARGES	3959.12
ADD 7 % GST	277.14
GRAND TOTAL	4236.26

---

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 16 July 2018 9:51 AM  
**To:** 'Lawrence Teo'; Norsipah  
**Cc:** SUR  
**Subject:** RE: GBE 9698C-DOA: 30/5/2018 (ERGO TP)

Dear Lawrence,

WITHOUT PREJUDICE

Confirmed amount \$3959.12 @ 6 working days.

**Please send relevant documents to ERGO Insurance.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Lawrence Teo [mailto:lawrenceteo@tanchong.com]  
**Sent:** Monday, 16 July 2018 9:21 AM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Norsipah <norsipah@tanchong.com>  
**Subject:** RE: GBE 9698C-DOA: 30/5/2018 (ERGO TP)

Dear Veron,

See attached.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd  
913 Bukit Timah Road  
Singapore 589622  
Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472  
Email: [lawrenceteo@tanchong.com](mailto:lawrenceteo@tanchong.com)  
Website: [www.tanchong.com](http://www.tanchong.com) :: [www.nissan.com.sg](http://www.nissan.com.sg)

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Monday, 16 July 2018 9:09 AM  
**To:** Norsipah <norsipah@tanchong.com>  
**Cc:** Lawrence Teo <lawrenceteo@tanchong.com>  
**Subject:** RE: GBE 9698C-DOA: 30/5/2018 (ERGO TP)

Dear Sipah,

\*Please forward us resurvey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Norsipah [<mailto:norsipah@tanchong.com>]  
**Sent:** Friday, 13 July 2018 3:49 PM  
**To:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>  
**Cc:** Lawrence Teo <[lawrenceteo@tanchong.com](mailto:lawrenceteo@tanchong.com)>  
**Subject:** RE: GBE 9698C-DOA: 30/5/2018 (ERGO TP)

Hi

For your finalization.

Best Regards,

Sipah

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

E: [norsipah@tanchong.com](mailto:norsipah@tanchong.com) D:+6567038915

Website: [www.tanchong.com](http://www.tanchong.com) :: [www.nissan.com.sg](http://www.nissan.com.sg)

---

**From:** Lawrence Teo  
**Sent:** Friday, 13 July 2018 3:46 PM  
**To:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>; Norsipah <[norsipah@tanchong.com](mailto:norsipah@tanchong.com)>  
**Subject:** RE: GBE 9698C-DOA: 30/5/2018 (ERGO TP)

Dear Veron,

Vehicle repair done.

Dear Sipah,

Please forward Finalized.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472

Email: [lawrenceteo@tanchong.com](mailto:lawrenceteo@tanchong.com)

Website: [www.tanchong.com](http://www.tanchong.com) :: [www.nissan.com.sg](http://www.nissan.com.sg)

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

**Sent:** Friday, 13 July 2018 3:10 PM

**To:** Lawrence Teo <lawrenceteo@tanchong.com>; Norsipah <norsipah@tanchong.com>

**Subject:** GBE 9698C-DOA: 30/5/2018 (ERGO TP)

Dear Lawrence/Sipah,

Kindly advise vehicle status.

**If vehicle has been repaired, please finalize with us.**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18009761/T1vd3e2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 25-07-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLU 9421G	Veh. Inspected	GBE 9698C
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1800936/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	30/05/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VM20088300	Colour	GREY
Odometer	20149	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	165/80 R14	TOYO	6 mm
L/H Front Tyre	165/80 R14	TOYO	6 mm
R/H Rear Tyre	165/80 R14	TOYO	6 mm
L/H Rear Tyre	165/80 R14	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/05/2018	Inspection Date	05/06/2018
Survey held at	TAN CHONG MOTOR SALES PTE LTD 913, BUKIT TIMAH RD, SINGAPORE 589623.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 9698C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	ORNAMENT-FRONT (N)	NOT NECESSARY	59.70	-
1	PROTECTOR-FR, LH FENDER (N)	NOT NECESSARY	70.00	-
1	GRILLE-RADIATOR (N)	NOT NECESSARY	338.00	-
1	BRKT-BPR SIDE, L (N)	NECESSARY	20.90	20.90
1	CLIP APRON \$1.20 EA x 20 (N)	NECESSARY	24.00	24.00
1	BRKT-APRON LWR (N)	NOT NECESSARY	210.00	-
1	ARMATURE ASSY-F (N)	BENT	559.00	559.00
1	ENERGY ABSORBER (N)	DEFORMED	265.10	265.10
1	BUMPER-FRONT LH FINISHER HEADLAMP (N)	DEFORMED	329.30	329.30
1	FACE-FR BUMPER (N)	DEFORMED	487.30	487.30
1	ROD-STABILIZER (N)	NOT NECESSARY	32.30	-
1	LINK COMPL, LH (N)	NOT NECESSARY	200.50	-
1	LINK COMPL, LH UPPER (N)	NOT NECESSARY	106.00	-
1	CAP-STRUT MTG (N)	NOT NECESSARY	8.00	-
1	INSULATOR-STRUT MTG (N)	NOT NECESSARY	87.30	-
1	LAMP ASSY-LH (N)	CRACKED	405.80	405.80
	LESS 20% DISCOUNT		-640.64	-418.28
			2,562.56	1,673.12
<b>SPECIAL NETT ITEMS</b>				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
1	GEAR&LINKAGE (SN)	NOT NECESSARY	1,428.00	-
1	MEMBER (SN)	NOT NECESSARY	302.50	-
1	BRG STRUT MTG (SN)	NOT NECESSARY	126.10	-
1	BUMPER ASSY-BOU (SN)	NOT NECESSARY	38.20	-
1	STRUT KIT-FRONT (SN)	NOT NECESSARY	252.80	-
1	SPDL-KNU LH (SN)	NOT NECESSARY	357.20	-
1	HUB ASSY-ROAD W (SN)	NOT NECESSARY	329.70	-
1	SFT ASSY-DRIVE (SN)	NOT NECESSARY	861.70	-
			3,796.20	20.00

Report Ref No. CS/EGI18009761/T1vd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION.		48.00	48.00
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL x 03.		360.00	120.00
	REMOVE / REFIX SUSPENSION CROSS MEMBER.	NOT NECESSARY	120.00	-
	REMOVE / REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE LH FRONT.	NOT NECESSARY	480.00	-
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		100.00	100.00
	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE.		103.00	103.00
	REPAIR LH SUPPORT, LH FRONT FENDER AND RENEW FRONT BUMPER.		1,800.00	1,170.00
	S/PAINT LH HEADLAMP FINISHER, LH SUPPORT, LH FRONT FENDER, RADIATOR GRILLE.		1,600.00	725.00
	CONDUCT WHEEL BALANCING LH FRONT STEEL RIM.	NOT NECESSARY	15.00	-
			4,626.00	2,266.00
	<b>GRAND TOTAL</b>		<b>10,984.76</b>	<b>3,959.12</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,959.12</b>

Report Ref No. CS/EGI18009761/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.