

22/03/2002

ASS. REC. BY:

REF: es/FCI18009821/Nrd362

Special Instruction:

Surveyor:  
CWSASSIGNMENT (Office)

From (Person): Karen Tan

of

FCI

Date/Time: 30/5/18 @ 2.55pm

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJE 67542

Insured:

SHD 3346S

at Workshop m/s

Automotive Repair

Tel:

64688834

of

38 Woodlands Ind. park E1 # 05-18

Policy No:

Claim No:

D18004164MP8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/05/2018

CA / REV / REP. / REV 24 HRS

lup

22062018 @ after 10am

H.O.D. Endorsement:

Date/Time:

10.22am @ 31/5/18

Person Contacted:

Suchian

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJE 67542-X
	SHD 3346S-CC3 / TMI 18006122 / K / 4bn2
	DAF: 2/4/18
19/9/18	Confirmed with Paymond LIS 82450 @ 4 days (Red: \$4450, 64%)

REF: FCI

## ASSIGNMENT

From:

Date: 22/06/2018

Veh No: SJE 6754 Z

Yr Regn: May / 2008

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SJE6754Z

Make: Nissan Latio

C.C

at Workshop n/s

Automotive Repair

Colour Gold

A/C Insured / Std / NI / NA

of 38 Woodlands Ind. Park Fl #05-18

Sp. Reading 105511

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No: HR15107467A

Policy No.

C/No: JN1BAACU1Z0004474

Claims No.

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

after 10am


Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: ☒ Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$23000

Tyre Size: F: 185/65 R15

R: 185/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

IDAC Accident Rpt:

Consistent? : Yes or No

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal. 6 mm

L/Bal. 6 mm

Est. Repairs:

days Res.: Yes or No

D.O.A. 22/5/2018

D.O.I. 22/6/2018

Lum Sum:

% 3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS <sup>up</sup>

Vehicle: IN / OUT

Des. of Damages: Frt / ☒ Rear / O/S ☒ N/S / U/C / Rooftop or

N/S Rear

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time. File Pass to?

☐

Preli. Report

1) typist

☒

Final Report

Date/Time. File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format:

TP

Lump Sum / ~~LD~~ (\$) 2450.00

165

50

50

41

286

**MOTOR SURVEY ASSIGNMENT**

Date	24-05-2018	Our Ref No. D18004164MFSH
Accident Date	22-05-2018	Claim Type. Third Party
Insured Vehicle	SHD3346S	Third Party Vehicle. SJE6754Z
Survey Location	38 WOODLANDS INDUSTRIAL PARK E1 #05-18	
Contact Person.	LIN SHU JUAN	
Contact No.	64688834/ 0	Fax No. 64622278
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	AUTOMOTIVE REPAIR CENTRE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/05/2018 21:20
Date Of Accident	22/05/2018 21:10
Exact Location Of Accident	CHANGI AIRPORT T2 AT ARRIVAL HALL TOWARDS CITY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE6754Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHAN SIOK CHEY
NRIC No	S0027954D
Email Address	MARYCHAN99@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91136442
Alternative Phone No	OFFICE-91136442

### Vehicle Particulars

Manufacturer	NISSAN
Model	LATIO 1.5L A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10829475
Cover Note Number	

### Driver

Name of Driver	JEREMY LIA FENGFA
NRIC No	S9010521C
Date Of Birth	03/04/1990
Occupation	INDOOR
Date Of Driving Pass	04/02/2016
Driving Experience	2 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91136442
Fax Number	
Contact Number	
Email Address	MARYCHAN99@GMAIL.COM

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

ACCIDENT STATEMENT (2000 characters)

I was at Changi Airport Terminal 2 arrival hall going straight when a taxi SHD3346S came out from the left side and its front right side collided onto my car left rear passenger door. Damages to my car were left rear passenger door, left rear fender and left rear rims. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

23 May 2018 at 8:16 PM

Date/Time:

23 May 2018 at 8:16 PM

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7954D
<b>Vehicle Details</b>	
Vehicle No.:	SJE6754Z
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	LATIO 1.5L A
Primary Colour:	Gold
Manufacturing Year:	2007
Engine No.:	HR15107467A
Chassis No.:	JN1BAAC11Z0004474
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$15,326.00
Original Registration Date:	02 May 2008
First Registration Date:	02 May 2008
Transfer Count:	0
Actual ARF Paid:	\$15,326.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Apr 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,328.00
COE Rebate Amount:	\$17,835.00
<b>Total Rebate Amount:</b>	<b>\$17,835.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Sep 2018

OK

## Janice Lee (LKKAuto)

---

**From:** raymond@automotiverepaircentre.com.sg  
**Sent:** Wednesday, September 19, 2018 4:41 PM  
**To:** Janice Lee (LKKAuto)  
**Cc:** 'Lin Shu Juan'  
**Subject:** RE: SJE 6754Z

Dear Janice,

We confirmed L/S \$2,450.00 (4 Repair days).

Thank you.

Best Regards,  
Raymond Tan  
**Automotive Repair Centre Pte Ltd**  
38 Woodlands Industrial Park E1  
#05-18, Singapore 757700  
Tel: +65 64688834  
Fax: +65 64622278

---

**From:** Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>  
**Sent:** Wednesday, 19 September 2018 4:18 PM  
**To:** raymond@automotiverepaircentre.com.sg  
**Subject:** RE: SJE 6754Z

Dear Raymond,

As spoken, Kindly assist to re-finalize the above mention vehicle.

Kindly confirm L/S \$2,450.00 @ 4 DAYS

Thank you.

Best Regards,  
**Jannice Lee (Ms) | Case Handler**  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** [raymond@automotiverepaircentre.com.sg](mailto:raymond@automotiverepaircentre.com.sg) [<mailto:raymond@automotiverepaircentre.com.sg>]  
**Sent:** Wednesday, July 25, 2018 4:22 PM  
**To:** Sathya Sai (LKK Auto) <[SathyaSai@lkkauto.com](mailto:SathyaSai@lkkauto.com)>  
**Cc:** CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SJE 6754Z



**ARC****Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

TO Motor Claim Department

**First Capital Insurance Limited**

36 Robinson Road #16-01 City House

Singapore 068877

Tel: 6507 3848, Fax: 65073849

- Lump Sum Repair

- Question mark item photo

- Photo after paint.

**ESTIMATE REPAIR COST****Estimate**

4 days

LKK Auto Consultants hence notify the Repairer of the following:

ESTIMATE NO. EST1405-048

DATE 24 May 2018

POLICY NO. AVIVA 10829475

VEHICLE REG. NO. SJE6754Z

VEHICLE MAKE NISSAN LATO 1.5L A

\* Third party survey is on a "Without Prejudice" basis

\* No illegal modification(s) is allowed

\* Supplementary item(s) must be resurveyed and for Surveyor approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<b>SPARE PARTS</b>				
1	Rear Door LH ✓ Deform	1	\$ 1,100.00	\$ 1,100.00
2	Rear Door Window Regulator LH ✓ BT } NN X	1	\$ 120.00	\$ 120.00
3	Rear Door Window Motor LH ✓ JAM	1	\$ 580.00	\$ 580.00
4	Rear Door Lower Hinge LH x	1	\$ 60.00	\$ 60.00
5	Rear Door Lower Hinge LH x	1	\$ 60.00	\$ 60.00
6	Rear Outer Door Handle LH x	1	\$ 60.00	\$ 60.00
7	Rear Outer Door Handle Cover LH x	1	\$ 20.00	\$ 20.00
8	Rear Door Retractor/Check LH x	1	\$ 50.00	\$ 50.00
9	Rear Door Out Weather Seal LH x	1	\$ 140.00	\$ 140.00
10	Rear Door Inner Seal LH x	1	\$ 100.00	\$ 100.00
11	Rear Upper Door Moulding (Black Sticker) LH ✓ NEC	1	\$ 30.00	\$ 30.00
12	Rear Rear Door Moulding (Black Sticker) LH ✓ NEC	1	\$ 30.00	\$ 30.00
13	Rear Fender LH R	1	\$ 1,100.00	\$ 1,100.00
14	Rear Fender Shield/Garnish LH ✓ Deform	1	\$ 30.00	\$ 30.00
15	Rear Fender Clip ✓ NEC	10	\$ 5.00	\$ 50.00
16	Side Skirt LH ✓ R	1	\$ 480.00	\$ 480.00
17	Nissan Rim ✓ CUT	1	\$ 680.00	\$ 680.00
Total Spare Parts				\$ 4,690.00
<b>SPECIAL NETT</b>				
Total Special Nett				\$ -
<b>LABOUR</b>				
18	S-painting B-Pillar, Side Skirt LH, Rear Fender LH and Door LH	1	\$ 1,000.00	\$ 1,000.00
19	Repair, Replace and Refill Affected Accident Area	1	\$ 1,000.00	\$ 1,000.00
20	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00
21	Wheels Computer Alignment / Wheel Balancing	1	\$ 80.00	\$ 80.00
22	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,210.00
Amount Before Excess				\$ 6,900.00
Add GST @ 7%				483.00
Total Amount Payable				\$ 7,383.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

2620  
- 20%  
2096

2096  
+ 1340  
3436  
- 20%  
2748.8

@ 4 days

confirmed.

**Janice Lee (LKKAUTO)**

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Thursday, September 13, 2018 9:12 AM  
**To:** 'Claim Workflow System'; SUR  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG; assignments  
**Subject:** RE: REMINDER - 3: REQUEST OF SURVEY REPORT-OUR REF:D18004164MFSH;ACCIDENT INVOLVING SHD3346S AND SJE6754Z ON 22-05-2018

Dear Sir / Madam,

Thank you for your email.

Dear Janice,

**FYNA. Our Ref: CS/FCI18009821/Vrd3**

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [mailto:[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)]  
**Sent:** Thursday, 13 September, 2018 8:30 AM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG  
**Subject:** REMINDER - 3: REQUEST OF SURVEY REPORT-OUR REF:D18004164MFSH;ACCIDENT INVOLVING SHD3346S AND SJE6754Z ON 22-05-2018

Dear Sir,

We received LOD from workshop/solicitor.

Please let us have the **Survey Report including Vehicle Inspection Photos & Survey Fees Invoice** asap.

Kindly upload the survey report through CWS from document management screen by selecting option Survey report.

Thanks & Regards,  
Motor Claims Department  
MS First Capital Insurance Ltd  
[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009821/Nrd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-09-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 3346S	Veh. Inspected	SJE 6754Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004164MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	30/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN LATIO	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JN1BAAC11Z0004474	Colour	GOLD	
Odometer	105511	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	FALKEN	6 mm	
L/H Front Tyre	185/65 R15	FALKEN	6 mm	
R/H Rear Tyre	185/65 R15	FALKEN	6 mm	
L/H Rear Tyre	185/65 R15	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/05/2018	Inspection Date	22/06/2018	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 6754Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR DOOR LH	DEFORMED	1,100.00	1,100.00
1	REAR DOOR WINDOW REGULATOR LH	NOT NECESSARY	120.00	-
1	REAR DOOR WINDOW MOTOR LH	NOT NECESSARY	580.00	-
1	REAR DOOR LOWER HINGE LH	NOT NECESSARY	60.00	-
1	REAR DOOR LOWER HINGE LH	NOT NECESSARY	60.00	-
1	REAR OUTER DOOR HANDLE LH	NOT NECESSARY	60.00	-
1	REAR OUTER DOOR HANDLE COVER LH	NOT NECESSARY	20.00	-
1	REAR DOOR RETRACTOR / CHECK LH	NOT NECESSARY	50.00	-
1	REAR DOOR OUT WEATHER SEAL LH	NOT NECESSARY	140.00	-
1	REAR DOOR INNER SEAL LH	NOT NECESSARY	100.00	-
1	REAR UPPER DOOR MOULDING (BLACK STICKER) LH	NECESSARY	30.00	30.00
1	REAR DOOR MOULDING (BLACK STICKER) LH	NECESSARY	30.00	30.00
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,100.00	-
1	REAR FENDER SHIELD / GARNISH LH	DEFORMED	30.00	30.00
10	REAR FENDER CLIP @\$5.00	NECESSARY	50.00	50.00
1	SIDE SKIRT LH	TO REPAIR SEE LABOUR	480.00	-
1	NISSAN RIM	CUT	680.00	680.00
	LESS 10% DISCOUNT		-	-192.00
			4,690.00	1,728.00
	<b><u>LABOUR</u></b>			
	S-PAINTING B-PILLAR, SIDE SKIRT LH, REAR FENDER LH AND DOOR LH.		1,000.00	600.00
	REPAIR, REPLACE AND REFILL AFFECTED ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF REAR FENDER LH AND SIDE SKIRT LH.		1,000.00	600.00
	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR.		100.00	60.00
	WHEELS COMPUTER ALIGNMENT / WHEEL BALANCING.		80.00	50.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			2,210.00	1,340.00

Report Ref No. CS/FCI18009821/Nrd3e2



GRAND TOTAL		6,900.00	3,068.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,450.00

Report Ref No. CS/FCI18009821/Nrd3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.