



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: FY 18/19/0010  
Our Ref: CC2/MIDA18009834/Npq2

**HQ-Transport Command**

Kranji Camp 3  
151 Chua Chu Kang Way  
Singapore 688248

**Attn : CPT MERLIN/ 1WO RAVEEN**

Dear Sir,

**ACCIDENT INVOLVING MID 20504 & SLN 5219M ON 22 MAY 2018**

We refer to the above matter.

We noted that third party lawyer had submitted Property Damage (PD) & Bodily Injury(BI) claim together and the case was handled by AGC.

In view of the above, we will proceed to close our file.

Our note of charges is enclosed for your necessary action.

Summary: -

	Date of submission:	Remarks:
Professional Service Fee		Completed
Disbursement Fee	NA	NA
TCA	NA	NA

Yours faithfully

Chew Hsiao Tong  
Claims Section  
DID: 6742 3197  
Fax: 6741 4108  
E-mail: chewht@lkkauto.com

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Friday, 29 March 2019 12:16 PM  
**To:** 'HQ TPT Safety Branch'  
**Cc:** Joy Irene (LKKAuto); 'CHOY\_Kai\_Wen@agc.gov.sg'; Olivia Lau (LKKAuto)  
**Subject:** RE: Photographs regarding Ref:AG/CIV/ACC/MID/2018/11 \*LKK REF: CC2/MIDA18009834/Npq2  
**Attachments:** LKKInspection.pdf; LKKAdjustment1a.pdf; LKK Survey Photos.pdf; LKK Resurvey Photos 1.pdf; LKK Resurvey Photos 2.pdf

Dear Sirs,

Apologised for later response.

We attached herewith a copy of our survey report and photos for your necessary action.

We will proceed to close file and submit our note of charge to you asap.

Thank you.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** HQ TPT Safety Branch <tptsafety@gmail.com>

**Sent:** Monday, 25 March 2019 11:11 AM

**To:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Kai Wen CHOY (AGC) <CHOY\_Kai\_Wen@agc.gov.sg>

**Subject:** Re: Photographs regarding Ref:AG/CIV/ACC/MID/2018/11

Good morning,

Any updates on this?

Regards,

Raveen

On Mon, Mar 18, 2019 at 2:07 PM HQ TPT Safety Branch <[tptsafety@gmail.com](mailto:tptsafety@gmail.com)> wrote:

Good afternoon Tong and Joy,

May I ask if the survey report has been completed? We have send over the photos on the 27th February and it is close to 3 weeks now with no further updates.

Please update us as soon as possible as the civilian party is close to commencing legal action against us.

Regards,  
Raveen

On Thu, Mar 7, 2019 at 3:44 PM Kai Wen CHOY (AGC) <[CHOY\\_Kai\\_Wen@agc.gov.sg](mailto:CHOY_Kai_Wen@agc.gov.sg)> wrote:

***Message Classification: Restricted***

**AGC Ref: AG/CIV/ACC/MID/2018/11**

**MINDEF Ref: MID 20504**

Dear 1WO Raveen,

The Claimant's solicitors are threatening legal proceedings against the Government if they do not receive an offer of settlement soon.

Please let us know if LKK is ready with their re-survey report for this claim. If they are not, please follow up with them to complete their re-survey report on an urgent basis as we are unable to advise MINDEF on settlement of the matter until we receive LKK's re-survey report.

Please let us know by 8 Mar 2019 when the LKK re-survey report will be ready.

Thank you.

Best Regards,  
CHOY Kai Wen

Manager (Litigation Support) | Civil Division

Attorney-General's Chambers

T (65) 6908 9355 W [www.agc.gov.sg](http://www.agc.gov.sg)

Requests for legal advice/assistance, feedback and queries to the Civil Division may be sent to [AGC\\_CIVIL@agc.gov.sg](mailto:AGC_CIVIL@agc.gov.sg). Emails sent to this address will be retrieved during office hours. If you would like an update on the status of your request (including any sent directly to a legal officer) for legal advice/assistance, please send us an email to [AGC\\_CIVIL@agc.gov.sg](mailto:AGC_CIVIL@agc.gov.sg).

[CONFIDENTIALITY: If you receive this email in error, you should delete it and not disseminate it or its contents in any form. Please also inform the sender that this email has been received in error. This email may contain confidential information and the Official Secrets Act (Cap 213) would make the unauthorised disclosure of this information a criminal offence.]



Taxonomy

[3S-id=2ed29e38-7669-4eb5-8d8f-7b37cd4b618c:895c999b]

---

**From:** Kai Wen CHOY (AGC)  
**Sent:** Friday, 1 February 2019 10:04 AM  
**To:** 'tptsafety@gmail.com' <tptsafety@gmail.com>  
**Cc:** Cassandra LEE (AGC) <Cassandra\_LEE@agc.gov.sg>  
**Subject:** RE: Photographs regarding Ref:AG/CIV/ACC/MID/2018/11

***Message Classification: Restricted***

**AGC Ref: AG/CIV/ACC/MID/2018/11**

**MINDEF Ref: MID 20504**

Dear 1WO Raveen,

I refer to your telephone conversation with Sarah on 30 January 2019, requesting for colour photographs of the civilian vehicle SLN 5219M, and your email below.

As requested, I attach a copy of the survey report dated 6 June 2018 for SLN 5219M prepared by Sincere Appraisal Services. The report encloses colour photographs of SLN 5219M.

Best Regards,

**CHOY Kai Wen**

Manager (Litigation Support) | Civil Division

Attorney-General's Chambers

T (65) 6908 9355 W [www.agc.gov.sg](http://www.agc.gov.sg)

Requests for legal advice/assistance, feedback and queries to the Civil Division may be sent to [AGC\\_CIVIL@agc.gov.sg](mailto:AGC_CIVIL@agc.gov.sg). Emails sent to this address will be retrieved during office hours. If you would like an update on the status of your request (including any sent directly to a legal officer) for legal advice/assistance, please send us an email to [AGC\\_CIVIL@agc.gov.sg](mailto:AGC_CIVIL@agc.gov.sg).

[CONFIDENTIALITY: If you receive this email in error, you should delete it and not disseminate it or its contents in any form. Please also inform the sender that this email has been received in error. This email may contain confidential information and the Official Secrets Act (Cap 213) would make the unauthorised disclosure of this information a criminal offence.]

Taxonomy

[3S-id=f428cb25-246a-4361-acfe-dd9576134d3d:895c999b]

---

**From:** HQ TPT Safety Branch <[tptsafety@gmail.com](mailto:tptsafety@gmail.com)>  
**Sent:** Wednesday, 30 January 2019 4:11 PM  
**To:** Sarah CHUA (AGC) <[Sarah\\_CHUA@agc.gov.sg](mailto:Sarah_CHUA@agc.gov.sg)>  
**Subject:** Photographs regarding Ref:AG/CIV/ACC/MID/2018/11

As spoken,

Please let us have the colour photographs for MID 20504 so that I can follow up on the case

Regards,

Raveen



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MINISTRY OF DEFENCE			Ref : CC2/MIDA18009834/Npq2	
HQ TRANSPORT COMMAND KRANJI CAMP 3 151 CHOA CHU KANG WAYSINGAPORE 688248			Date : 29-03-2019  Code : MIDA	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	MID 20504	Veh. Inspected	SLN 5219M	
Policy No.		Coverage (\$)	0.00	
Claim No.	FY 18/19/0010	Excess (\$)	0.00	
Assign From		Assign Date	24/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF TSI 1.4	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WVWZZZ1KZAW011211	Colour	BLUE	
Odometer	129683	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	TOYO	7 mm	
L/H Front Tyre	225/45 R17	TOYO	7 mm	
R/H Rear Tyre	225/45 R17	DAYTON	7 mm	
L/H Rear Tyre	225/45 R17	DAYTON	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/05/2018	Inspection Date	24/05/2018	
Survey held at	A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 5219M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER ASSY	BUCKLED	1,271.20	1,000.00
1	FRONT BUMPER LEFT RETAINER	DEFORMED	88.90	88.90
1	FRONT BUMPER LOWER COVER	DEFORMED	450.50	350.00
1	FRONT LEFT BUMPER BRACKET	SERVICEABLE	84.30	-
1	FRONT LEFT HEADLAMP	CRACKED	1,198.20	1,000.00
1	FRONT LEFT FENDER ASSY	CUT	850.10	850.10
1	FRONT LEFT FENDER INNER COWLING	TORN	260.70	260.70
1	FRONT LEFT DOOR PANEL	TO REPAIR SEE LABOUR	2,480.10	-
1	FRONT LEFT WING MIRROR COMPLETE ASSY	NOT WORKING	1,400.80	1,000.00
1	FRONT LEFT KNUCKLE ARM	SERVICEABLE	864.50	-
1	FRONT LEFT LOWER ARM CARRIER	SERVICEABLE	637.20	-
1	FRONT LEFT FOG LAMP	CRACKED	282.00	282.00
1	FRONT LEFT FOG LAMP GARNISH	SCRATCHED	165.00	165.00
1	FRONT LEFT SUSPENSION ASSY	BENT	990.70	400.00
1	FRONT LEFT WHEEL HUB BEARING	NECESSARY	261.80	261.80
1	FRONT GRILLE ASSY	CRACKED	262.10	262.10
	LESS 10% DISCOUNT		-1,154.81	-592.06
			10,393.29	5,328.54
<b>SPECIAL NETT ITEMS</b>				
12	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
10	FRONT BUMPER LOWER COVER CLIPS (SN)	NECESSARY	30.00	30.00
8	FRONT LEFT FENDER INNER COWLING CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT LEFT SPORTS RIM (SN)	GRAZED	750.00	580.00
1	FRONT LEFT TYRE (SN)	SERVICEABLE	400.00	-
			1,260.00	690.00
<b>LABOUR</b>				
	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN FRONT LEFT AFFECTED AREA AND REPLACE FRONT LEFT DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT LEFT DOOR PANEL .		900.00	500.00

Report Ref No. CC2/MIDA18009834/Npq2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING FRONT LEFT PORTION .		900.00	500.00
	TO APPLY ANTI PROOFING TO FRONT LEFT AFFECTED AREA.		100.00	50.00
	TO REMOVE AND INSTALL FRONT LEFT UNDERCARRIAGE PARTS.		280.00	100.00
	TO CONDUCT WHEEL ALIGNMENT.		80.00	60.00
	TO BALANCE FRONT LEFT WHEEL .		50.00	30.00
	TOWING SERVICE.	NOT NECESSARY	100.00	80.00
			2,410.00	1,320.00
	<b>GRAND TOTAL</b>		<b>14,063.29</b>	<b>7,338.54</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,900.00</b>

Report Ref No. CC2/MIDA18009834/Npq2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLN 5219M

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 5219M

RE-INSPECTION









## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 5219M

RE-INSPECTION





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

