



南方摩哆

SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel:62730369 Fax:62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 25th May 2018
Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way # 07-16 AIG Building
Singapore 079120

Dear Sirs

Re: Cost of repair to Suzuki DRZ 400SM - FSM 1669Y

1 pc of Handle bar	DA	210.00 ?
" Clutch lever		45.00 ant ✓
" Clutch cable		65.00 dis ✓
" Handle grips		25.00 fr ✓
" Handle switch LH		145.00 dis ✓
" Front fairing headlamp unit		225.00 ant ✓
" Front rim sliders		110.00 ant ✓
" Clutch lever		95.00 ant ✓
2 pcs of Centre fairing		350.00 ant ✓
1 pc of Rear signal		25.00 dis ✓
" Body sliders		140.00 ant ✓
" Rear rim sliders		110.00 ant ✓
" Magneto cover		255.00 dis ✓
" Brake pedal		115.00 bt ✓
" Rear brake pump		235.00 dis ✓
" Rear Footrest bracket		25.00 bt ✓
" Side box Rear RH fender		350.00 int ✓
" Clutch cover		350.00 dis ✓
		<hr/>
		3035.00
		1303.50
		<hr/>
		2731.50

Tanpin 77495749
- WP
01/06/18 @ 1230
Insurance
Ready after repair
5 days.
Surrender amount
Yours faithfully,
SOUTHERN MOTOR

Less 10%
Nett

Transport	30.00 ✓
Basket	35.00 ✓ sec
Engine oil	60.00 new ✓
1 set of No plates	25.00 bt ✓
Jack body	250.00 180
Evulant	25.00 X
Jack fork & alignment	140.00 100
Lebow	250.00 200
	<hr/>
	2731.50

Tel 64193000
Fax 64153727