

15/9/2019

INS. CASE OWNER:

CC 4/LPC1800

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

world
auto

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 3,550

(8 days)

Reduction:

46 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

100 %

(Agreed / Assessed) BOLA S/N No.:

8a

If NO or B 28, Ass. Lia:

Repair Cost:

SS 3,798.50

DID TRAVELING INTO THE MAIN DRIVE WAY.

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 480.00

(\$ 60 x 8 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS 200

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+150

Total:

SS 4,280.50

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

SS 4,280.50

Name 1:

WORLD AUTO PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

(09/11/13)

Surveys

REF:

48976

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 65076

at Workshop m/s WORLD AUTO

of No. 1 KANSI LANE

Insured: LONGALUP

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLH 65076 Yr Regn: 2016 / NSW

Type: C M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA SHUTTLE 1.5 HB C.C. 1796

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP 71043626

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R16

R: . .

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 27/05/18 D.O.I. 01/06/18

Survey held at WORLD AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

48: +3,580 (RED: +3,018 46%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18009925/R1eb3		
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		Date : 01-06-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 9937J	Veh. Inspected	SLH 6507G	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	01/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/05/2018	Inspection Date	01/06/2018	
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18009925/R1eb3

Date: 06.06.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLH6507G


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.06.2018 at the premises of M/s World Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	6,568.00
Revised Estimate Amount	: S\$	4,524.00
"Check" Items Amount	: S\$	336.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 8 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Asker

Celine Fong (LKKAUTO)

From: tggtan@worldauto.com.sg
Sent: Friday, 12 October 2018 2:08 PM
To: Celine Fong (LKKAUTO)
Subject: RE: OUTSTANDING CASES - Rasul - VEHICLE NO. SLH 6607G

Hi Celine

Finalised COR \$ 3550 and 8 days of repairs.

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

From: Celine Fong (LKKAUTO) <celinefong@lkkauto.com>
Sent: Friday, 12 October 2018 11:18 AM
To: tggtan@worldauto.com.sg
Cc: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: RE: OUTSTANDING CASES - Rasul - VEHICLE NO. SLH 6607G

Dear Sophia,

Lump sum \$3,550.00, 8 days

Please check.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>
Sent: Tuesday, 11 September 2018 5:56 PM
To: Celine Fong (LKKAUTO) <celinefong@lkkauto.com>
Subject: FW: OUTSTANDING CASES - Rasul

Hi Celine

Can assist these files for Rasul

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD
100 BEACH RD #19-00 SHAW TOWER
S'PORE 189702

Attention : Motor Claim Department
Contact : 62507388 Fax No. : 62963767

Estimate : ES000140

Date : 30/05/2018
Vehicle Num. : SLH 6507G (LCR) 2016 NOV
Make/Model : HONDA SHUTTLE HYBRID 4P 7104 3626
Chassis/Eng# :
Accident Date : 27/05/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|-----|---|-------------------------------|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | FRONT FENDER - RH | | |
| 3. | 1 | FRONT FENDER HYBRID EMBLEM RH | | |
| 4. | 1 | FRONT DOOR - RH | | |
| 5. | 1 | FRONT DOOR GLASS REGULATOR RH | | |
| 6. | 1 | FRONT DOOR HINGE LOWER RH | | |
| 7. | 1 | FRONT DOOR HINGE UPPER RH | | |
| 8. | 1 | REAR DOOR - RH | | |
| 9. | 1 | REAR DOOR GLASS REGULATOR RH | | |
| 10. | 2 | SIDE SKIRT RH | | |
| | | WHEEL CAP | | |

List Total S\$:
20.00% Discount S\$:

LABOUR :
TRANSFER DOOR MECHANISM (X2 DOORS)

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER
TO REPAIR INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
PANEL WHERE NECESSARY & REPLACE ABOVE ITEMS

PUTTY & SPRAY PAINT ON ALL AFFECTED AREAS

Labour Total S\$:

550.00 Repair
38 100.00
1,200.00
210.00
80.00
80.00
1,200.00
210.00
430.00
200.00
4,260.00
852.00
3,408.00

350.00 120
1,200.00 800
1,500.00 1100
3,160.00

E. & O.E.

Total S\$: 6,568.00

for WORLD AUTO PTE LTD

Repair
Hp 90010068
8 days
4/5
01/06/18 P 1635
Repair after repair

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD

100 BEACH RD #19-00 SHAW TOWER

S'PORE 189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62963767

Estimate : ES000140

Date : 30/05/2018

Vehicle Num. : SLH 6507G (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 27/05/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

- | | | | | |
|-----|---|-------------------------------|--------|---------------|
| 1. | 1 | FRONT FENDER - RH | | 550.00 Repair |
| 2. | 1 | FRONT FENDER HYBRID EMBLEM RH | | 100.00 na - |
| 3. | 1 | FRONT DOOR - RH | | 1,200.00 PA - |
| 4. | 1 | FRONT DOOR GLASS REGULATOR RH | | 210.00 ? |
| 5. | 1 | FRONT DOOR HINGE LOWER RH | | 80.00 X |
| 6. | 1 | FRONT DOOR HINGE UPPER RH | | 80.00 X |
| 7. | 1 | REAR DOOR - RH | | 1,200.00 PA - |
| 8. | 1 | REAR DOOR GLASS REGULATOR RH | | 210.00 ? |
| 9. | 1 | SIDE SKIRT RH | | 430.00 sch - |
| 10. | 2 | WHEEL CAP | 100.00 | 200.00 sch - |

List Total S\$:

20.00% Discount S\$:

4,260.00

852.00

3,408.00

LABOUR :

TRANSFER DOOR MECHANISM (X2 DOORS)

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER
TO REPAIR INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
PANEL WHERE NECESSARY & REPLACE ABOVE ITEMS

PUTTY & SPRAY PAINT ON ALL AFFECTED AREAS

Labour Total S\$:

350.00 120

1,200.00 800

1,600.00 1100

3,160.00

E. & O.E.

Total S\$: 6,568.00

=====

for WORLD AUTO PTE LTD

Repair
4p 900/10068
8 days
L/S
01/06/18 @ 1635
Repair after repair

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 1 June 2018 11:37 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG; ainee@worldauto.com.sg
Subject: FW: Request for Third Party Motor Claim Resurvey

12:19pm @ 1/6/18
person @ sofia
vehicle @ In
SUR @ Resurvey

Our Ref : 17/18/18/VP05/020639

Dear Catherine,

Kindly proceed to conduct the survey as detailed below.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Ainee31 [mailto:aine31@worldauto.com.sg]
Sent: Friday, 1 June, 2018 11:27 AM
To: MT_Claim_SG
Subject: Request for Third Party Motor Claim Resurvey

Good morning/afternoon,
We would like to request for a third party motor claim survey, details as follow;

Our Vehicle: SLH6507G
Your Insured: SJU9937J
DOA: 27-05-2018

Our vehicle is currently in the workshop, address as follow;
AINEE
World Auto Pte Ltd
No.1, Kranji Loop
Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee

Thanks and Rgds,

World Auto Pte Ltd

Kranji: 63621776

Fax: 64557576

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 7 June 2018 9:33 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Request for Third Party Motor Claim Resurvey ***LKK REF:CC4/LPC18009925/R1eb3
Attachments: 07062018093026.pdf

Dear Shu Pei,

Attached a copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 6 June, 2018 5:28 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAUTO)
Subject: RE: Request for Third Party Motor Claim Resurvey ***LKK REF:CC4/LPC18009925/R1eb3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLH 6507G at M/s World Auto Pte Ltd.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Kindly let us have a copy of your insured's GIA report for our necessary action.

Our case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 1 June 2018 12:21 PM
To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; ainee@worldauto.com.sg; Admin A <admin-a@lkkauto.com>
Subject: RE: Request for Third Party Motor Claim Resurvey

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]
Sent: Friday, 1 June 2018 11:37 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>; ainee@worldauto.com.sg
Subject: FW: Request for Third Party Motor Claim Resurvey

Our Ref : 17/18/18/VP05/020639

Dear Catherine,

Kindly proceed to conduct the survey as detailed below.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Ainee31 [<mailto:aine31@worldauto.com.sg>]
Sent: Friday, 1 June, 2018 11:27 AM
To: MT_Claim_SG
Subject: Request for Third Party Motor Claim Resurvey

Good morning/afternoon,

We would like to request for a third party motor claim survey, details as follow;

Our Vehicle: SLH6507G

Your Insured: SJU9937J

DOA: 27-05-2018

Our vehicle is currently in the workshop, address as follow;

AINEE
World Auto Pte Ltd
No.1, Kranji Loop
Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee

Thanks and Rgds,

World Auto Pte Ltd

Kranji: 63621776

Fax: 64557576

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 19 June 2018 8:58 AM
To: 'ainee31@worldauto.com.sg'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: RE: Request for Third Party Motor Claim Resurvey ***LKK REF:CC4/LPC18009925/R1eb3

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]
Sent: Friday, 1 June 2018 11:37 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>; ainee@worldauto.com.sg
Subject: FW: Request for Third Party Motor Claim Resurvey

Our Ref : 17/18/18/VP05/020639

Dear Catherine,

Kindly proceed to conduct the survey as detailed below.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Ainee31 [<mailto:aine31@worldauto.com.sg>]

Sent: Friday, 1 June, 2018 11:27 AM

To: MT_Claim_SG

Subject: Request for Third Party Motor Claim Resurvey

Good morning/afternoon,

We would like to request for a third party motor claim survey, details as follow;

Our Vehicle: SLH6507G

Your Insured: SJU9937J

DOA: 27-05-2018

Our vehicle is currently in the workshop, address as follow;

AINEE

World Auto Pte Ltd

No.1, Kranji Loop

Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee

Thanks and Rgds,

World Auto Pte Ltd

Kranji: 63621776

Fax: 64557576




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18009925/R1eb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 11-02-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 9937J	Veh. Inspected	SLH 6507G	
Policy No.	Z17VP05014161	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020639	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	01/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE 1.5 HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	GP71043626	Colour	GREY	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R16	PIRELLI	5 mm	
L/H Front Tyre	185/60 R16	PIRELLI	5 mm	
R/H Rear Tyre	185/60 R16	PIRELLI	5 mm	
L/H Rear Tyre	185/60 R16	PIRELLI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/05/2018	Inspection Date	01/06/2018	
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 6507G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER -RH	TO REPAIR SEE LABOUR	550.00	-
1	FRONT FENDER HYBRID EMBLEM RH	NECESSARY	100.00	38.00
1	FRONT DOOR -RH	BENT	1,200.00	1,200.00
1	FRONT DOOR GLASS REGULATOR RH	SERVICEABLE	210.00	-
1	FRONT DOOR HINGE LOWER RH	SERVICEABLE	80.00	-
1	FRONT DOOR HINGE UPPER RH	SERVICEABLE	80.00	-
1	REAR DOOR -RH	BENT	1,200.00	1,200.00
1	REAR DOOR GLASS REGULATOR RH	SERVICEABLE	210.00	-
1	SIDE SKIRT RH	SCRATCHED	430.00	430.00
2	WHEEL CAP @\$100.00	SCRATCHED	200.00	160.00
	LESS 20% DISCOUNT		-852.00	-605.60
			3,408.00	2,422.40
LABOUR				
	TRANSFER DOOR MECHANISM (X2 DOORS).		360.00	120.00
	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIR INCLUDING PANEL BEAT ,CUT/WELD ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE ITEMS.INCLUSIVE OF THE REPAIR OF FRONT FENDER -RH .		1,200.00	800.00
	PUTTY & SPRAY PAINT ON ALL AFFECTED AREAS.		1,600.00	1,100.00
			3,160.00	2,020.00
GRAND TOTAL			6,568.00	4,442.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,550.00

Report Ref No. CC4/LPC18009925/R1eb3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.