

SHC 8988L

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,000.00 700/-
	Spray Painting Charge			\$ 800.00 600/-
	Wiring Charge			\$ 50.00 22
	Tuff Kote			\$ 80.00 30/-
	Towing Charge			\$ 50.00 42
	Remove/Refix Cushion & Upholstery Rear			\$ 80.00 60/-
	Remove/Refix Rear Windscreen Glass			\$ 100.00 80/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Transfer of Door			\$ 80.00 60/-
	Rear Wheel Alignment			\$ 80.00 60/-
	TOTAL LABOUR			\$ 2,520.00
	ESTIMATE TOTAL			\$ 11,458.04
	01/06/2018 @ 1330m Not Actual 2/5mm 6 7 days. LKK Auto			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			