From: Date:	Veh No: SJX4211L	Yr Regn: 2011	/ Nov -
Estimated Cost:	Type: M.Car/ M.Cycle / Bus / Van / Lorry	/ Taxi / Prime Move	r l
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or		
To Inspect Vehicle No:	Make: Audi AS SB	c.c	984 -
CESTS (100 CONT. 190 CONT. 100 CONT.	Colour Grey. A	VC: Insured / St	d / NI / NA
at Workshop m/s		/Radio: Insured / S	td / NI / NA
of	Eng/No:		
Policy No. 2100316652	CNO: WAUZZZ 8T45	3A10818D .	
61 1-101 202 5/2	Gen. Cond: Good / Fair / Poor / Burnt		
Alum)	Steering: Inorder / Jammed / Leaked / Bu	rnt or	
The state of the s	Brake: Inferder / Jammed / Leaked / Bu		
(Client's Record)	Modi: Nil /S/Rim / STD A/Rim or		
Make of Veh:	2006/112	R18.	
	Tyre Size: F: 245/40R	Part of the Control o	
(Policy Condition)  Remark: The yet had commenced its.  N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MI	-	SUMI /
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	TOYO/YOKO or	o i omi oo i oo ii oo	
TOK		Rear	
Dat of Market Forces	R/Bal. 06 mm	R/Bal.	mm
IDAC Accident Rport: Consistent? : Yes or No	1 N	L/Bal.	
GIA / PR Seen: Consistent? : Yes or No	D.O.A. mm	D.O.I. 01/0	1
Est. Repairs: Ves or No	0	2000	110
Lum Sum: % 3 Val.: Yes or No	0011011101000	The state of the s	n of
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear O/S / N	IS / U/C / Rootto	p or
Vehicle: IN / OUT  Date: Person Contacted:	The U/C / Chassis frame / Body S	tructure affected du	ue to collision.
Date / Time   Action / Instruction	the old / chassis frame / body c		
bale / Time Action / Historian			
33x 42112 - NA/INC[8107766/h4	DA: 7	7052018	
04/c/188 4.36/ revert to victor you main	un,		
516-@ Authorise repair at 11:39 516-Inform premium authorise	am by notor		
5/6- Inform premium authorse	vepair excess \$1400	-	
2 2 210 110 10 8 5	Jama [ pod 14723 11	0 5207 ]	
Confirm \$ 10,241 60 @ 50		0.0010	
RECEIVED 2 8 S	SEP 2018		
Date/Time, File Pass 107 : Preli. Report	Days Of Repair: 5	-	
1269 Typist T: Final Report	Resurvey No. of Trip:	Survey Fee:	200
Date/Time, File Return to?	122	Transportation:	10
Add Fee		) _ S+RS SF	
# E	Interview (\$	) Pholos	
Report Format:	Tech, Invs (\$	) Others	
Lump Sum / LB.I: (% 10241-60 )	Weekend (\$	-	
		TOTAL	210

#### Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn:

Dally Amri, Mimi Zarina

04 Jun 2018

#### Preliminary Advice

Vehicle No

: SJX4211L

Accident Date

: 27/05/2018

Make

: AUDI A5

Policy No.

Assignment Date

: 01/06/2018

Excess

: \$\$1,400.00

Date of Inspection

: 01/06/2018

Est. Duration of Repair

: 8.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,475.00
Revised Amount	:S\$	12,703.00
Check Items (Estimated)	:S\$	144.00
Total	:S\$	12,847.00

Lump Sum Repair

:S\$

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	57,354.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,646.00

#### Remarks

- The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments: REPAIRER AGREED REPAIR COST NOT MORE THAN \$12,600.00.

#### Note: This document has not been finalised.

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Dally Amri, Mimi Zarina

Date:

04 Jun 2018

#### **Preliminary Advice**

Vehicle No

: SJX4211L

Accident Date

: 27/05/2018

Make

: AUDI A5

Policy No.

Assignment Date

: 01/06/2018

Excess

:\$\$

: S\$1,400.00

Date of Inspection : 01/06/2018

Est. Duration of Repair

: 8.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,475.00
Revised Amount	:S\$	12,703.00
Check Items (Estimated)	:S\$	144.00
Total	:S\$	12,847.00

Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	57,354.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,646.00

#### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kin	dly
N.	10510	let us have your authorisation.	

1	The vehicle is	s uneconomical	to be	repaired,	you are advised	to	invite	tender	for	the	wrec	:k
---	----------------	----------------	-------	-----------	-----------------	----	--------	--------	-----	-----	------	----

Other comments:

#### Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Tuesday, 5 June 2018 1:47 PM

To:

Claims; SUR

Subject:

RE: OD CLAIM FOR SJX 4211 L

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SJX 4211L (Excess \$1400/-). NOT MORE THAN \$12,600/-

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Tuesday, 5 June 2018 8:27 AM

To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: OD CLAIM FOR SJX 4211 L

Dear all,

Any update for this case?

Thank you.

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

No record

### Claim Audit

A	UDIT TRAIL			0
0,	On	Audit	Remarks	By () Maximum
	28 May 2018 17:34	Clm Veh Model Changed		[] Merimen Administrato
	28 May 2018 17:34	Clm Created	Reg No: SJX4211L. Policy No: 2100316652-05. Acct Date: 2018/05/27. Claim Typ e: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notificatio n, Created from SAS:MPA118068791	[I] Merimen Administrato []
3	01 Jun 2018 17:20	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	CATHERINE CHONG KAI LING
4	01 Jun 2018 17:20	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	CATHERINE CHONG KAI LING
5	01 Jun 2018 17:20	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING [A]
6	01 Jun 2018 17:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/12	CATHERINE CHONG KAI LING
7	01 Jun 2018 17:20	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	01 Jun 2018 17:20	Clm Registration Modified	Rep:1137->200611.	(A) CATHERINE CHONG KAI LING
9	01 Jun 2018 17:20	Clm Veh Model Changed	(202377) AUDI A5 2.0 SPORTBACK QUATTRO (A).	[A] CATHERINE CHONG KA LING
10	01 Jun 2018 17:20	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	04 Jun 2018 10:12	Clm Registration Modified	Acct Time:14:45:00->14:00:00.	[I] AIG OneClaim Integration User
12	04 Jun 2018 11:42	Clm Registration Modified	Init,Est.:->6,000 - 7,000. Excess: -> 1400.00. 2F Remarks: -> Not Applicable. GS T: -> 7.00.	[I] Dally Amri, Mimi Zarina
13	04 Jun 2018 11:42	Label Added	(20226):Coverage Confirmed.	[A] Merimer Administrato [A] DENISE
14	04 Jun 2018 14:00	Adj Rpt Initiated		TAY KWEE CHENG [A] DENISE
15	04 Jun 2018 14:00	Clm Dtl Modified	JPJ Reg. Date: -> 2011/11/30.	TAY KWEE CHENG [A] DENISE
16	14:00	Clm Details Notified		TAY KWEE CHENG
17	04 Jun 2018 16:35	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/12  Cur.Req:12847.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER	[A] SHIAU CHAN
18	04 Jun 2018 16:36	Adj Mandate Request	AGREED REPAIR COST NOT MORE THAN \$12,600.00. WE HAVE NOT AUTHORISE R EPAIR.	[A] SHIAU CHAN
19	05 Jun 2018 11:39	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/06/12. Mandate Remarks: Dear Adrian, Please checked again photographs upload into Merimen is the correct vehicle? Re-inspection to be done for damage check and supplementary items / labour.	Ken-FK
20	05 Jun 2018 11:39	Adj Mandate Set	Approved:12847.00:Dear Adrian, Please checked again photographs upload into Me rimen is the correct vehicle? Re-inspection to be done for damage check and supple mentary items / labour.	[I] Wong, Ken-FK

Date From	■ Date To	Audit Type None	▼ Go
ACTIVITY			

terimen Billin	g for this case - '	Transaction H	istory	7.1			
Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref. 2	Amount
1822840	04/06/2018 14:00	Motor	LKK Auto Consultants Pte	LKK Auto Consultants Pte	SJX4211L		10.70

#### > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	1093F	
Vehicle No.:	SJX4211L	
Vehicle to be Exported:	No	
Intended De-registration Date:	04 Jun 2018	
Vehicle Make:	AUDI	
Vehicle Model:	A5 SPORTBACK 2.0 TFSI QU	
Primary Colour:	Grey	
Manufacturing Year:	2011	
Engine No.:	CDN228828	
Chassis No.:	WAUZZZ8T4BA108180	
Maximum Power Output:	155.0 kW (207 bhp)	
Open Market Value:	\$47,537.00	
Original Registration Date:	30 Nov 2011	
First Registration Date:	30 Nov 2011	
Transfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$47,537.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	29 Nov 2021	
PARF Rebate Amount: Intended COE Rebate Details	\$30,899.00	
COE Expiry Date:	29 Nov 2021	
COE Category:	E - Open Category	
COE Period(Years):	10	
QP Paid:	\$75,889.00	
COE Rebate Amount:	\$26,455.00	
Total Rebate Amount:	\$57,354.00	

The information contained herein is correct as at 04 Jun 2018

ОК

MPA118068791 / Premium Automobiles Pte Ltd - UBI ENTRY DATE & TIME: 28/05/2018 09:31 SUBMITTED BY: Mastura Binte Osman Basah

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date Of Report

28/05/2018 09:31

Date Of Accident

27/05/2018 14:45

Exact Location Of Accident

FAR EAST SHOPPING CENTER CARPARK

SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number

SJX4211L

Insured/Policyholder

Country/State of Loss

Name Of Registered Owner

ANDRE MOSES TAN CHANG ANN

NRIC No

S7831093F

Email Address

EARTHMUDDER@GMAIL.COM

Mobile Phone No

(LOCAL) +65-96330418

Alternative Phone No

OTHERS-96330418

Vehicle Particulars

Manufacturer

AUDI

Model

A5 SB 2.0 TFSI QU 8T

Exact Purpose for which vehicle was being used at PRIVATE USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

2100316652-05

Cover Note Number

Driver

Name of Driver

ANDRE MOSES TAN CHANG ANN

NRIC No Date Of Birth S7831093F 23/10/1978

Occupation

INDOOR

Date Of Driving Pass

21/07/2005

Driving Experience

12 YEARS AND 10 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-96330418

Fax Number

Contact Number

OTHERS-96330418

EMail Address

EARTHMUDDER@GMAIL.COM

Address BLK 476 TAMPINES STREET 44

#03-175

Postcode 520476

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? No

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

I WAS MAKING A RIGHT TURN IN A TIGHT SPACE AND MISJUDGEED THE SPACE I HAD. I GRAZED HIS PARKED CAR ON THE FRONT RIGHT CORNER OF HIS BUMPER AND SMALL CRACK ON HIS HEADLIGHT. DAMAGE TO MY CAR IS ON RIGHT REAR PASSENGER DOOR AND TYRE AREA.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SKN338Y

Vehicle Make/Model/Colour

BMW / MATTE WHITE

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LIM CHANG TAT

NRIC/Passport Number

E569588H

Contact Number

82288677

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

#### SKETCH PLAN

u

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The Issue and acceptance of this Form by insurance companies is not an admission of policy Bability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes, and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholdes Synature

Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

De

Reporting Centre Personnel's Signature

Name Toy Foody NRIC/FIN NO. 6 20+1997K

#### Sketch Plan #2

SKETCH PLAN



Veh B: SKN338Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
I was moling a right turn in a tright,
space and disjudged the space Phend.
I grazed his radied can on the
front right corner of his bunger
front right corner of his bunger and shall wade od his headlight.
O .
Damare to my ear in our right near
Damare to my ear in our right near possenger door and type onen

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder & Date & Time Signature

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name Tony Forny NRSC/FIN NO.: GERHALOTA



#### REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7831093F





Name

ANDRE MOSES TAN CHANG ANN

Rece

CHINESE Date of birth

5/83/093F

23-10-1978 M SINGAPORE

4406240 MRIC No. S7831093F

22-05-2009

APT BLK 476 TAMPINES STREET 44 #03-175 SINGAPORE 520476

# E LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

PASS DATE

Monte cars =< 200 CC

Monte cars =< 3000 kg with =< 7 passengers, exclusive of the driver; and motor tractors/vehicles =< 2500 kg

29 Jul 2004 26 Jan 2006

S / No. 9000041426


# DRIVING LICE S7831093F



ANORE MOSES TAN CHANG

(ANDRE MOSES CHEN ZHANG'AN)

10000 Date 23 Oct 1978





### CERTIFICATE OF INSURANCE

#### AUDI AUTO PROTECTOR PRIVATE VEHICLE

: CDN228828

Name of Policyholder

: Andre Moses Tan Chang Ann

Period of Insurance

: 30 Nov 2017 To 29 Nov 2018

Engine No. Chassis No.

: WAUZZZ8T4BA108180

Vehicle No.

: SJX4211L

Policy No.

: 2100316652-05

Endorsement No.

Issued Date

: 01 Nov 2017

#### ABOUT THE COVER

Make/Model

: AUDI A5 SPORTBACK 2.0 TFSI QU

Engine Capacity/Tonnage : 1,984.00 CC

Sum Insured : Market Value

First Year of Registration : 2011

Driver Restriction

: NA

Off Peak Car : No

Insuring with COE/PARF : Yes

#### Person or Classes of Persons Entitled to Drive":

a) time Posicynologier
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition

: All Age Condition

Limitation as to use\* :

Use only for social, domestic, and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tustion, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Parry Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Section 1 Fire - S0 Own Damage - \$1400 Theft - \$0 Flood Cover - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Andre Moses Tan Chang Ann - \$1400 (Own Damage)

#### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/ArG Authorised Repairers, please contact our 24-hour accident emergency holline at +65 6338 6200. Attemptively, you may refer to ArG website www.akg.com.ag. or ArG SG from iTunes or Google Play.

#### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: POST OFFICE SAVINGS BANK

(We hareby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189). Part IV of the Road Transport Act. 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules: 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

#### IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES

#### What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

#### What should I do in the event of an accident?

- Keep gain, and move your car to a safe place.

  Do not admit or discuss fault or blame with the other party(ies).

  Report the accident to us with your accident vehicle (whether day via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- mone/Corresponde immediately.

#### If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, rame and address, insurance company and policy number of the other driver(s) and vehicle(s). Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

#### If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.

  Record vehicle number, name and address, insurance company and policy number of the other driven's) and vehicle(s), if applicable

  Collect details (name, address and contact number) of witnesses and/or by to take photographs of the scene of the accident.

  Report the accident to us with your accident vehicle (whether demaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

#### LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

#### Steps to activate Loss of Use Car Replacement Benefit and Important Information

- 1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
- 2. Your rental car will be made available within 3 working hours of activation with the Rental Car Company.
- 3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
- 4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy
- 5. Rental cars are strictly for use in Singapore only.
- Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day
- 7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223 55 Ubi Road 1 Singapore 408699

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

\*The Rental Car Company a Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

#### IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### Telefax

- 12 - 12

Estimate : Accident Repairs
Workshop : Ubi Road 1

Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/0629/2018/GW

Date : 28-May-18

Vehicle not IN workshop. Kindly assist to arrange for survey.

#### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Andre Moses Tan Chang Ann

Address : Blk 476 Tampines Street 44

#03-175

Singapore 520476

Telephone : HP +65 96330418

Type of Claim : Own Damage Claims

Policy No.

Vehicle No : SJX 4211 L

Model Code : Audi A5 SB 2.0 TFSI Qu

Model / Year : Nov-11 Engine No : CDN 228828

Chassis No : WAUZZZ8T4BA108180

Mileage :

Date In :

Liability : Excess Cost :

Estimated By : Johnny Boo / Allan Wu

Accident Date : 27-May-18

Place of Accident : Four East Shopping Centre Car Park

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

### Estimated Labour Charges for Accident Vehicle SJX 4211 L.

S/N	Nature of Jobs		Estimated Charges
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00
2	To renew rhs 1/4 glass to facillitate fender renewal.	S/N	\$ 300.00 ×
3	To remove and transfer rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 280.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00 ×
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, set belts. Dislodge roof lner and disengage curtain airbag etc.	S/N	\$ 1,400.00 7 500. 700
	SUB-TOTAL LABOUR CHARGES	:	\$ 3,660.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

### Estimated Labour Charges for Accident Vehicle SJX 4211 L.

			Estimated	
S/N	Nature of Jobs		Charges	
6	To dismantle rhs rear door and rear bumper. Cut out and weld rhs rear fender. Renew rhs rear door and rear bumper. Reinstall all parts removed.		\$ 4,800.00	2500 2500
7	To respray rhs rear door, door handle, rhs rear fender. Rhs sill panel, door entrance, drain panel, roof channel, end panelling and rear bumper. To carry out stone chip treatment and joint sealer works .		\$ 5,000.00	2200. #50 2250
8	To renew rhs rear rim and try. Carry out wheel alignment.	S/N	\$ 280.00	1
9	To carry out diagnostic check.	S/N	\$ 192.00	//
	TOTAL LABOUR CHARGES	:	\$ 13,932.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

### Material List for Accident Vehicle Regn No. SJX 4211 L.

				Damage Par	ts & Prices
S/N	Parts Description			S/NETT	REMARKS
	- La con ou on kd		s	2 619 00 .	209520
1	REAR DOOR-RH Dested		s	192.00	
2	REAR OUTER DOOR SEAL-RH			144.00	
3	REAR DOOR CATCH-RH NEW .		\$		
4	KEAR DOOK CATCH KIT		\$	105.00×	7
5	REAR DOOR HANDLE-RH		\$	131.00 &	(×
6	REAR WINDOW REGULATOR WITHOUT MOTOR-RH	(#I_	\$	323.00 🗶	x Perlin Eplocene
7	REAR SIDE PANEL-RH		\$	2,341.00	X
8	SIDE WINDOW-RH		\$	517.00	×
9	PRIMER		\$	19.00	
10	REAR BUMPER		\$	1,602.00	4
11	REAR BUMPER GUIDE SECTION-RH 7	2	\$	46.00	
12	REAR BUMPER UPPER GUIDE SECTION-RH		\$	16.00 +	
13	REAR WHEEL HOUSING LINER-RH		\$	231.00	
14	WHEEL HOUSING LINER ATTACHEMENT PART		\$	38.00	
15	REAR ALUMINIUM RIM-RH		\$	1,139.00	- 911 20
16	1/4 GLASS SEALANT 7	S/N	\$	100.00 /	
17	to the area than an area and a country to the country of the count	S/N	\$	180.00	
18		S/N	\$	140.00	140
19	, —	S/N	\$	180.00	- 180
20		S/N	\$	280.00	(280
21	SUNDRIES HELE		\$	200.00 /	
	TOTAL SPARE PARTS	:	\$	10,543.00	
	TOTAL LABOUR CHARGES	:	\$	13,932.00	
	GRAND TOTAL	:	\$	24,475.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

**Authorised Date** 

**Excess Cost** 

Liability Remarks : More Andhorsed, 08 Days.

LKK Auto Consultants hence notify

. Third party survey is on a "Without Prejudice" basis

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

the Repairer of the following:

No illegal modification(s) is allowed

Acknowledged by Repairer

Signature:

Date:

. To resurvey before/after spray painting . To display damaged part(s) during resurvey · Parts prices are subject to confirmation

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### Telefax

Estimate

Accident Repairs

Workshop

Ubi Road 1

Contact No

6366 2323 : 6841 1183

Fax No Reference

: PA/OD/0629/2018/GW

Date

28-May-18

Vehicle not IN workshop. Kindly assist to arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Hi Adrian 5 days of repairs - ok - jb - 23 jul 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Mr. Andre Moses Tan Chang Ann

Address

Blk 476 Tampines Street 44

#03-175

Singapore 520476

Telephone

HP +65 96330418

Type of Claim

Own Damage Claims

Policy No.

Vehicle No

SJX 4211 L

Model Code

Audi A5 SB 2.0 TFSI Qu

Model / Year

Nov-11

Engine No

CDN 228828

Chassis No

WAUZZZ8T4BA108180

Mileage

Date In

Liability

**Excess Cost** 

Johnny Boo / Allan Wu

Estimated By Accident Date

27-May-18

Place of Accident

Four East Shopping Centre Car Park

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

### Estimated Labour Charges for Accident Vehicle SJX 4211 L.

S/N	Nature of Jobs		Estimated Charges	_	
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00	s	280.00
2	To renew rhs 1/4 glass to facillitate fender renewal.	S/N	\$ 300.00		
3	To remove and transfer rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 280.00	\$	280.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00		
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, set belts. Dislodge roof lner and disengage curtain airbag etc.	S/N	\$ 1,400.00	\$	700.00
	SUB-TOTAL LABOUR CHARGES		\$ 3,660.00	\$	1,260.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

### Estimated Labour Charges for Accident Vehicle SJX 4211 L.

			Estimated
S/N	Nature of Jobs		Charges
	c/f		
6	To dismantle rhs rear door and rear bumper. Cut out and weld rhs rear fender. Renew rhs rear door and rear bumper. Reinstall all parts removed.		\$ 4,800.00
7	To respray rhs rear door, door handle, rhs rear fender. Rhs sill panel, door entrance, drain panel, roof channel, end panelling and rear bumper. To carry out stone chip treatment and joint sealer works.		\$ 5,000.00
8	To renew rhs rear rim and try. Carry out wheel alignment.	S/N	\$ 280.00
9	To carry out diagnostic check.	S/N	\$ 192.00
	TOTAL LABOUR CHARGES	:	\$ 13,932.00

\$ 1,260.00

\$ 2,500.00

\$ 2,250.00

\$ 280.00

\$ 192.00

\$ 6,482.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

### Material List for Accident Vehicle Regn No. SJX 4211 L.

				Damage Pa	rts i	The state of the s
S/N	Parts Description			S/NETT		REMARKS
1	REAR DOOR-RH		\$	2,619.00	\$	2,095.20
2	REAR OUTER DOOR SEAL-RH		\$	192.00	\$	153.20
3	REAR DOOR ATTACHMENT PARTS	2	\$	144.00		
4	REAR DOOR CATCH-RH		\$	105.00		
5	REAR DOOR HANDLE-RH		\$	131.00		
6	REAR WINDOW REGULATOR WITHOUT MOTOR-RH		\$	323.00		
7	REAR SIDE PANEL-RH		\$	2,341.00		
8	SIDE WINDOW-RH		\$	517.00		
9	PRIMER		\$	19.00		
10	REAR BUMPER		\$	1,602.00		
11	REAR BUMPER GUIDE SECTION-RH	2	\$	46.00		
12	REAR BUMPER UPPER GUIDE SECTION-RH		\$	16.00		
13	REAR WHEEL HOUSING LINER-RH		\$	231.00		
14	WHEEL HOUSING LINER ATTACHEMENT PART		\$	38.00		
15	REAR ALUMINIUM RIM-RH		\$	1,139.00	\$	911.20
16	1/4 GLASS SEALANT	S/N	s	100.00		
17	ACRYLIC SEALANT	S/N	\$	180.00		
18	CAVITY WAX	S/N	\$	140.00	\$	140.00
19	STONE CHIP GUARD	S/N	\$	180.00	\$	180.00
20	METAL FILLER POWDER	S/N	\$	280.00	\$	280.00
21	SUNDRIES		\$	200.00		
	TOTAL SPARE PARTS	1	\$	10,543.00	\$	3,759.60
	TOTAL LABOUR CHARGES	:	\$	13,932.00	\$	6,482.00
	GRAND TOTAL	10	\$	24,475.00	\$	10,241.60

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

Name

.

Surveyed Date

:

**Authorised Date** 

.

**Excess Cost** 

958

Liability Remarks

.

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SJX 4211 L Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg

Body & Paint Dept PA/OD/0629/2018/NK

16 Sept 2018

from

Telephone +65-Telefax +65-

**EMail** 

Date

Our department

Our Ref Your Ref

Dept 2010

total pages

Dear Sir.

RE: INSURANCE CLAIM FOR SJX 4211 L, Audi A5 SB 2.0 TFSI.

With reference to the above-mentioned vehicle, no. SJX 4211 L, claimant, Mr. Andre Moses Tan Chang Ann, please find the related document per attached.

- A copy of the Original invoice no. 85012902- S\$9,460.51.
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls

AIG - SJX 4211 L

Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699

Telefax (65) 6471 3733

Telephone (65) 6336 2323 Telefax (65) 684 11183

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Subm	itted	Adj Assigned	Ad1 F	Rpt	Adj Submitted	Ins Auth'ed	Status		
Main	02 Jun 2018			01 Jun 2018 17:20 Edit Adj Rpt	S\$10,2 Edit Esti	N 69 4 5 5 7 1 1 1	S\$10,241.60 View Rpt		Pending for Sur Report Cancel Case		
-	Main		Refe	rence	ľ	Claim De	tails	Documents		Show All	
	UBFOLDER DE		ANDRE	MOSES TAN CH	IANG ANN,	ID: 578	31093F, Tel: +65	[Create	ed by insurer	]	
Insured: Vehicle Reg. No.:			SJX4211L Date of Loss:			Date of Loss:			018 14:00 - :5 hths and <b>27</b> Da e (Man Yr)]		
Claim Tys	oe:		OD / 00	51510628850	G Policy/Cover Note No.:			210031	2100316652 (Comprehensive)		
					Execus;			and the second s	S\$1,400.00		
Repairer:	8		Premiur	n Automobiles	Pte Ltd (U	BI) 55 U	bi Road 1, 408699	Jbi - Tel: 676898	28/9827/9911	test western	
Handling	Insurer:			a Pacific Insur na.DallvAmri@a		.td. (SG)	- Tel: 65-6419-300	0 [Handled by	Dally Amri, M	imi Zarina	
Adjuster:				o Consultants Advice due 1			6256-3561 [Han				
Driver/Cu	ustodian:		ANDRE N	MOSES TAN CHA	NG ANN (39	) / Male),	NRIC: S7831093	F, Tel: +65963	30418		
ASSOCI	ATED MAIL RE	CEIVED						View All	Compose	Case Mail	
AIG_S     AIG_S	G (05/06/2018): G (04/06/2018):	Alert - Ad SJX4211L	j Manda / OD /	te Approved ( 27/05/2018	S\$12847.0 / Coverage	0) - SJX & Exces	4211L - Claim Har s update	ndler: Dally Amr	l		
ALL AS	SOCIATED TAS	KS				Vi	ew All Search To	asks Create	New Task	Complete	
Due D		Туре	Task Gr	oup Subje	ct Hand	ler A	ssigned By C	Completed On	Created Or	Done?	

#### Claim Documents

\*SJX4211L (0615106288SG) OD May 27 2018 2:00PM [ANDRE MOSES TAN CHANG ANN]
Premium Automobiles Pte Ltd

-	Jpload Documents	Upload Photos Compose New Letter Upload Video Upload Audio	,	Use Viewer	-
Pho	tos/Images		3 per		V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	_	Thumbnail	
1	05/06/18 13:41	General View	0	Load JPG	V
2	05/06/18 13:41	General View	0	Load JPG	V
3	05/06/18 13:41	General View	0	Load JPG	V
4	05/06/18 13:41	General View	0	Load JPG	V
5	05/06/18 13:41	General View	0	Load JPG	V
6	05/06/18 13:41	General View	0	Load JPG	V
7	05/06/18 13:41	General View	0	Load JPG	V
8	05/06/18 13:41	General View	0	Load JPG	V
9	05/06/18 13:41	General View	0	Load JPG	V
10	05/06/18 13:41	General View	0	Load JPG	V
11	05/06/18 13:41	General View	0	Load JPG	7
12	05/06/18 13:41	General View	0	Load JPG	7
13	05/06/18 13:41	General View	0	Load JPG	1
14	05/06/18 13:41	General View	0	Load JPG	V
15	05/06/18 13:41	General View	0	Load JPG	V
16	05/06/18 13:41	General View	0	Load JPG	
17	05/06/18 13:41	General View	0	Load JPG	V
18	05/06/18 13:41	General View	0	Load JPG	V
Doc	umentation		1 per	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/06/18 14:46	Certificate of Insurance	0	Load PDF	
2	04/06/18 14:46	estimate	0	Load PDF	
3	04/06/18 14:46	Singapore Accident Statement	0	Load PDF	
4	04/06/18 14:46	Driver's Driving License and NIRC	0	Load PDF	
5	28/09/18 08:49	WORKSHOP INVOICE	0	Load PDF	
6	28/09/18 08:49	DISCHARGE VOUCHER	0	Load PDF	

#### **Linked Accident Report Documents**

			View	Use Viewer	•
Ass	essment Reports		1 per p	age 🕶	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	The second second	Thumbnail	Print
1	28/05/18 17:34	Accident Statement	0	Load HTM	
Pho	tos/Images		3 per p	age 🕶	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/05/18 17:29	Accident Photo	Ð	Load JPG	V
2	28/05/18 17:29	Accident Photo	0	Load JPG	V
3	28/05/18 17:29	Accident Photo	0	Load JPG	V
4	28/05/18 17:29	Accident Photo	0	Load JPG	V
5	28/05/18 17:29	Accident Photo	0	Load JPG	7
6	28/05/18 17:29	Accident Photo	0	Load JPG	V
7	28/05/18 17:29	Accident Photo	0	Load JPG	7
8	28/05/18 17:29	Accident Photo	0	Load JPG	V
9	28/05/18 17:29	Accident Photo	0	Load JPG	7

10	28/05/18 17:29	Accident Photo	0	Load JPG	V
Doc	umentation		1 per p	nage 🕶	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/05/18 17:24	Sketch Plan	Ð	Load JPG	V
2	28/05/18 17:24	Sketch Plan #2	0	Load JPG	<b>V</b>

### **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.	

CC3/AIG18009970/ATBN2

CDN228828

99020 km

WAUZZZ8T4BA108180

Yes

28/09/2018

Our File No:

Engine No:

Chassis No:

Odometer:

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #07-16

Date: Singapore 079120

REFERENCE

2100316652 ANDRE MOSES TAN CHANG ANN Policy No: Insured/Claimant:

Claim No: 0615106288SG Nature of Claim: OD 27/05/2018 Date of Loss:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SJX4211L

Make & Model:

AUDI A5, 2.0 SPORTBACK QUATTRO (A)

30/11/2011 (Man. Year: 2011)

Reg. Date: Grey

Colour: Engine Capacity:

1984 cc

Market Value/New Car Price:

S\$70,000.00

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): General Condition:

Yes Footbrake (Serviceable):

Pre-accident Condition: Yes Engine Modification: Handbrake (Serviceable):

CONDITION OF TYRES

245/40R18 245/40R18 Rear Tyre Size: Front Tyre Size: Pirelli 6 mm Rear Left Side: Front Left Side: Pirelli 6 mm Pirelli 6 mm Rear Right Side: Front Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 10,543.00 0.00	Adjuster's 3,759.60 0.00	6,783.40 0.00	Diff % 64.34
Labour Paintwork Labour	13,932.00 0.00	6,482.00 0.00	7,450.00 0.00	53.47
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,475.00	10,241.60	14,233.40	58.15
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	23,075.00	8,841.60	14,233.40	61.68
+ GST 7.00/7.00% (S\$)	1,615.25	618.91	996.34	61.68
Nett Amount (S\$)	24.690.25	9,460.51	15,229.74	61.68

INSPECTION

Date of Assignment:

01/06/2018

Date Inspected:

01/06/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

5.0 days

Manager: DENISE TAY KWEE CHENG Adjuster: ADRIAN LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Re	com	mended Parts	
No.	Otv	Part No. Particulars	

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1 2	1	*REAR DOOR-RH *REAR OUTER DOOR SEAL-RH	Dented Necessary		*2,095.20 FS *153.20 FS
3	2	*REAR DOOR ATTACHMENT PARTS *REAR DOOR CATCH-RH	Not Necessary Not Necessary		*-FS
5	1	*REAR DOOR HANDLE-RH *REAR WINDOW REGULATOR WITHOUT MOTOR-RH	Not Necessary Not Necessary		*-FS
7	1	*REAR SIDE PANEL-RH *SIDE WINDOW-RH	Repair Not Necessary	2,341.00 FS	
9	1	*PRIMER *REAR BUMPER	Not Necessary Repair	19.00 FS 1,602.00 FS	
11	2	*REAR BUMPER GUIDE SECTION-RH *REAR BUMPER UPPER GUIDE SECTION-RH	Not Necessary Not Necessary		
13	1	*REAR WHEEL HOUSING LINER-RH *WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary Not Necessary		
15 16	1	*REAR ALUMINIUM RIM-RH *1/4 GLASS SEALANT	Cut Not Necessary	1,139.00 FS 100.00 FS	
17 18	1	*ACRYLIC SEALANT *CAVITY WAX	Not Necessary Necessary	180.00 FS 140.00 FS	
19	1	*STONE CHIP GUARD *METAL FILLER POWDER	Necessary Necessary	180.00 FS 280.00 FS	
21	1 anchise	*SUNDRIES part. S=SpcNett.	Not Necessary	200.00 FS	*-FS
e.co403		**************************************	Total Parts (S\$	10,543.00	3,759.60

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items There are no new miscellaneous items selected.

No	commended Labour	Lab.Type	Repairer's	Amount
NO	raticulais		3.5-0.5 M WHA WY SOUNS AND	
Labo	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO RENEW RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	-
3	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	280.00	280.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	K*
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SET BELTS. DISLODGE ROOF LNER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	700.00
6	TO DISMANTLE RHS REAR DOOR AND REAR BUMPER.CUT OUT AND WELD RHS REAR FENDER.RENEW RHS REAR DOOR AND REAR BUMPER.REINSTALL ALL PARTS REMOVED	New	4,800.00	2,500.00
7	TO RESPRAY RHS REAR DOOR, DOOR HANDLE, RHS REAR FENDER. RHS SILL PANEL, DOOR ENTRANCE, DRAIN PANEL, ROOF CHANNEL, END PANELLING AND REAR BUMPER. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	5,000.00	2,250.00
8	TO RENEW RHS REAR RIM AND TRY.CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		13,932.00	6,482.00
	Report was unsubmitted during			

< END OF ESTIMATES >