

INS. CASE OWNER:

CC6, QBE 180/5009, Awa3g

LKK:

IDAC:

Surveyor:

ADRIAN

DOI:

ASSIGNMENT

31/5/2018

Date / Time:

31/5/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFW 7881K

Name of Insured:

Chirav Loi Thi Giang

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

23/05/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Lim Kim Hwee

Driver Tel No.:

9090991 (V/L: YES / NO)

Claim No.:

VCO1525

Ex.

Policy No.:

Q-VCO18057-mv-a-2001

Make / Model:

Perodi A3

Place of Accident:

Tegore Lane

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

my solution



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

6/6/2018

2/6/18

31/7/18

SFW 7881K } NO/INCL 9376/24 ; WA: 23/5/18

email to QBE to seek advice

Email from QBE reject TP claim

Reject claim based on TP coming out from minor Rd.

Email to Workshop reject claim.

Reject Case

By (Staff): V-Juan

Approved by: V-Juan

Date: 01-5-18

RECEIVED 03 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher

Final Repair Bill

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

W/P

3) Survey fee:

\$300.00

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFW900K Yr Regn: 2011, MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 320i c.c. 1995Colour: Black A/C: Insured / Std / NI/NASp. Reading: 101365 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NBARD52060E482248.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA (MIC) / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 3/05/18Survey held at MG SolutionDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP QBE</u>
<u>31/7/18</u>	<u>Confirm US \$ 3500.00 with 2 working days</u>

(red) = \$6325.90
b31.)

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD			Ref : CC6/QBE18010009/Awa3	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Date : 03-06-2018	
			Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFW 7881K	Veh. Inspected	SFW 900K	
Policy No.	8-V0015077-MVA-R001	Coverage (\$)	0.00	
Claim No.	VC011525	Excess (\$)	0.00	
Assign From		Assign Date	03/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/05/2018	Inspection Date	31/05/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: QBE INSURANCE INTERNATIONAL LTD	DATE	: 30-May-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:	WBAKDS2060E491248	
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SFW 900 K	Vivian	
MODEL	: BMW 320I		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 23-May-18
		TIME	: 1040HRS
THIRD PARTY REQUESTOR / CONTACT		:	DEON

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Del'd</i>	1	\$ 1,655.00	\$ 1,655.00
2	FRONT BUMPER SPONGE <i>Cont'd</i>	1	\$ 233.00	\$ 233.00
3	FRONT BUMPER SIDE RETAINER <i>re</i>	2	\$ 89.00	\$ 178.00
4	FRONT BUMPER TOWING COVER <i>Del'd</i>	1	\$ 80.00	\$ 80.00
5	FRONT BUMPER LOWER GRILLE <i>Rit cont'd</i>	2	\$ 98.00	\$ 196.00
6	FRONT BUMPER LOWER GRILLE OUTER GARNISH <i>Rit cut</i>	2	\$ 82.00	\$ 164.00
7	FRONT BUMPER LOWER GRILLE (CENTER) <i>re</i>	1	\$ 190.00	\$ 190.00
8	FRONT BUMPER FOGLAMP RH <i>re</i>	1	\$ 355.00	\$ 355.00
9	FRONT BUMPER UNDER COVER <i>re</i>	1	\$ 190.20	\$ 190.20
10	FRONT HEADLAMP RH (HID) <i>cut</i>	1	\$ 3,800.00	\$ 3,800.00
11	FRONT HEADLAMP LOWER GARNISH <i>cut</i>	1	\$ 263.00	\$ 263.00
12	FRONT HEADLAMP NOZZLE <i>3x1</i>	2	\$ 243.00	\$ 486.00
13	FRONT HEADLAMP NOZZLE COVER <i>re</i>	2	\$ 96.00	\$ 192.00

4018

381710

TOTAL PRICE	\$	7,982.20
LESS 5%	\$	24.30
SUB TOTAL PRICE	\$	7,957.90

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE Bent	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP(SET) m	1	\$ 22.00	\$ 22.00
3	CENTER GRILLE per	2	\$ 280.00	\$ 280.00

52

TOTAL \$ 352.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 800.00	250	
2	TO SPRAY PAINT AFFECTED AREA	\$ 600.00	250	
3	TUFF COAT	\$ 50.00	X	
4	WIRING CHECK	\$ 30.00	✓	
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 100.00	X	

530

TOTAL \$1,580.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,309.90
TOTAL LABOUR COST : \$ 1,580.00
TOTAL REPAIR COST : \$ 9,889.90

APPROVED DETAILS

SURVEYOR :
CONTACT NO :

FAX

PART BY PART / LUMP SUM :
NO OF DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Adrian Lim
L/s 31/05/18

03 Days
Total: 4399.10
L/s: B.51C

Mei Kwan (LKKAuto)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Tuesday, 5 June, 2018 9:39 AM
To: Mei Kwan (LKKAuto); claims-singapore@qbe.com
Cc: Vivian Lau (LKKAuto); Thin Thin (LKKAuto); Admin A
Subject: FW: Direct Settlement - Accident Involving SFW7881K (OI : QBE - TBA) AND SFW900K (TP : LKK REF - CC6/QBE18010009/Awa3) on 23/05/2018 [VC011525]
Attachments: TP GIA REPORT.PDF; SFW7881K.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Our Ref. VC011525

Hi

Attached GIA report for your attention.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65-6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Monday, 4 June, 2018 6:23 PM
To: Joyce Foo <joyce.foo@qbe.com>
Cc: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SFW7881K (OI : QBE - TBA) AND SFW900K (TP : LKK REF - CC6/QBE18010009/Awa3) on 23/05/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SFW 900K at M/s MG Solution Pte Ltd - Kaki Bukit.

Enclosed here with a copy of TP's GIA report for your perusal.

Please be informed that the estimated cost of repair and preliminary advice is not ready yet.

We will revert to you on preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Tuesday, 31 July, 2018 6:00 PM
To: Sharon
Cc: Thin Thin (LKKAuto)
Subject: Your Ref: SFW 900K, Our Ref: CC6/QBE1801009/Awa3, Accident involving Vehicle SFW 900K & SFW 7881K ON 23/05/2018
Attachments: Sketch Plan .pdf

WITHOUT PREJUDICE

Your Ref: SFW 900K
Our Ref: CC6/QBE1801009/Awa3

Dear Sir/Madam,

Accident involving Vehicle SFW 900K & SFW 7881K ON 23/05/2018

We refer to the above matter

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client.. your client turning from major road into minor road has precedence over vehicle turning from minor road to major road. BOLA 9 (c) applies.

We attached herewith our insured's accident report for your perusal.

Under such circumstances, we have our principal's instruction to deny liability of your client's claim.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Vivian Lau (LKKAUTO)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Tuesday, 12 June, 2018 4:15 PM
To: Vivian Lau (LKKAUTO); claims-singapore@qbe.com
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving SFW7881K (OI : QBE - TBA) AND SFW900K (TP : LKK REF - CC6/QBE18010009/Awa3) on 23/05/2018 [VC011525]

Hi Vivian

Please proceed to reject as advised.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Vivian Lau (LKKAUTO) [mailto:vivianlau@lkkauto.com]
Sent: Tuesday, 12 June, 2018 3:43 PM
To: Joyce Foo <joyce.foo@qbe.com>; claims-singapore@qbe.com
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving SFW7881K (OI : QBE - TBA) AND SFW900K (TP : LKK REF - CC6/QBE18010009/Awa3) on 23/05/2018 [VC011525]

Your Ref: SFW 7881K
Our Ref: CC6/QBE1801009/Awa3

Dear Joyce

ACCIDENT INVOLVING SFW 7881K (Insured) & SFW 900K (Third Party) ON 23/05/2018 ALONG TAGORE LANE

We refer to the above matter

The third party reported that he was exiting out from the junction, checked both side traffic was clear. TP process to make a right turn, OI cut across Tagore Lane.

Insured reported that he was travelling alone Tagore lane turning right into Tagore Industrial Ave. TP collided OI 's rear portion.

Based on the circumstances of both parties and available information in hand. We are in the opinion that Vehicle turning from major road into minor road has precedence over vehicle turning from minor road to major road. BOLA 9 (c) applies.

As such, we intend to reject the claim.

Kindly advice on your view/opinion/instruction for this claim.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo [mailto:joyce.foo@qbe.com]

Sent: Tuesday, 5 June, 2018 9:39 AM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; claims-singapore@qbe.com

Cc: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: FW: Direct Settlement - Accident Involving SFW7881K (OI : QBE - TBA) AND SFW900K (TP : LKK REF - CC6/QBE18010009/Awa3) on 23/05/2018 [VC011525]

Our Ref. VC011525


Hi

Attached GIA report for your attention.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Monday, 4 June, 2018 6:23 PM

To: Joyce Foo <joyce.foo@qbe.com>

Cc: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving SFW7881K (OI : QBE - TBA) AND SFW900K (TP : LKK REF - CC6/QBE18010009/Awa3) on 23/05/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SFW 900K at M/s MG Solution Pte Ltd - Kaki Bukit.

Enclosed here with a copy of TP's GIA report for your perusal.

Please be informed that the estimated cost of repair and preliminary advice is not ready yet.

We will revert to you on preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly

inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC6/QBE18010009/Awa3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 15-08-2018



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFW 7881K	Veh. Inspected	SFW 900K
Policy No.	8-V0015077-MVA-R001	Coverage (\$)	0.00
Claim No.	VC011525	Excess (\$)	0.00
Assign From		Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 320i	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAKD52060E492248	Colour	BLACK
Odometer	101365	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	MICHELIN	6 mm
L/H Front Tyre	225/40 R18	MICHELIN	6 mm
R/H Rear Tyre	225/40 R18	MICHELIN	6 mm
L/H Rear Tyre	225/40 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/05/2018	Inspection Date	31/05/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFW 900K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	1,655.00	1,012.00
1	FRONT BUMPER SPONGE	CRACKED	233.00	233.00
2	FRONT BUMPER SIDE RETAINER @\$89.00	NECESSARY	178.00	178.00
1	FRONT BUMPER TOWING COVER	DEFORMED	80.00	80.00
2	FRONT BUMPER LOWER GRILLE @\$98.00	O/S CRACKED	196.00	98.00
2	FRONT BUMPER LOWER GRILLE OUTER GARNISH @\$82.00	O/S CUT	164.00	82.00
1	FRONT BUMPER LOWER GRILLE (CENTER)	NOT NECESSARY	190.00	-
1	FRONT BUMPER FOGLAMP RH	NOT NECESSARY	355.00	-
1	FRONT BUMPER UNDER COVER	NOT NECESSARY	190.20	-
1	FRONT HEADLAMP RH (HID)	CUT	3,800.00	2,072.00
1	FRONT HEADLAMP LOWER GARNISH	CRACKED	263.00	263.00
2	FRONT HEADLAMP NOZZLE @\$243.00	NOT NECESSARY	486.00	-
2	FRONT HEADLAMP NOZZLE COVER @\$96.00	NOT NECESSARY	192.00	-
	LESS 5% DISCOUNT		-399.11	-200.90
			7,583.09	3,817.10
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	BENT	50.00	30.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	22.00	22.00
2	CENTER GRILLE (SN)	NECESSARY	280.00	-
			352.00	52.00
LABOUR				
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.		800.00	250.00
	TO SPRAY PAINT AFFECTED AREA.		600.00	250.00
	TUFF COAT.	NOT NECESSARY	50.00	-
	WIRING CHECK .		30.00	30.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	100.00	-
			1,580.00	530.00



GRAND TOTAL		9,515.09	4,399.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00

Report Ref No. CC6/QBE18010009/Awa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.