

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

To Survey by LKK

VEHICLE NO : SHA 4613E

DATE : 31.05.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

India

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover <i>distorted</i>			\$ 538.80	✓
	Front Bumper Sponge <i>NH</i>			\$ 136.30	x
	Front Bumper Reinforcement <i>NH</i>			\$ 504.10	x
	Front Bumper Bracket Top (RH) <i>NH</i>			\$ 22.40	x
	Front Bumper Protector (RH) <i>cut</i>			\$ 29.20	✓
	Front Bumper Bracket (RH) <i>NH</i>			\$ 20.10	x
	Front Bumper Side Bracket <i>NH</i>			\$ 14.30	x
	Headlamp Support Panel Assy <i>broken</i>			\$ 1,023.00	✓
	Headlamp (RH) <i>scratched</i>			\$ 797.90	✓
	Front Fender (RH) <i>distorted</i>			\$ 593.00	✓
	Front Fender Shield (RH) <i>NH</i>			\$ 86.00	x
	Wiper Container <i>NH</i>			\$ 59.00	x
	Wiper Container Motor <i>NH</i>			\$ 63.00	x
	Front Wheel Rim (RH) <i>2 BT</i>			\$ 284.70	✓
	Front Wheel Hub Cap (RH) <i>cut</i>			\$ 145.00	✓
	Front Wheel Bearing <i>2 Dam</i>			\$ 258.50	✓
	Front Shock Absorber (Assy) (RH) <i>2 distorted</i>			\$ 203.70	✓
	Front Shock Absorber Mounting (RH) <i>NH NH</i>			\$ 72.00	x
	Front Shock Absorber Fork (RH) <i>NH 2 distorted</i>			\$ 203.30	✓
	Front Suspension Upper Arm (RH) <i>NH 2 distorted</i>			\$ 240.00	✓
	STG Tie End <i>2 distorted</i>			\$ 66.50	✓
	Front Suspension Lower Arm (RH) <i>2 distorted</i>			\$ 685.20	✓
	Knuckle Arm (RH) <i>2 distorted</i>			\$ 558.60	✓
	SUB TOTAL			\$ 6,604.60	
	LESS 20%			\$ 1,320.92	
	DISCOUNTED TOTAL			\$ 5,283.68	
	Front Fender Advertisement Logo (RH) <i>cut</i>			\$ 100.00	Nett ✓
	Front Tyre (RH) <i>svc</i>			\$ 207.00	Nett x
				\$ 307.00	
	Labour Charge <i>05/06/18 @ 1100m</i>				
	Panel Beating <i>NH Antenna</i>			\$ 800.00	500/-
	Spray Painting Charge <i>4/5mm</i>			\$ 500.00	400/-
	Wiring Charge <i>7</i>			\$ 50.00	30/-
	Tuff Kote <i>2 days</i>			\$ 50.00	20/-
	Towing Charge <i>NH</i>			\$ 50.00	NH
	Remove/Refix Undercarriage (FRT) <i>LKK Ant</i>			\$ 180.00	150/-
	FRT Wheel Alignment <i>8</i>			\$ 100.00	60/-
	TOTAL LABOUR			\$ 1,730.00	
	ESTIMATE TOTAL			\$ 7,113.68	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a person of your appointment by the insurance company.					