

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

31-May-18

Our ref : TP/4517/18

Sun Kee (Pte) Ltd

TP A16.
Xiao Tony

RE : estimate cost for vehicle no : GBF 5020D

1 pc	rear bumper	old	\$	612.20	✓	682.6
1 pc	rear bumper rh retainer	new		70.40	✓	614.34
1 pc	rear rh fender	Repis		1760.00	✓	
				2442.60		
			less 10%	732.78		
				1,709.82		
1 pc	rh taillamp	old		255.60	nett ✓	255.60
			less 10%	25.56		230.04
				230.04		
1 pc	rear rh tyre	new		300.00	snett ✓	
1 pc	rear rh rim	new		300.00	+	
1 pc	rear rh hup cap	old		150.00	80	
				600.00	400	
				500.00	300	890
				30.00	✓	
				80.00	✓	
				3,899.86		
			Plus 7% GST	272.99		
				4,172.85		

SD : Four thousand one hundred seventy-two & cents eighty-five only.

Adrian Limy. total: 1734.38
P/P 01/06/18. (P/P)
03 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: