



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 19/11/2019

Survey Details:

Date of loss	1-Jun-18
Date of appointment	5-Jun-18
Date of survey	5-Jun-18
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 5673P
Make and Model	RENAULT LATITUDE 2.0L DCI AUTO
Date of registration	4-Nov-14
Excess	
Market Value (est)	\$0.00
Parf Rebate (est)	\$0.00
Nett Loss (est)	\$0.00

Repair details:

Initial Estimate	\$ 27,268.04
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 4,957.16
Check items (estimate)	\$ -
Labour	\$ 1,460.00
Total	\$ 6,417.16
Lump Sum(if applicable)	\$ 5,150.00

Number of days for repair	<u>4 DAYS</u>
---------------------------	---------------



Remarks:

We have not authorized repairs. It was reported that Insured vehicle swerved lane when collided to the TP taxi that was travelling along the right most lane. A letter was sent out to the Insured to notify TP claim and NCD issues. Furthermore, TP repairer had provided a copy of the video footage from the building that captures the entire incident (footage uploaded in SC with accident location from google map). Based on footage, TP taxi was travelling along the right most lane and likely, the Insured vehicle swerved

Mandate:

Liability(TP)		100%
Proposed Repair Cost	\$	5,510.50 w/gst
Loss of Use	\$	- no. of days
Loss of Rental	\$	710.22 \$101.46 x 7 days
Loss of Income	\$	350.00 \$50 x 7 days
GIA Search Fees	\$	7.49
Others (Medical Bills)	\$	-
Proposed Total	\$	6,578.21
***TBC - To Be Confirmed		