

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA INSURANCE SINGAPORE PTE LTD	DATE	: 4-Jun-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SLD 2121 H		
MODEL	: TOYOTA COROLLA ALTIS 1.6		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 3-Jun-18
		TIME	: 1540HRS
THIRD PARTY REQUESTOR / CONTACT	:	DEON	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT LH DOOR <i>dent</i>	1	\$ 1,322.30	\$ 1,322.30
2	REAR LH DOOR <i>Repair</i>	1	\$ 1,280.00	\$ 1,280.00
3	FRONT BUMPER <i>dent</i>	1	\$ 594.00	\$ 594.00
4	FRONT BUMPER SIDE RETAINER <i>m</i>	1	\$ 55.00	\$ 55.00
5	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 365.00	\$ 365.00
6	FRONT BUMPER REINFORCEMENT SPONGE <i>new</i>	1	\$ 180.00	\$ 180.00
7	FRONT BUMPER FOGLAMP GARNISH <i>new</i>	1	\$ 160.20	\$ 160.20
8	FRONT BUMPER FOGLAMP <i>new</i>	1	\$ 380.00	\$ 380.00
9	FRONT HEADLAMP <i>cut</i>	1	\$ 1,922.00	\$ 1,922.00
10	FRONT HEADLAMP LOWER BRACKET <i>new</i>	1	\$ 52.00	\$ 52.00
11	FRONT FENDER <i>Distorted</i>	1	\$ 688.90	\$ 688.90
12	FRONT FENDER EMBLEM "VVT-I" <i>new</i>	1	\$ 63.20	\$ 63.20
13	FRONT WHEEL HOUSE PANEL <i>Repair</i>	1	\$ 523.10	\$ 523.10
14	FRONT FENDER INNER COWLING <i>dent</i>	1	\$ 230.00	\$ 230.00
15	FRONT LH LOWER ARM <i>2</i>	1	\$ 354.10	\$ 354.10
16	FRONT LH STABILIZING LINK <i>new</i>	1	\$ 235.10	\$ 235.10
17	FRONT KNUCKLE ARM LH <i>dent</i>	1	\$ 232.10	\$ 232.10
18	FRONT KNUCKLE ARM BEARING LH <i>new</i>	1	\$ 187.20	\$ 187.20
19	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 326.50	\$ 326.50

5294.70
3971.02

TOTAL PRICE \$ 9,150.70
LESS 25% \$ 2,287.68
SUB TOTAL PRICE \$ 6,863.03

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS (SET) <i>Am</i>	1	\$ 20.00	\$ 20.00
2	HEADLAMP CLIPS <i>Am</i>	1	\$ 20.00	\$ 20.00
3	FRONT FENDER COWLING CLIPS <i>m</i>	1	\$ 20.00	\$ 20.00
4	FRONT WHEEL RIM LH <i>at</i>	1	\$ 780.00	\$ 780.00
5	FRONT WHEEL TYRE LH <i>Ne Am</i>	1	\$ 280.00	\$ 280.00

TOTAL \$ 1,120.00

510

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	<i>500</i>
2	TO REMOVE AND REFIX FRONT AND REAR LH DOOR <i>ittings</i>	\$ 800.00	<i>80</i>
3	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>80</i>
4	TUFF COAT	\$ 250.00	<i>+</i>
5	WIRING CHECK	\$ 250.00	<i>30</i>
6	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>x</i>
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 350.00	<i>100</i>
8	FOUR WHEEL ALIGNMNET	\$ 120.00	<i>80</i>

TOTAL

\$4,230.00

1590

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,983.03
TOTAL LABOUR COST : \$ 4,230.00
TOTAL REPAIR COST : \$ 12,213.03

APPROVED DETAILS

SURVEYOR :
CONTACT NO :
PART BY PART / LUMP SUM :
NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6071.02

L/S: 4.8K.

05 days