

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 06 Jun 2018

Preliminary Advice

Vehicle No	: SLW479P	Accident Date	: 29/05/2018
Make	: VOLKSWAGEN SPORTSVAN	Policy No.	: A29070319AVW
Assignment Date	: 04/06/2018	Excess	: S\$500.00
Date of Inspection	: 05/06/2018	Est. Duration of Repair	: 3.00
Inspection At	: VOLKSWAGEN CENTRE SINGAPORE (HQ) 247 ALEXANDRA ROAD SINGAPORE 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,922.49
Revised Amount	:S\$	3,483.89
Check Items (Estimated)	:S\$	217.13
Total	:S\$	3,701.02

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	53,002.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,998.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.