

## Hsiao Tong (LKKAUTO)

---

**From:** Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>  
**Sent:** Tuesday, 24 July 2018 9:15 AM  
**To:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: <Seek Instruction> Your ref: 1025443037SG \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(OI) & SGK 339H(TP) ON 31/05/2018]  
**Attachments:** TP LOD.pdf

Hi Hsiao Tong,

Received TP LOD for this case. You may proceed to reject the claim once again.

Thank you.

**Best Regards,**

Bernard Ler  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946 | Fax +(65) 6835 7416

[Bernard-JQ.Ler@aig.com](mailto:Bernard-JQ.Ler@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Ler, Bernard-JQ  
**Sent:** 12 June 2018 4:21 PM  
**To:** 'Hsiao Tong (LKKAUTO)'  
**Subject:** RE: <Seek Instruction> Your ref: 1025443037SG \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(OI) & SGK 339H(TP) ON 31/05/2018]

Dear Hsiao Tong,

As per video, there is no vehicle in front of TP and hence there is no reason for the TP driver to brake and stop suddenly.

Please proceed to reject TP claim in totality.

Thank you.

**Best Regards,**

Bernard Ler  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946 | Fax +(65) 6835 7416

[Bernard-JQ.Ler@aig.com](mailto:Bernard-JQ.Ler@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**From:** Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

**Sent:** 12 June 2018 3:12 PM

**To:** Ler, Bernard-JQ

**Subject:** <Seek Instruction> Your ref: 1025443037SG \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(OI) & SGK 339H(TP) ON 31/05/2018]

Your ref: **1025443037SG**

Our Ref: CC4/AIG18010192/Apb3

Dear Sir/Madam,

**ACCIDENT INVOLVING SLL 9880L(OI) & SGK 339H(TP) ON 31/05/2018**

We refer to the above matter.

Third party reported that he was travelling along Bukit Batok West Ave 6 towards Bukit Batok Swimming complex. Suddenly the car in front of him stop and he managed to stop without hitting the front car. Suddenly he felt an big impact from the rear. He went down to check and realised that there was 2 car involved in this accident.

Ol reported that he was travelling along Bukit Batok West Ave 6 towards Bukit Timah road. While going straight, third party suddenly E-brake with no vehicle in front of him. Ol has no time to react as third party E-brake was too sudden. Thus caused the collision between both vehicles.

We have contacted Ol, Mr Wee to verify the nature of accident and inform third party claim. However Ol disputed on third party claim as third party suddenly jammed braked without any reason. Ol mentioned that third party is making a false statement. There was no car in front of him while he jammed brake. Kindly refer to the video footage submitted by Ol to support his version.

In view of this, we seek your advice/ instruction in order for us to proceed further.

Thank you.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Tuesday, 31 July 2018 10:49 AM  
**To:** 'claims@unitedsg.com.sg'  
**Subject:** RE: <REJECTION> Your Ref: SGK 339H \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(AIG) & SGK 339H ON 31/05/2018]

### Without Prejudice

Hi Sirs/ Mdm,

We refer to the above matter and your LOD dated 17 July 2018, addressed to AIG Asia Pacific Insurance Pte Ltd.

We have our principal instruction to maintain rejection on this matter.

Thank you.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Thursday, 14 June 2018 11:51 AM  
**To:** 'claims@unitedsg.com.sg' <claims@unitedsg.com.sg>  
**Subject:** RE: <REJECTION> Your Ref: SGK 339H \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(AIG) & SGK 339H ON 31/05/2018]

### Without Prejudice

Hi,

Attached is a copy of our insured video for your reference.

Please note that the video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Hsiao Tong (LKKAuto)

**Sent:** Thursday, 14 June 2018 10:21 AM

**To:** 'claims@unitedsg.com.sg' <[claims@unitedsg.com.sg](mailto:claims@unitedsg.com.sg)>

**Subject:** <REJECTION> Your Ref: SGK 339H \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(AIG) & SGK 339H ON 31/05/2018]

Your Ref: **SGK 339H**

**Without Prejudice**

Our Ref: CC4/AIG18010192/Apb3

Dear Sirs,

**ACCIDENT INVOLVING SLL 9880L(AIG) & SGK 339H ON 31/05/2018**

We refer to the above matter.

We attached here with a copy of our insured police report for your easy reference. Our insured mentioned that your driver is making a false statement, there was no car in front of him while he jammed his brake. Kindly refer to video screenshot below for your perusal.



In view of the above, we are of the view that our insured driver is not liable for the accident and we have our principal instruction to reject your client's claim.

Thank you.

• "Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Hsiao Tong (LKKAUTO)

---

**From:** Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>  
**Sent:** Thursday, 26 September 2019 3:01 PM  
**To:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: <Seek Instruction> Your ref: 1025443037SG \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(OI) & SGK 339H(TP) ON 31/05/2018]

Hi Hsiao Tong,

Please update me once this is done.

Thanks.

**Best Regards,**

Bernard Ler  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd  
  
78 Shenton Way #08-16 Singapore(079120)  
  
Tel +(65) 6419 1946  
  
[Bernard-JQ.Ler@aig.com](mailto:Bernard-JQ.Ler@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]  
**Sent:** 27 August 2019 13:53  
**To:** Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>  
**Subject:** [EXTERNAL] RE: <Seek Instruction> Your ref: 1025443037SG \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(OI) & SGK 339H(TP) ON 31/05/2018]

This message is from an external sender; be cautious with links and attachments.

Hi Bernard,

Apologised for late response.

We will close this case by this week.

Best Regards,  
**Hsiao Tong, Chew** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Ler, Bernard-JQ <[Bernard-JQ.Ler@aig.com](mailto:Bernard-JQ.Ler@aig.com)>

**Sent:** Tuesday, 27 August 2019 11:34 AM

**To:** Hsiao Tong (LKKAUTO) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Subject:** RE: <Seek Instruction> Your ref: 1025443037SG \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(OI) & SGK 339H(TP) ON 31/05/2018]

Hi Hsiao Tong,

Can assist on the below?

Thanks.

**Best Regards,**

Bernard Ler

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

[Bernard-JQ.Ler@aig.com](mailto:Bernard-JQ.Ler@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Ler, Bernard-JQ

**Sent:** 30 July 2019 11:30

**To:** 'Hsiao Tong (LKKAUTO)' <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Subject:** RE: <Seek Instruction> Your ref: 1025443037SG \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(OI) & SGK 339H(TP) ON 31/05/2018]

Hi Hsiao Tong,

Can assist to submit WP report and billing for our closure?

Thanks!

**Best Regards,**

Bernard Ler

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

[Bernard-JQ.Ler@aig.com](mailto:Bernard-JQ.Ler@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Ler, Bernard-JQ

**Sent:** 12 June 2018 16:21

**To:** 'Hsiao Tong (LKKAUTO)' <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Subject:** RE: <Seek Instruction> Your ref: 1025443037SG \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(OI) & SGK 339H(TP) ON 31/05/2018]

Dear Hsiao Tong,

As per video, there is no vehicle in front of TP and hence there is no reason for the TP driver to brake and stop suddenly.

Please proceed to reject TP claim in totality.

Thank you.

**Best Regards,**

Bernard Ler  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946 | Fax +(65) 6835 7416

[Bernard-JQ.Ler@aig.com](mailto:Bernard-JQ.Ler@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Hsiao Tong (LKKAUTO) [<mailto:chewht@lkkauto.com>]

**Sent:** 12 June 2018 3:12 PM

**To:** Ler, Bernard-JQ

**Subject:** <Seek Instruction> Your ref: 1025443037SG \*Our Ref: CC4/AIG18010192/Apb3 [ACCIDENT INVOLVING SLL 9880L(OI) & SGK 339H(TP) ON 31/05/2018]

Your ref: **1025443037SG**

Our Ref: CC4/AIG18010192/Apb3

Dear Sir/Madam,

**ACCIDENT INVOLVING SLL 9880L(OI) & SGK 339H(TP) ON 31/05/2018**

We refer to the above matter.

Third party reported that he was travelling along Bukit Batok West Ave 6 towards Bukit Batok Swimming complex. Suddenly the car in front of him stop and he managed to stop without hitting the front car. Suddenly he felt a big impact from the rear. He went down to check and realised that there was 2 car involved in this accident.

OI reported that he was travelling along Bukit Batok West Ave 6 towards Bukit Timah road. While going straight, third party suddenly E-brake with no vehicle in front of him. OI has no time to react as third party E-brake was too sudden. Thus caused the collision between both vehicles.

We have contacted OI, Mr Wee to verify the nature of accident and inform third party claim. However OI disputed on third party claim as third party suddenly jammed braked without any reason. OI mentioned that third party is making a false statement. There was no car in front of him while he jammed brake. Kindly refer to the video footage submitted by OI to support his version.

In view of this, we seek your advice/ instruction in order for us to proceed further.

Thank you.



Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# United

"We are always in your journey" ....

53 Ubi Avenue 1 #01-56 Paya Ubi Industrial Park Singapore 408934

Tel: 6747-4454 | Fax: 6747-7752 | Email: claims@unitedsg.com.sg

Register No: 201729521C | GST No: 201729521C

508767

17<sup>th</sup> July 2018

Our reference: USG-201806-02

Your reference: SLL9880L

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#08-16  
Singapore 079120  
Attn: Motor Claims Department

RECEIVED BY AIG Claims Dept	
19 JUL 2018	
CL No.	1025443037
Party	SG 003
Adl	

BY POST

Dear Sir/ Madam,

Claimant : NASENDRAN S/O VEERASAMY

Address : BLOCK 289E BUKIT BATOK STEET 25 #07-164 SINGAPORE 654289

We are instructed by the above named to claim damages against your insured/your insured's driver in connection with a road accident on 31 MAY 2018 along BUKIT BATOK WEST AVENUE 6 TOWARDS BUKIT BATOK SWIMMING COMPLEX involving our client's vehicle registration number SGK339H and vehicle registrations number SLL9880L driven by you/your insured's driver at the material time.

The accident was caused by your insured negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

Cost of Repair	:	\$8,239.00
Loss of Rental	:	\$1,800.00
LTA Search Fee	:	\$7.45
Surveyor Report Fee	:	\$449.00
Total	:	\$10,495.45

A copy of each of the following supporting documents are enclosed:-

- |   |  |
|---|--|
| a) Our client's Accident Report/Police Report | b) COE/PARF Certificates                 |
| c) Certificate Of Insurance                   | d) Owner / Driver's IC & Driving License |
| e) LTA Search                                 | f) Letter Of Authorisation               |
| g) Invoice                                    | h) Rental Agreement                      |
| i) Surveyor Report                            |  |

The demand herein is in respect of our client's claim for damages pertaining to their motor vehicle and any settlement following or subsequent of this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to personal injuries.

Please send to us an acknowledgement of receipt of this letter with 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim is quantified based on the supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Yours faithfully



United SG Automobile Pte Ltd

Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 01 Jun 2018 / 16:18:11

Receipt Date/Time : 01 Jun 2018 / 16:18:10

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-180601-001942

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SLL9880L As at 31 May 2018/20:00:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.			
1	Insurance Enquiry - SLL9880L Enquiry Fee 20180601161743391116	7.00	0.49	7.49
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
	<b>Paid By</b>			
	xxxxxxxxxxxx0343		Credit Card: Visa /MasterCard	7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Date 17 JUL 2018

Attn: Motor Claims Dept

Alh

Dear Sir/Mdm

ACCIDENT ON 31 May 2018  
INVOLVING VEHICLE NOS: SHK 339H / PLL 9880L  
ALONG Bukit Batok West Avenue 6 towards Bukit Batok Substation Complex

I/We the registered owner/driver of vehicle regn. no. SHK 339H which was involved  
in the above accident with motor vehicle regn no. PLL 9880L insured by you.

I/We also hereby authorise that any payment due to me/us from the aforesaid claim be paid to M/s UNITED SG AUTOMOBILE PTE LTD.

I/We hereby indemnify M/s United SG Automobile Pte Ltd against all claims and/or damages which may arise from all action taken for and on my/our behalf.

I/We hereby affirmed that above-mentioned statement to be true and correct.

Yours faithfully



Owner Signature

(Company's stamp if applicable)

Name in Full : Hasendran s/o Veerasamy  
NRIC No : S1344900H  
Address : Block 288E Bukit Batok  
Street 25 #07-164 S16542891

# United SG Automobile Pte Ltd

53 Ubi Avenue 1 #01-56 Paya Ubi Industrial Park Singapore 408934  
Tel : 6747-4454 | Fax : 6747-7752 | Email: claims@unitedsg.com.sg  
UEN No : 201729521C | GST No : 201729521C

## TAX INVOICE

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#08-16  
SINGAPORE 079120  
ATTN: MOTOR CLAIMS DEPARTMENT

Invoice number : UNITED/18/202  
Date : 29-Jun-18  
Vehicle number : SGK339H  
Make Model : MITSUBISHI LANCER  
Accident date : 31-May-18  
Reference number : USG-201806-02

Description		Amount SGD\$
Inclusive of supplying parts, labour, panel beating and spray painting		
Lump Sum Repair		7700.00
GST @ 7%		539.00
	Total	8239.00

Singdollars: Eight Thousand Two Hundred and Thirty Nine



UNITED SG AUTOMOBILE PTE LTD



## S-26 Auto

Co. Reg No: 53343173E

Address: 31, Jurong Port Road,  
#04-27/28, Jurong Logistics Hub,  
Singapore 619115

Tel: 6274 0030

### VEHICLE RENTAL AGREEMENT

Vehicle No: Replacement No:

SKH33914	8839 C
----------	--------

Vios.

HIRER'S PARTICULAR		○ SAME AS HIRER DRIVER'S PARTICULAR	
Name: <i>Hasendran s/o Veerasamy</i>		Name: <i>Dineshwaran s/o Hasendra</i>	
Address:		Address: <i>Block 289E Bukit Batok</i>	
		<i>Street 25 #07-164 Spore 654289</i>	
IC: <i>S13449006</i>	D.O.B:	IC: <i>S 92230876</i>	D.O.B: <i>05 July 1992</i>
Contact:	Pass Date:	Contact: <i>9365 8290</i>	Pass Date: <i>03 July 2014</i>

	A - ACCIDENT	Hirer's acceptance
	C - CRACKED	
	D - DENTS	Driver's acceptance
	S - SCRATCHES	

RENTAL DETAILS					
Mileage Out		REMARKS	Mileage In		REMARKS
Date Out	<i>01 June 2018</i>		Date In	<i>16 June 2018</i>	
Time Out	<i>1500</i>		Time In	<i>1800</i>	
ASSIGNED BY			CHECKED BY		

RENTAL CHARGES				PETROL/ DIESEL LEVEL					
Daily	@ \$	<i>120</i>	<i>15</i> Days @ \$ <i>1800</i>	OUT	E	1/4	1/2	3/4	F
Weekly	@ \$		Wks @ \$						
Monthly	@ \$		Mth @ \$	IN	E	1/4	1/2	3/4	F
Hours	@ \$		Hrs @ \$						
*Inclusive of additional charges (if any)				Petrol Charges		YES	NO	AMT: _____	
Amt payable* \$ <i>1800</i>				CDW		YES	NO	AMT: _____	
Payment: ○ CASH ○ NETS ○ CHQ ○ VISA ○ MAST				Security Deposit		YES	NO	AMT: _____	
Bank/ Cheque No.:				Advance Payment		YES	NO	AMT: _____	

I/We have read and agree to the terms and conditions stated on this page and overleaf. I/We am/are also aware that should there be any parking and/or traffic offence committed during the leasing period when the vehicle is in my/our possession, we will be billed accordingly. Subsequently, our personal details may be tendered accordingly to the government parking and/or traffic offence department. With us undersigning below, I/We am/are sure that all information I/We have given to S-26 Auto in connection with this agreement are true and accurate.

#### IMPORTANT INFORMATION (To be go through by the personnel of S-26 Auto to the hirer and/or driver upon leasing of vehicle)

- > Only persons above 25 and below 60 years of age with 2 years driving experience, authorised, licensed and signing this agreement may drive the vehicle.
- > Vehicle is strictly for Singapore use only and may not be driven out of Singapore without prior consent of the company S-26 Auto.
- > Use of the vehicle illegal purpose such as in connection with theft, drug peddling or trafficking, smuggling is strictly prohibited.
- > Additional drivers are required to register with us before they are allowed to drive the vehicle. Otherwise, he/she will not be protected by the insurance cover.
- > The hirer shall be liable for excess charges for any late return of the rate shown per hour or on a per day basis.
- > In case of any accident, the hirer MUST report to S-26 Auto immediately regardless of the seriousness of the impact occurred. If there are bodily injuries, a police report MUST be made within the next 24 hours.
- > In view of all accident, the hirer will bear the full responsibility for the SGD\$3,500/- excess payable to S-26 Auto and also the first SGD\$3,500/- excess for damaged to the third party vehicle.

ACKNOWLEDGEMENT	
 Signature of hirer / driver (company stamp if any)	 For and on behalf of S-26 AUTO (authorised signature only)



## S-26 Auto

Co. Reg No: 53343173E

Address: 31, Jurong Port Road  
#04-27/28, Jurong Logistics  
Hub, Singapore 619115  
Tel: 6274 0030

## TERMS AND CONDITIONS

### **S-26 AUTO**

An agreement is made as per the day in the schedule between S-26 Auto (hereinafter called 'the owner') of the one part and the hirer named in the schedule hereto whose particulars and signature appear overleaf (hereinafter called 'the hirer') of the other part whereby it is agreed as follows : -

The owner will let and the hirer will take on hire, subject to terms and conditions hereinafter the motor vehicle described in the schedule here to (hereinafter call 'the vehicle'). Upon signing the agreement overleaf, the hirer shall agree to all terms and conditions stated on both sides of the agreement.

The hirer shall commence and expire on the date and time specified in the schedule.

The hirer acknowledges that the vehicle is the property of the owner and that the vehicle is without any visible defects and in perfect running condition. The hirer is under obligation to return the vehicle with all tyres, tools, accessories and equipment in as good order and condition as of what the vehicle was when collected by the hirer from the owner.

The hirer shall also pay rent in advance and the deposit specified in the agreement. The owner shall (without prejudice) be at liberty to retain out of such deposit :-

- a) The portion of any damage or loss which the hirer undertakes to be responsible regardless of the negligence as set out in this agreement.
  - b) The amount of any loss or damage for which the hirer is responsible under the provisions of the clause of the front page hereof.
  - c) Any other additional charges payable under clauses 7 and 8 hereof.
  - d) All cost and expenses.
5. During the period of leasing, customer shall not drive vehicle into Malaysia, Thailand without prior notification and payment of additional charges to the company.
6. The use of the vehicle is strictly restricted to the Republic Of Singapore only, otherwise with the prior consent of the owner. Additional surcharge shall be paid before the hirer is allowed to drive the vehicle into West Malaysia. The hirer hereby indemnifies and keeps indemnifies the owner against all loss suffered by the owner including all loss from inability to use the vehicle in consequence of the vehicle passing out of the Republic of Singapore without prior consent of the owner.
7. During the hiring period, petrol is at the hirer's expense if the vehicle is delivered with a full tank of petrol, it must be returned likewise. In the event if the hirer is unable to fill up the vehicle, the owner will be authorised to do so in his name and at the hirer's account.
8. If there is any breach of terms and conditions herein by the hirer, including the payment of rental charges and others, the hirer shall pay for the full owner's legal cost, loss, damage, claims and expenses arising out of any damage to the said vehicle. In the event if the hirer fail to return the vehicle at the expiration of the period of rent then without prejudice to the other rights of the owner and the hirer shall pay to the owner to every hour elapsing between the time of such expiration and the time the vehicle is returned to the owner such further charge in accordance with the owner's current rate of rental charges or at such other rate as the owner may in its absolute discretion deem fit.
9. Should you decided to direct our bill charges to some other person, firm or organisation who fail to make any payment promptly when due, you will have to undertake the payment and pay accordingly to the company upon demand. All charges and amounts due hereunder which are not paid when due shall bear interest at 2% per month until they are paid.
10. As mentioned overleaf, hirer will have to pay for all fines, penalties, forfeitures and court costs imposed for any parking or traffic offences with respect to the vehicle during the period of leasing under this agreement. You will immediately report such violations to the company and will hold company harmless from all claims arising out of such violations.
11. If the vehicle is confiscated by the Government, the hirer shall compensate the company on all cost incurred including the value of the vehicle at the material time of confiscation.
12. The hirer shall agree to take proper care of the vehicle and drive the same in a careful and skilful manner observing the traffic regulations and laws. In the event of any breach thereof, the hirer shall pay all Police and Traffic Court Summonses, Notices and Inquires in connection therewith. Particular attention is to be accorded to the following factor : -





## S-26 Auto

Co. Reg No: 53343173E

Address: 31, Jurong Port Road,  
#04-27/28, Jurong Logistics  
Hub, Singapore 619115  
Tel: 6274 0030

### TERMS AND CONDITIONS

- a) The hirer shall not carry load or passengers in excess of the motor vehicle's license carrying capacity of that particular make and model the hirer is leasing.
- b) The hirer shall not drive the vehicle whilst under the influence of intoxicating liquor or drugs.
- c) The hirer shall not leave the vehicle unattended while it is unlocked or while the keys are inside the vehicle.
- d) The hirer shall not deface the paintwork or bodywork of the vehicle nor add or erect any painting sign-writing.
- e) The hirer shall not use or permit the vehicle to be used for transportation of animals, creatures, plant or fruit which is or which contains properties which are unfit for carriage or which are improperly packed, inflammable, harmful, illegal, verminous, infested, contaminated, condemned or offensive smelling.
- f) The hirer must inform the owner of any serious faults, failures, mechanical issues or whatsoever so that the owner can rectify the problem. Otherwise should there be any losses, damaged and/or charges arise, the hirer will be liable.
- g) In case of any breakdowns, failures, accidents, or whatsoever occurs in Singapore or West Malaysia, the hirer must inform the owner immediately and/or its agent and the hirer is not allowed to engage any towing agents or motor workshops without the owner's written consent. Should the hirer engage any unauthorised workshop and/or agents, the hirer shall be liable to pay for the loss.

An authorised driver will immediately report any accident within 24 hours to the company at the location where the vehicle was rented and will also deliver to the company at that location, every summons, and complaint of paper of any kind received by authorised driver in any relating to any accident involving the vehicle while rented under this agreement. An authorised driver will not aid or encourage the filing of any claims as a result of any accident and cooperate fully with the company and its insurer in the investigation and defence of any claim or lawsuit. The hirer or driver must not admit to or compound any claim either partially or in full. It is important that they secure the names and address of all witnesses as well as the license number of any and all vehicles involved in the accident. In any case if the local police authorities have to be informed of any injuries with relates to the accident that happened in Malaysia, hirer are required to lodge a police report both in Malaysia and Singapore within 24 hours. All repairs must only be carried out by - Auto authorised workshop.

In the event that the vehicle or any part thereof is damaged or missing which includes all accessories and items, the hirer shall forthwith pay to the owner the excess amount payable in respect of each and every incident regardless of negligence. Arrangement may however be made at the request of the hirer to cover the vehicle with such a policy during the period of the hire, upon the hire having the current rate of premium as evidenced by his initials in 'accept' space provided on the overleaf.

- 15. The hirer and the registered additional driver are not insured under a policy of insurance against personal injury or death to themselves.
- 16. The owner is not obligated to provide any replacement vehicle if any accidents or breakdowns occur in Malaysia, whether or not the accident or breakdown is due to the negligence of the hirer, but however, if the owner chooses to provide any replacement vehicle for accident that occurred in Singapore, it will be at the hirer's expenses.
- 17. The person signing this agreement assumes the full personal responsibility along with the firm, person or organisation in whole name he/she might sign.
- 18. In the event of any disputes arising out of or in connection with this agreement, the parties here to, hereby and submit to the jurisdiction of the Courts of the Republic Of Singapore.

# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224  
Email: Winsongkk@hotmail.com Contact: 9747 0063  
Company Register No. 53326249J

Our Ref: WG/TP/2018-201  
Invoice No: TP/UNITED/2018-201  
Vehicle No: SGK339H  
Attn: NASENDRAN S/O VEERASAMY  
Company: UNITED SG AUTOMOBILE PTE LTD  
Address: 53 UBI AVE 1, #01-56 PAYA UBI INDUSTRIAL PARK,  
SINGAPORE 408934

Date 25 June 2018

## Invoice

Surveyor Fee:	S\$310
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$39/- (@ \$1 per photo, total 39 photos)
Total:	S\$449

Surveyor: Winsen Goh  
Signature: *[Signature]*  
Date: 25/6/2018



# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: [winsongkk@hotmail.com](mailto:winsongkk@hotmail.com) Contact: 9747 0063

Company Register No. 53326249J

## ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S NASENDRAN S/O VEERASAMY  
C/O UNITED SG AUTOMOBILE PTE LTD  
53 UBI AVE 1, #01-56 PAYA UBI INDUSTRIAL PARK  
SINGAPORE 408934

Date : 25 June 2018  
Our Ref : WG/TP/2018-202

### REFERENCE PARTICULARS

Date of Accident : 31 May 2018  
Date of Inspection : 04 June 2016

Type of Inspection : Third Party Claim  
Date of Re-Inspr : 06 June 2018

### VEHICLE PARTICULARS

Registration No : SGK339H  
Make : MITSUBISHI  
Model : LANCER 1.6 M  
Year : 2006

Engine No : 4G18HK2917  
Chassis No : JMYSNCS3A6U008191  
Odometer : 208755km  
Colour : White

### CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good  
Foot Brake : Serviceable  
Hand Brake : Serviceable

General Body Work : Good  
Steering : Serviceable  
Lightings : Serviceable

### TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Near side	Kumho	215/55R16
Front Off Side	Kumho	215/55R16
Rear Near Side	Kumho	215/55R16
Rear off Side	Kumho	215/55R16

Thread Balance
5 mm
5 mm
5 mm
5 mm

### GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear portion.  
For details, refer to assessment for repairs and photographs attached.

### ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$7,700.00** nett at lump sum basis. (Subject to GST if applicable)  
Under normal circumstances, estimated period required for repairs : Fourteen ( 14 ) working days.

Enclosed Thirty-nine ( 39 ) photographs depicting damage to the vehicle.

Inspection conducted at : UNITED SG AUTOMOBILE PTE LTD  
53 UBI AVE 1, #01-56 PAYA UBI INDUSTRIAL PARK. SINGAPORE 408934

In accordance to your instruction, we have **not authorise** repairs and inspection  
was conducted strictly on a **"WITHOUT PREJUDICE BASIS"**.

VEHICLE NO : SGK339H  
MODEL : LANCER 1.6 M

Our Ref : WG/TP/2018-202

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
	PC/SET			
1 REAR BUMPER	1	DEFORMED	\$ 765.30	\$ 765.30 ✓
2 REAR BUMPER SIDE RETAINER	2	NECESSARY	\$ 69.40	\$ 69.40 ✓
3 REAR BUMPER BEAM CENTRE	1	NOT NECESSARY	\$ 68.00	\$ - ✓
4 END PANEL	1	DENTED	\$ 589.40	\$ 589.40 ✓
5 END PANEL TOP GARNISH	1	DEFORMED	\$ 149.60	\$ 149.60 ✓
6 TAILLAMP	2	CRACKED	\$ 897.60	\$ 897.60 ✓ 664
7 TAILLAMP SEAL	2	NECESSARY	\$ 30.00	\$ 30.00 ✓
8 REAR LH TAILLAMP PANEL	1	REPAIR	\$ 159.00	\$ - ✓
9 REAR RH TAILLAMP PANEL	1	DENTED	\$ 159.00	\$ 159.00 ✓
10 REAR LH FENDER INNER TRIM	1	NOT NECESSARY	\$ 212.93	\$ - ✓
11 REAR RH FENDER INNER TRIM	1	TORN	\$ 212.93	\$ 212.93 ✓
12 REAR WINDSCREEN MOULDING	1	NECESSARY	\$ 69.00	\$ 69.00 ✓
13 BOOTLID EMBLEM -LOGO	1	NECESSARY	\$ 56.00	\$ 56.00 ✓
			\$ 3,438.16	\$ 2,998.23
		Less 10%	\$ 343.81	\$ 299.82
			<u>\$ 3,094.35</u>	<u>\$ 2,698.41</u>
<b>B) S/NETT ITEM</b>				
14 REAR BUMPER CLIP	1 SET	NECESSARY	\$ 60.00	\$ 50.00 30
15 REAR WINDSCREEN MOULDING	1	NECESSARY	\$ 130.00	\$ 100.00 ✓
16 REAR REVERSE SENSOR	1 SET	MALFUNCTION	\$ 400.00	\$ 300.00 200
17 REAR FENDER INNER TRIM CLIP	1 SET	NECESSARY	\$ 50.00	\$ 40.00 ✓
18 BOOTLID ( AFTER MARKET )	1	DENTED	\$ 1,400.00	\$ 1,200.00 800
19 BOOTLID OUTER GARNISH ( AFTER MARKET )	1	CRACKED	\$ 400.00	\$ 300.00 ✓
20 EXHAUST SILENCER ( AFTER MARKET )	1	DENTED	\$ 1,500.00	\$ 1,200.00 800
21 JOINT SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00 60
22 WINDSCREEN SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00 ✓
			<u>\$ 4,240.00</u>	<u>\$ 3,450.00</u>
		<b>Parts Total :</b>	<u>\$ 7,334.35</u>	<u>\$ 6,148.41</u>
<b>C) LABOUR CHARGES &amp; MISC</b>				
23 CHECK REAR WIRING AND LIGHTING SYSTEM			\$ 60.00	\$ 50.00 30
24 REMOVE AND REFIT REAR LINING, TRIM AND GARNISH			\$ 200.00	\$ 180.00 60
24 REMOVE AND RENEW REAR REVERSE SENSOR			\$ 150.00	\$ 130.00 50
25 REMOVE AND RENEW REAR EXHAUST ASSY			\$ 150.00	\$ 120.00 80
26 REMOVE AND REFIT REAR WINDSCREEN			\$ 150.00	\$ 120.00 ✓
27 TRANSFER PARTS , ATTACHMENT FROM OLD BOOTLID TO NEW			\$ 200.00	\$ 180.00 30
28 PANEL BEATING ON AFFECTED AREAS			\$ 1,600.00	\$ 1,400.00 1000
29 SPRAY PANTING ON AFFECTED AREAS			\$ 1,400.00	\$ 1,200.00 1000
30 APPLY ANTI RUST ON AFFECTED AREAS			\$ 150.00	\$ 130.00 60
		<b>Labour Total :</b>	<u>\$ 4,060.00</u>	<u>\$ 3,510.00</u>
		<b>Total Parts and Laboure :</b>	<u>\$ 11,394.35</u>	<u>\$ 9,658.41</u>

FINAL LUMP SUM ADJUSTMENT

\$ 7,700.00

08 ap

#### POINT OF IMPACT

The impact was confined to the rear portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.

#### ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

#### CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$7,700.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully

WG APPRAISAL SERVICE

Winson Goh  
Automotive Appraiser



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jun 2018 <a href="#">Edit Reg</a>		01 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	<b>WEE PEI WEN (HUANG PEIWEN)</b> , ID: S8712289A		
Main Claimant:	<b>NASENDRAN S/O VEERASAMY</b> , ID: S1344900G		
Vehicle Reg. No.:	<b>SGK339H</b>	Date of Loss:	31/05/2018 20:00 - :59 [142 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 1025443037SG</b>	Policy/Cover Note No.:	2100508625 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SLL9880L</b>	Policy No. (Claimant):	GA118160/1
		Excess:	
Repairer:	<b>United SG Automobile Pte Ltd (HQ)</b> 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park, 408934 Ubi - Tel: 9007 7556		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 14/06/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date    Priority    Type    Task Group    Subject    Handler    Assigned By    Completed On    Created On    Done?

No results.



## Claim Documents

**\*SGK339H (1025443037SG)**  
**[SLL9880L]**  
**TP**  
**NASENDRAN S/O VEERASAMY**  
**May 31 2018 8:00PM**  
**[WEE PEI WEN (HUANG PEIWEN)]**  
**United SG Automobile Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	12/06/18 15:40	Video - Accident														Load MP4		
Assessment Reports															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	12/06/18 15:24	Accident Statement From: SC - Reg. No: SLL9880L, Claimant: WEE PEI WEN (HUANG PEI WEN)														Load HTM		
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
2	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
3	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
4	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
5	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
6	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
7	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
8	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
9	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
10	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
11	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
12	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
13	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
14	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
15	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
16	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
17	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
18	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
19	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
20	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
21	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
22	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
23	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
24	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
25	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
26	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
27	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
28	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
29	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
30	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
31	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
32	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		
33	11/06/18 14:44	General View														Load JPG <input checked="" type="checkbox"/>		



Video			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	11/06/18 14:44	General View	1 Load JPG	✓
35	11/06/18 14:44	General View	1 Load JPG	✓
36	11/06/18 14:44	General View	1 Load JPG	✓
37	11/06/18 14:44	General View	1 Load JPG	✓
38	11/06/18 14:44	General View	1 Load JPG	✓
39	11/06/18 14:44	General View	1 Load JPG	✓
40	11/06/18 14:44	General View	1 Load JPG	✓
41	11/06/18 14:44	General View	1 Load JPG	✓
42	11/06/18 14:44	General View	1 Load JPG	✓
43	11/06/18 14:44	General View	1 Load JPG	✓
44	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
45	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
46	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
47	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
48	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
49	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
50	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
51	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
52	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
53	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
54	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
55	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
56	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
57	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
58	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
59	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
60	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
61	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
62	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
63	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
64	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
65	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
66	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
67	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
68	03/10/19 14:00	Reinspection Photo	1 Load JPG	✓
69	03/10/19 14:01	Photo After Spray	1 Load JPG	✓
70	03/10/19 14:01	Photo After Spray	1 Load JPG	✓
71	03/10/19 14:01	Photo After Spray	1 Load JPG	✓
72	03/10/19 14:01	Photo After Spray	1 Load JPG	✓
73	03/10/19 14:01	Photo After Spray	1 Load JPG	✓
74	03/10/19 14:01	Photo After Spray	1 Load JPG	✓
75	03/10/19 14:01	Photo After Spray	1 Load JPG	✓
76	03/10/19 14:01	Photo After Spray	1 Load JPG	✓
77	03/10/19 14:01	Photo After Spray	1 Load JPG	✓
78	03/10/19 14:01	Photo After Spray	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/06/18 17:00	EMAIL FROM AIG DD 01062018	1 Load PDF	
2	05/06/18 17:00	TP GIA REPORT	1 Load PDF	
3	14/06/18 10:27	Email from AIG dd 120618	1 Load PDF	
4	14/06/18 10:27	Email to TP_Reject dd 140618	1 Load PDF	
5	03/10/19 13:59	Email to TP_Maintain rejection dd 310718	1 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/06/18 11:25	OI GIA REPORT	1 Load PDF	

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG18010192/APB3S2  
**Date:** 03/10/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100508625  
**Claimant Vehicle No :** SGK339H **Insured Vehicle No :** SLL9880L  
 Date of Loss: 31/05/2018 Nature of Claim: TP Claim No: 1025443037SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGK339H**  
 Make & Model: MITSUBISHI LANCER, 1.3 (A) Engine No: 4G18HK2917  
 Reg. Date: 27/07/2006 (Man. Year: 2006) Chassis No: JMYSNCS3A6U008191  
 Colour: White Odometer: 208755 km  
 Engine Capacity: 1584 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/50 R15 Rear Tyre Size: 195/50 R15  
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm  
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,334.34	4,356.07	2,978.27	40.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	2,310.00	1,750.00	43.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,394.34</b>	<b>6,666.07</b>	<b>4,728.27</b>	<b>41.50</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,300.00</b>		
<b>(S\$)</b>	11,394.34	5,300.00	6,094.34	53.49
<b>+ GST 7.00/7.00% (S\$)</b>	797.60	371.00	426.60	53.49
<b>Nett Amount (S\$)</b>	<b>12,191.94</b>	<b>5,671.00</b>	<b>6,520.94</b>	<b>53.49</b>

### INSPECTION

Date of Assignment: 01/06/2018  
 Date Inspected: 05/06/2018 Inspected At: United SG Automobile Pte Ltd (HQ)  
 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park  
 Singapore 408934  
 Estimated Period of Repair: 8.0 days

**Adjuster:** ADRIAN LING

**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	765.30 FL	*765.30 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	69.40 FL	*69.40 FL
3	1		*REAR BUMPER BEAM CENTRE	Not Necessary	68.00 FL	*- FL
4	1		*END PANEL	Dented	589.40 FL	*589.40 FL
5	1		*END PANEL TOP GARNISH	Deformed	149.60 FL	*149.60 FL
6	2		*TAILLAMP	Cracked	897.60 FL	*664.00 FL
7	1		*TAILLAMP SEAL	Necessary	30.00 FL	*30.00 FL
8	1		*REAR LH TAILLAMP PANEL	Repair	159.00 FL	*- FL
9	1		*REAR RH TAILLAMP PANEL	Dented	159.00 FL	*159.00 FL
10	1		*REAR LH FENDER INNER TRIM	Not Necessary	212.93 FL	*- FL
11	1		*REAR RH FENDER INNER TRIM	Torn	212.93 FL	*212.93 FL
12	1		*REAR WINDSCREEN MOULDING	Not Necessary	69.00 FL	*- FL
13	1		*BOOTLID EMBLEM - LOGO	Necessary	56.00 FL	*56.00 FL
14	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
15	1		*REAR WINDSCREEN MOULDING	Not Necessary	130.00 FS	*- FS
16	1		*SET REAR REVERSE SENSOR	Malfunction	400.00 FS	*200.00 FS
17	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	50.00 FS	*40.00 FS
18	1		*BOOTLID (AFTER MARKET)	Dented	1,400.00 FS	*800.00 FS
19	1		*BOOTLID OUTER GARNISH (AFTER MARKET)	Not Necessary	400.00 FS	*- FS
20	1		*EXHAUST SILENCER (AFTER MARKET)	Bent	1,500.00 FS	*800.00 FS
21	1		*JOINT SEALANT	Necessary	150.00 FS	*60.00 FS
22	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,678.16</b>	<b>4,625.63</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>343.82</b>	<b>269.56</b>
<b>Total Parts (\$\$)</b>	<b>7,334.34</b>	<b>4,356.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM.	New	60.00	30.00
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.	New	200.00	60.00
3	REMOVE AND RENEW REAR REVERSE SENSOR.	New	150.00	50.00
4	REMOVE AND RENEW REAR EXHAUST ASSY.	New	150.00	80.00
5	REMOVE AND RENEW REAR WINDSCREEN.	New	150.00	0.00
6	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW.	New	200.00	30.00
7	PANEL BEATING ON AFFECTED AREAS.	New	1,600.00	1,000.00
8	SPRAY PAINTING AFFECTED AREAS.	New	1,400.00	1,000.00
9	APPLY ANTI RUST ON AFFECTED AREAS.	New	150.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>4,060.00</b>	<b>2,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >