

OK

22/03/2018

REF: CS/FCI18010198/Uvbnz Special Instruction:

ASS. REC. BY:

MIV2405

ASSIGNMENT (Office)

From (Person): WS Sithara of FCI Date/Time: 05062018 232pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SBR 2448K Insured: SHB 3623C

at Workshop m/s SME Motor Tel: 6747 6106

of Blk 1 Kaki Bukit Ave 6 #02-15

Policy No: Claim No: DIS004277MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 27052018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' H.O.D. Endorsement:

Date/Time: 05062018 251pm Person Contacted: Pei Ying Vehicle IN/OUT

| Date/Time | Action/Instruction                 |
|-----------|------------------------------------|
|           | ( ✓ ) Estimate                     |
|           | SBR 2448K - CS / HSB10V08376 / Rvn |
|           | SHB 3623C - X                      |
|           |                                    |
| 12/6/18   | Email preli revised to FCI         |
|           |                                    |
|           |                                    |

DIA: 30042010

(06/11/13) Wef

ASS. REC. BY: MORCIS

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBR244Pat Workshop m/s Sm

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 10367 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SBR244P Yr Regn: 5-11  
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Volkswagen Passat C.C / 1798Colour: Black A/C: Insured / Std / NI / NASp. Reading: 200227 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVWZZZ3CZB6749831Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 235/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or continental

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 27/5/18D.O.A. 11/6/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 35708No second hand partsno LS repair→ no endorsement26/7/18 confirmed final fig @ 10367.74 with AM ying (Real 10,692.78, 50%) (No LS)

RECEIVED 27 JUL 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 27/7- typistDays Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: CWSLump Sum / I.B.I: (\$ 10,367.74)

Survey Fee:

Transportation:

S + RS, SI

Photocopy

Others

TOTAL

11x15

170 + 165

50

50

75

(510)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18004277MFSH

Our ref: CS/FCI18010198/Uvb

DATE: 12/6/2018

The Motor Claims Department  
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

**INITIAL INSPECTION REPORT OF VEHICLE NO. SBR 2448K**


We thank for your instruction on 5/6/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 11/6/2018 at the premises of M/s SME MOTOR PTE LTD and have the following to report:-

|                          |                |
|--------------------------|----------------|
| Workshop Estimate Amount | : S\$19,224.17 |
| Revised Estimate Amount  | : S\$9,127.45  |
| "Check" Items Amount     | : S\$4,313.25  |
| Market Value             | : S\$          |
| LTA Reimbursement Value  | : S\$          |
| Nett Value               | : S\$          |

**Description of Damage:**

The vehicle sustained damages at the n/s body



Comments/Present Status:  
Damages Consistent

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

### MOTOR SURVEY ASSIGNMENT

|                           |                                                               |                                      |
|---------------------------|---------------------------------------------------------------|--------------------------------------|
| <b>Date</b>               | 30-05-2018                                                    | <b>Our Ref No.</b> D18004277MFSH     |
| <b>Accident Date</b>      | 27-05-2018                                                    | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHB3623C                                                      | <b>Third Party Vehicle.</b> SBR2448K |
| <b>Survey Location</b>    | 1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18 AUTOBAY @ KAKI BUKIT |                                      |
| <b>Contact Person.</b>    | PEIYING                                                       |                                      |
| <b>Contact No.</b>        | 67476106/ 0                                                   | <b>Fax No.</b> 67442368              |
| <b>Survey Type</b>        | DIRECT SETTLEMENT:                                            |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                                  |                                      |
| <b>Contact Person</b>     | NA                                                            | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA                                                            |                                      |

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

|                          |                   |                                |
|--------------------------|-------------------|--------------------------------|
| <b>Cc : Workshop</b>     | SME MOTOR PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | SITHARA           |                                |

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Tuesday, 12 June 2018 9:19 AM  
**To:** 'Claim Workflow System'  
**Cc:** SITHARA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18004277MFSH/1, SBR 2448K  
**Attachments:** SBR 2448K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SBR 2448K  
Date of survey: 11/6/2018  
Number of days:5 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 5 June 2018 2:53 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18004277MFSH/1

Dear Sir / madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 5 June, 2018 2:32 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SITHARA@MSFIRSTCAPITAL.COM.SG](mailto:SITHARA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004277MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



Passat CC 1.8T

Price Range ▼

Depreciation ▼

2011 ▼

Vehicle Type ▼

Home » Used Cars » Faster Auto Trading » Volkswagen Passat CC 1.8T

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Volkswagen Passat CC 1.8T

Overview

Financial

Accessories

Similar

Research

Photos

Map



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

## Car Details

|                     |                                                                                                                                                       |   |
|---------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|---|
| <b>Price</b>        | <b>\$50,800</b>                                                                                                                                       |   |
| <b>Depreciation</b> | \$11,530 /yr<br>View models with similar depreciation                                                                                                 | ? |
| <b>Reg Date</b>     | 21-Jun-2011<br>(3yrs 9days COE left)                                                                                                                  |   |
| <b>Manufactured</b> | 2011                                                                                                                                                  | ? |
| <b>Mileage</b>      | 114,000 km (16.3k /yr)                                                                                                                                |   |
| <b>Transmission</b> | Auto                                                                                                                                                  |   |
| <b>Engine Cap</b>   | 1,798 cc                                                                                                                                              |   |
| <b>Road Tax</b>     | \$976 /yr                                                                                                                                             | ? |
| <b>Power</b>        | 118.0 kW (158 bhp)<br>View specs of the Volkswagen Passat (2005-2011)                                                                                 |   |
| <b>Curb Weight</b>  | 1,513 kg                                                                                                                                              | ? |
| <b>Features</b>     | Professional APR Tuned, Upgraded Instrument Panel, 7 Speed DSG, Paddle Shift, ABS, BA, EBD, SRS Airbags, Keyless Entry/Start/Stop, Cruise Control.    |   |
| <b>Accessories</b>  | Electric Memory Seats, Dual Digital Auto Climate Aircon With Rear Aircon Vent, Multi Function Steering Controls, Auto Park Feature,Built-In Bluetooth |   |
| <b>Description</b>  | 1 Owner. 5 Seater Passat CC, Low Mileage, Pristine Black Exterior With Perfect Brown Leather Interior.Call For Viewing Appointment.                   |   |



Seller Infor

Company

Address

Location

## Car Leasing



Compare



Passat CC 1.8T

Price Range ▼

Depreciation ▼

2011 ▼

Vehicle Type ▼

Home » Used Cars » Dosh Car » Volkswagen Passat CC 1.8T

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Volkswagen Passat CC 1.8T

Overview

Financial

Accessories

Similar

Research

Photos

Map



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

## Car Details

|                     |                                                                                                                                                                   |   |
|---------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|---|
| <b>Price</b>        | <b>\$50,151</b>                                                                                                                                                   |   |
| <b>Depreciation</b> | \$12,050 /yr<br>View models with similar depreciation                                                                                                             | ? |
| <b>Reg Date</b>     | 15-Apr-2011<br>(2yrs 10mths 3days COE left)                                                                                                                       |   |
| <b>Manufactured</b> | 2011                                                                                                                                                              | ? |
| <b>Mileage</b>      | -                                                                                                                                                                 |   |
| <b>Transmission</b> | Auto                                                                                                                                                              |   |
| <b>Engine Cap</b>   | 1,798 cc                                                                                                                                                          |   |
| <b>Road Tax</b>     | \$976 /yr                                                                                                                                                         | ? |
| <b>Power</b>        | 118.0 kW (158 bhp)<br>View specs of the Volkswagen Passat (2005-2011)                                                                                             |   |
| <b>Curb Weight</b>  | 1,513 kg                                                                                                                                                          | ? |
| <b>Features</b>     | Responsive 1.8L TSI Turbocharged Engine, 7 Speed DSG, Paddle Shift, ABS, BA, EBD, Auto Hold, Airbag, Keyless Entry/Start/Stop, Cruise Control.                    |   |
| <b>Accessories</b>  | Electric Memory Seat, Dual Digital Auto Climate Aircon With Rear Aircon Vent, Multi Function Steering Controls, Retractable Side Mirror With Indicator            |   |
| <b>Description</b>  | Beautiful Unit With Original Condition! Peace Of Mind! Serviced Regularly. Well Maintained By Previous Careful Owner. One Of The Most Popular And Reliable Luxury |   |



Seller Information

Company

## Car Leasing

**CL LEASING**  
YOUR PREFERRED CAR LEASING  
OPTION IN SINGAPORE

6769 7117 8720 5000 8720 8000

Compare



> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                          |
|-------------------------------------|--------------------------|
| <b>Vehicle Owner Particulars</b>    |                          |
| Owner ID Type:                      | Singapore NRIC           |
| Owner ID:                           | 2581G                    |
| <b>Vehicle Details</b>              |                          |
| Vehicle No.:                        | SBR2448K                 |
| Vehicle to be Exported:             | No                       |
| Intended De-registration Date:      | 12 Jun 2018              |
| Vehicle Make:                       | VOLKSWAGEN               |
| Vehicle Model:                      | PASSAT CC 1.8T AT 3574H7 |
| Primary Colour:                     | Black                    |
| Manufacturing Year:                 | 2011                     |
| Engine No.:                         | CDA195684                |
| Chassis No.:                        | WVWZZZ3CZBE749831        |
| Maximum Power Output:               | 118.0 kW (158 bhp)       |
| Open Market Value:                  | \$31,775.00              |
| Original Registration Date:         | 18 May 2011              |
| First Registration Date:            | 18 May 2011              |
| Transfer Count:                     | 0                        |
| Actual ARF Paid:                    | \$31,775.00              |
| <b>Intended PARF Rebate Details</b> |                          |
| PARF Eligibility:                   | Yes                      |
| PARF Eligibility Expiry Date:       | 17 May 2021              |
| PARF Rebate Amount:                 | \$19,065.00              |
| <b>Intended COE Rebate Details</b>  |                          |
| COE Expiry Date:                    | 17 May 2021              |
| COE Category:                       | B - Car (1601cc & above) |
| COE Period(Years):                  | 10                       |
| QP Paid:                            | \$56,801.00              |
| COE Rebate Amount:                  | \$16,643.00              |
| <b>Total Rebate Amount:</b>         | <b>\$35,708.00</b>       |

The information contained herein is correct as at 11 Jun 2018

OK

# SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883  
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg  
 GST:201119451E RCB NO:201119451E

*Not Actual*  
*1/58*  
*5d7.*  
*11/6/18*  
*Tekong has other reg-*

M/S : FIRST CAPITAL INSURANCE LIMITED  
 36 ROBINSON ROAD #16-01  
 CITY HOUSE  
 Singapore 068877  
 TEL: 65073848 FAX: 65073849  
 ATTN: Motor Claim Department  
 Your Ref No: 18/FC/TP-114 (05)  
 Claim Type: Third Party  
 Accident Date: 27/05/2018  
 TP Veh Reg No: SHB3623C

Estimate No: EST0004167  
 Date: 01 Jun 2018  
 Policy No: GA194708  
 Veh Reg No: SBR2448K  
 Make/Model: VOLKSWAGEN PASSAT  
 Chasis No: WVVZZZ3CZBE749831  
 Engine No: CDA195684  
 Reg. Date: 18/05/2011

## Estimate Repair Cost to Vehicle No :SBR2448K

| Description                                           | Quantity         | List Price | Amount    |
|-------------------------------------------------------|------------------|------------|-----------|
|                                                       |                  | SS         | SS        |
| <b>List Price</b>                                     |                  |            |           |
| 1 LH SIDE MIRROR SIGNAL LAMP <i>scn n/c</i>           | 1 PC             | 75.00      | X         |
| 2 FRT LH DOOR <i>3d50 2296.99</i>                     | 1 PC             | 2,681.50   | —         |
| 3 FRT LH DOOR LOCK <i>11</i>                          | 1 PC             | 412.50     | X         |
| 4 FRT LH DOOR PROTECTOR (CHROME) <i>3d4</i>           | 1 PC             | 197.90     | —         |
| 5 FRT LH DOOR OUTER HANDLE <i>11</i>                  | 1 PC             | 750.00     | X         |
| 6 FRT LH DOOR GLASS GEAR <i>11</i>                    | 1 PC             | 650.00     | X         |
| 7 FRT LH DOOR POWER WINDOW MOTOR <i>11</i>            | 1 PC             | 1,250.00   | X         |
| 8 FRT LH DOOR INNER TRIM BOARD <i>11</i>              | 1 PC             | 1,690.00   | X         |
| 9 FRT LH DOOR INNER TRIM BOARD CLIP <i>11</i>         | 8 PC             | 40.00      | X         |
| 10 REAR LH DOOR <i>20/3d4</i>                         | 1 PC             | 1,625.00   | —         |
| 11 REAR LH DOOR PROTECTOR (CHROME) <i>scn</i>         | 1 PC             | 197.90     | —         |
| 12 REAR LH SHOCK ABSORBER <i>11</i>                   | 1 PC             | 550.00     | X         |
| 13 REAR LH WHEEL HUB <i>11</i>                        | 1 PC             | 650.11     | X         |
| 14 REAR LH SPORTS RIM <i>CU7</i>                      | 1 PC             | 1,800.00   | 8005.~    |
| 15 REAR BUMPER <i>2d4</i>                             | 1 PC             | 1,895.70   | —         |
| 16 REAR BUMPER RETAINER LH <i>3d4</i>                 | 1 PC             | 95.00      | —         |
| 17 REAR BUMPER CLIP <i>2d4</i>                        | 10 PC            | 50.00      | —         |
| 18 REAR BUMPER MOULDING (SIDES) <i>sc2 115 287.50</i> | 2 PC             | 575.00     | 12c       |
| 19 REAR BUMPER MOULDING CENTER <i>11</i>              | 1 PC             | 295.90     | X         |
| 20 LH CENTER PILLAR <i>~</i>                          | 1 PC             | 3,000.90   | X         |
|                                                       |                  | 18,482.41  |           |
|                                                       | Less 10%         | 1,848.24   | 16,634.17 |
| <b>Labour</b>                                         |                  |            |           |
| 21 WIRE CHECKING                                      | 1 UNIT           | 50.00      | 20        |
| 22 REMOVE & REFIX REAR UNDERCARRIAGE                  | 1 UNIT <i>11</i> | 200.00     | X         |
| 23 4 WHEEL ALIGNMENT                                  | 1 UNIT           | 65.00      | 60        |
| 24 WHEEL BALANCING                                    | 1 UNIT <i>11</i> | 25.00      | X         |
| 25 REMOVE & REFIX CUSHION AND SEATS                   | 1 UNIT           | 150.00     | 80        |
| 26 TRANSFER 2 DOORS COMPONENT FROM OLD TO NEW         | 1 UNIT           | 250.00     | 160       |
| 27 LABOUR CHARGE                                      | 1 UNIT           | 950.00     | 800       |
| 28 SPRAY PAINTING                                     | 1 UNIT           | 900.00     | 880       |
|                                                       |                  | 2,590.00   | 2,590.00  |

6645.99

# SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883  
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg  
GST:201119451E RCB NO:201119451E

**M/S :** FIRST CAPITAL INSURANCE LIMITED  
36 ROBINSON ROAD #16-01  
CITY HOUSE  
Singapore 068877  
**TEL:** 65073848 **FAX:** 65073849  
**ATTN:** Motor Claim Department  
**Your Ref No:** 18/FC/TP-114 (05)  
**Claim Type:** Third Party  
**Accident Date:** 27/05/2018  
**TP Veh Reg No:** SHB3623C

**Estimate No:** EST0004167  
**Date:** 01 Jun 2018  
**Policy No:** GA194708  
**Veh Reg No:** SBR2448K  
**Make/Model:** VOLKSWAGEN PASSAT  
**Chasis No:** WVWZZZ3CZBE749831  
**Engine No:** CDA195684  
**Reg. Date:** 18/05/2011


## Estimate Repair Cost to Vehicle No :SBR2448K

| Description | Quantity   | List Price           | Amount       |
|-------------|------------|----------------------|--------------|
|             |            | <u>SS</u>            | <u>SS</u>    |
|             | 21, 060.52 | Total                | SS 19,224.17 |
|             |            | Add GST @ 7%         | 1,345.69     |
|             |            | Total Amount Payable | SS 20,569.86 |

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FIVE HUNDRED SIXTY NINE AND CENTS EIGHTY SIX ONLY

**For SME Motor Pte Ltd**

AUTHORISED SIGNATURE



# SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883  
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg  
 GST:201119451E RCB NO:201119451E

M/S : ANTHON DAMIEN KIONG CHOR HWEE

Singapore

ATTN:

Your Ref No: 18/FC/TP-114 (05)

Claim Type: Third Party

Accident Date: 27/05/2018

TP Veh Reg No: SHB3623C

Estimate No: EST0004167

Date: 18 Jul 2018

Policy No: GA194708

Veh Reg No: SBR2448K

Make/Model: VOLKSWAGEN PASSAT

Chasis No: WVWZZZ3CZBE749831

Engine No: CDA195684

Reg. Date: 18/05/2011

## Estimate Repair Cost to Vehicle No :SBR2448K

| Description                     | Quantity             | List Price | Amount      |
|---------------------------------|----------------------|------------|-------------|
|                                 |                      | <u>SS</u>  | <u>SS</u>   |
| Supplementary Parts to Repair   |                      |            |             |
| <b>List Price</b>               |                      |            |             |
| 1 REAR LH DOOR RUBBER (AT DOOR) | 1 PC                 | 287.50 ✓   |             |
| 2 SIDE SKIRTS LH                | 1 PC                 | 920.10 ✓   |             |
| 3 FRT LH DOOR INNER RUBBER      | 1 PC                 | 242.90 ✓   |             |
| 4 LH SIDE SKIRTS BRACKET (FRT)  | 1 PC                 | 162.50 ✓   |             |
| 5 LH SIDE SKIRTS BRACKET CLIPS  | 7 PC                 | 38.50 ✓    |             |
|                                 |                      | 1,651.50   |             |
|                                 | Less 10%             | 165.15     | 1,486.35    |
| <b>Labour</b>                   |                      |            |             |
| 6 REPAIR LH DOOR PILLAR         | 1 UNIT               | 200.00 X   |             |
| 7 SPRAY LH DOOR PILLAR          | 1 UNIT               | 150.00 100 |             |
|                                 |                      | 350.00     | 350.00      |
|                                 | Total                |            | SS 1,836.35 |
|                                 | GST Amount           |            | SS 128.54   |
|                                 | Total Amount Payable |            | SS 1,964.89 |

List = 8682  
 - 10% = 7813.80

SN 800  
 LC 2350

~~10,963.80~~

86820.8

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

P- 8297.49  
 102  
 7467.74  
 2900  
 10367.74



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                             |                            |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------|--|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                                             | Ref : CS/FCI18010198/Uvbn2 |                                                                                     |  |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                             | Date : 03-08-2018          |  |  |
|                                                                                                                                                                                        |                                                                                             | Code : FCI2                |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                             |                            |                                                                                     |  |
| Insured Veh.                                                                                                                                                                           | SHB 3623C                                                                                   | Veh. Inspected             | SBR 2448K                                                                           |  |
| Policy No.                                                                                                                                                                             |                                                                                             | Coverage (\$)              | 0.00                                                                                |  |
| Claim No.                                                                                                                                                                              | D18004277MFSH                                                                               | Excess (\$)                | 0.00                                                                                |  |
| Assign From                                                                                                                                                                            | SITHARA                                                                                     | Assign Date                | 05/06/2018                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                             |                            |                                                                                     |  |
| Make & Model                                                                                                                                                                           | VOLKSWAGEN PASSAT CC (A)                                                                    | c.c                        | 1798                                                                                |  |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                      | Year of Reg.               | 2011                                                                                |  |
| Chassis No.                                                                                                                                                                            | WWWZZZ3CZBE749831                                                                           | Colour                     | BLACK                                                                               |  |
| Odometer                                                                                                                                                                               | 200227                                                                                      | Steering                   | IN ORDER                                                                            |  |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                    | Modification               | SPORTS RIM                                                                          |  |
| General                                                                                                                                                                                | GOOD                                                                                        |                            |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                             |                            |                                                                                     |  |
|                                                                                                                                                                                        | Size                                                                                        | Make                       | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                                                                         | 235/45 R17                                                                                  | CONTINENTAL                | 7 mm                                                                                |  |
| L/H Front Tyre                                                                                                                                                                         | 235/45 R17                                                                                  | CONTINENTAL                | 7 mm                                                                                |  |
| R/H Rear Tyre                                                                                                                                                                          | 235/45 R17                                                                                  | CONTINENTAL                | 7 mm                                                                                |  |
| L/H Rear Tyre                                                                                                                                                                          | 235/45 R17                                                                                  | CONTINENTAL                | 7 mm                                                                                |  |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                             |                            |                                                                                     |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS.                                                                                                                 |                                                                                             |                            |                                                                                     |  |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                             |                            |                                                                                     |  |
| Accident Date                                                                                                                                                                          | 27/05/2018                                                                                  | Inspection Date            | 11/06/2018                                                                          |  |
| Survey held at                                                                                                                                                                         | SME MOTOR PTE LTD<br>1 KAKI BUKIT AVE 6<br>#02-15 (AUTOBAY @KAKI BUKIT)<br>SINGAPORE 417883 |                            |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                             |                            |                                                                                     |  |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                             |                            |                                                                                     |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                             |                            |                                                                                     |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                             | <b>5 Working Days</b>      |                                                                                     |  |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBR 2448K

| Qty                         | Description of Parts                       | Condition                      | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--------------------------------------------|--------------------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                            |                                |                           |                   |
| 1                           | LH SIDE MIRROR SIGNAL LAMP (SCRATCHED)     | NOT CONSISTENT WITH THE IMPACT | 75.00                     | -                 |
| 1                           | FRT LH DOOR                                | BADLY DENTED                   | 2,681.50                  | 2,296.99          |
| 1                           | FRT LH DOOR LOCK                           | NOT NECESSARY                  | 412.50                    | -                 |
| 1                           | FRT LH DOOR PROTECTOR (CHROME)             | BENT                           | 197.90                    | 197.90            |
| 1                           | FRT LH DOOR OUTER HANDLE                   | NOT NECESSARY                  | 750.00                    | -                 |
| 1                           | FRT LH DOOR GLASS REAR                     | NOT NECESSARY                  | 650.00                    | -                 |
| 1                           | FRT LH DOOR POWER WINDOW MOTOR             | NOT NECESSARY                  | 1,250.00                  | -                 |
| 1                           | FRT LH DOOR INNER TRIM BOARD               | NOT NECESSARY                  | 1,690.00                  | -                 |
| 8                           | FRT LH DOOR INNER TRIM BOARD CLIP          | NOT NECESSARY                  | 40.00                     | -                 |
| 1                           | REAR LH DOOR                               | DENTED / BENT                  | 1,625.00                  | 1,625.00          |
| 1                           | REAR LH DOOR PROTECTOR (CHROME)            | SCRATCHED                      | 197.90                    | 197.90            |
| 1                           | REAR LH SHOCK ABSORBER                     | NOT NECESSARY                  | 550.00                    | -                 |
| 1                           | REAR LH WHEEL HUB                          | NOT NECESSARY                  | 650.11                    | -                 |
| 1                           | REAR BUMPER                                | DEEP CUT                       | 1,895.70                  | 1,895.70          |
| 1                           | REAR BUMPER RETAINER LH                    | BENT                           | 95.00                     | 95.00             |
| 10                          | REAR BUMPER CLIP                           | NECESSARY                      | 50.00                     | 50.00             |
| 2                           | REAR BUMPER MOULDING (SIDES)               | N/S SCRATCHED                  | 575.00                    | 287.50            |
| 1                           | REAR BUMPER MOULDING CENTER                | NOT NECESSARY                  | 295.90                    | -                 |
| 1                           | LH CENTER PILLAR                           | TO REPAIR SEE LABOUR           | 3,000.90                  | -                 |
| 1                           | REAR LH DOOR RUBBER (AT DOOR) (ADDITIONAL) | NECESSARY                      | 287.50                    | 287.50            |
| 1                           | SIDE SKIRTS LH (ADDITIONAL)                | DEFORMED / WARPED              | 920.10                    | 920.10            |
| 1                           | FRT LH DOOR INNER RUBBER (ADDITIONAL)      | NECESSARY                      | 242.90                    | 242.90            |
| 1                           | LH SIDE SKIRTS BRACKET (FRT) (ADDITIONAL)  | DISTORTED                      | 162.50                    | 162.50            |
| 7                           | LH SIDE SKIRTS BRACKET CLIPS (ADDITIONAL)  | NECESSARY                      | 38.50                     | 38.50             |
|                             | LESS 10% DISCOUNT                          |                                | -1,833.39                 | -829.75           |
|                             |                                            |                                | 16,500.52                 | 7,467.74          |
| 1                           | REAR LH SPORT RIM (SN)                     | CUT                            | 1,800.00                  | 800.00            |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                | Description of Parts                                        | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                    | LESS 10% DISCOUNT                                           |               | -180.00                   | -                 |
|                                    |                                                             |               | 1,620.00                  | 800.00            |
|                                    | <b>LABOUR</b>                                               |               |                           |                   |
|                                    | WIRE CHECKING.                                              |               | 50.00                     | 20.00             |
|                                    | REMOVE & REFIX REAR UNDERCARRIAGE.                          | NOT NECESSARY | 200.00                    | -                 |
|                                    | 4 WHEEL ALIGNMENT.                                          |               | 65.00                     | 60.00             |
|                                    | WHEEL BALANCING.                                            | NOT NECESSARY | 25.00                     | -                 |
|                                    | REMOVE & REFIX CUSHION AND SEATS.                           |               | 150.00                    | 80.00             |
|                                    | TRANSFER 2 DOORS COMPONENTS FROM OLD TO NEW.                |               | 250.00                    | 160.00            |
|                                    | LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF LH CENTER PILLAR. |               | 950.00                    | 800.00            |
|                                    | SPRAY PAINTING.                                             |               | 900.00                    | 880.00            |
|                                    | REPAIR LH DOOR PILLAR. (ADDITIONAL)                         | NOT NECESSARY | 200.00                    | -                 |
|                                    | SPRAY LH DOOR PILLAR. (ADDITIONAL)                          |               | 150.00                    | 100.00            |
|                                    |                                                             |               | 2,940.00                  | 2,100.00          |
|                                    | <b>GRAND TOTAL</b>                                          |               | <b>21,060.52</b>          | <b>10,367.74</b>  |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                             |               |                           | <b>10,367.74</b>  |

Report Ref No. CS/FC18010198/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.