

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 07 Jun 2018

Preliminary Advice

Vehicle No	: SKW8773Z	Accident Date	: 26/05/2018
Make	: VOLKSWAGEN GOLF A7	Policy No.	: A28634600AVW
Assignment Date	: 05/06/2018	Excess	: S\$500.00
Date of Inspection	: 07/06/2018	Est. Duration of Repair	: 8 days
Inspection At	: Volkswagen Centre Singapore - Tuas (HQ) 17 TUAS AVE 9 Singapore 639197		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,163.82
Revised Amount	:S\$	7,812.25
Check Items (Estimated)	:S\$	7,531.56
Total	:S\$	15,343.81
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	77,000.00
COE / PARF Rebate	:S\$	52,618.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,382.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.