



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JAMES ONG KAY SIANG
BLK 10P BRADDELL HILL
#03-67
SINGAPORE 579733

Estimate No: MC0913149
Date: 05 Jun 2018
Policy No: MT/00045111/06
Veh Reg No: SJB3458P
Make/Model: HONDA CIVIC 1.8L A

ATTN:
Your Ref No: SJB3458P
Claim Type: Third Party
Accident Date: 04/06/2018
TP Veh Reg No: SLX7073A

Estimate Repair Cost to Vehicle No :SJB3458P

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT	1 PC	610.70	
2 REAR BOOT HINGE LH & RH	2 PC	97.20	
3 REAR BOOT EMBLEM	1 PC	25.70	
4 REAR BOOT CIVIC LOGO	1 PC	29.10	
5 REAR BOOT I-VTEC LOGO	1 PC	34.10	
6 REAR BOOT LAMP LH & RH	2 PC	291.80	
7 REAR BOOT NO PLATE LAMP LH & RH	2 PC	36.00	
8 REAR BOOT NO PLATE GARNISH	1 PC	121.60	
9 REAR BOOT OUTER LOCK CYLINDER	1 PC	97.20	
10 REAR BOOT RUBBER	1 PC	97.60	
11 REAR BOOT INSULATOR	1 PC	133.70	
12 REAR BOOT INSULATOR CLIPS	10 PC	35.00	
13 REAR BOOT INNER LOCK	1 PC	194.50	
14 REAR BOOT INNER LOCK STRIKER	1 PC	27.50	
15 TAILAMP LH & RH	2 PC	452.40	
16 TAILAMP PANEL LH & RH	2 PC	131.40	
17 REAR BUMPER	1 PC	638.00	
18 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	29.20	
19 REAR BUMPER CLIPS	15 PC	58.50	
20 REAR BUMPER BRACKET LH & RH	2 PC	27.80	
21 REAR BUMPER MUDFLAP LH & RH	2 PC	149.80	
22 REAR END PANEL	1 PC	300.50	
23 REAR END PANEL TOP GARNISH	1 PC	56.10	
24 SPARE TYRE PANEL	1 PC	992.00	
25 SPARE TYRE PANEL TOP TRIMBOARD	1 PC	316.00	
26 TOOLBOX	1 PC	46.80	
27 SPARE TYRE BRACKET BOLT	1 PC	10.00	
28 SPARE TYRE HOLDER ADAPTER	1 PC	9.00	
29 REAR FENDER INNER TRIM LH & RH	2 PC	291.80	
30 REAR FENDER INNER TRIM CLIPS	20 PC	90.00	
31 REAR EXHAUST PIPE	1 PC	535.00	
32 REAR EXHAUST PIPE CHROME LH & RH	2 PC	197.40	
33 REAR EXHAUST PIPE MOUNTING	4 PC	66.00	
34 REAR EXHAUST PIPE TOP HEAT SHIELD	1 PC	43.80	
		6,273.20	
	Less 20%	1,254.64	5,018.56

Special Nett





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JAMES ONG KAY SIANG
BLK 10P BRADDELL HILL
#03-67
SINGAPORE 579733

Estimate No: MC0913149
Date: 05 Jun 2018
Policy No: MT/00045111/06
Veh Reg No: SJB3458P
Make/Model: HONDA CIVIC 1.8L A

ATTN:
Your Ref No: SJB3458P
Claim Type: Third Party
Accident Date: 04/06/2018
TP Veh Reg No: SLX7073A

Estimate Repair Cost to Vehicle No :SJB3458P

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
35 NUMBER PLATE	1 PC	35.00	
36 REVERSE SENSOR	1 SET	200.00	
37 SPARE TYRE - CHECK PRICE	1 PC	0.00	
38 SPARE TYRE RIM - CHECK PRICE	1 PC	0.00	
		235.00	235.00
LABOUR			
39 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
40 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	
41 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	
42 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	350.00	
43 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	
44 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	120.00	
45 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00	
46 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,SPARE TYRE PANEL,TAILAMP PANEL LH & RH.TO KNOCK & REPAIR REAR FENDER LH & RH,REAR CHASSIS LH & RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,600.00	
47 TO SPRAY REAR BOOT,REAR BUMPER,END PANEL, SPARE TYRE PANEL,REAR FENDER LH & RH,TAILAMP PANEL LH & RH,REAR CHASSIS LH & RH.	1 PC	1,600.00	
		4,130.00	4,130.00
Total			S\$ 9,383.56
Add GST @ 7%			656.85
Total Amount Payable			S\$ 10,040.41

TOTAL: SINGAPORE DOLLAR TEN THOUSAND FORTY AND CENTS FORTY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	3751A

Vehicle Details

Vehicle No.:	SJB3458P
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L A
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	R18A13017394
Chassis No.:	JHMFD16308S210705
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,899.00
Original Registration Date:	09 Jan 2008
First Registration Date:	09 Jan 2008
Transfer Count:	2
Actual ARF Paid:	\$22,989.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	08 Jan 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$26,136.00
COE Rebate Amount:	\$24,014.00
Total Rebate Amount:	\$24,014.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Jun 2018

OK