

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
(Email Adress : woonmeng @singnet.com.sg)
Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : First Capital Insurance Ltd
Motor Claims Dept

Date : 13 Jun 2018

Dear Sirs :

Fax : 6507 3849

RE : ESTIMATE COST FOR NISSAN E25 - GBC3509R ACCIDENT INVOLVING GBC3509R & SHD4858A ON 03/02/2018

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper	1pc	\$ 632.70
2	Rear bumper retainer @\$15each	2pcs	\$ 30.00
3	Rear lamp o/s.	1pc	\$ 208.70
			\$ 871.40
Less 30%			\$ (261.42)
			\$ 609.98
4	Rear bumper sensor.	1set	\$ 220.00
Sum Carried Forward			
			\$ 829.98

Sum Carried Forward		\$ 829.98
<u>Labour Charge & Misc</u>		
To remove, repair, replace & install front damaged parts.	} }	\$ 600.00
To numbering logo.		\$ 350.00
To remove logo		\$ 250.00
To R & R sensor/ light wiring		\$ 80.00
To putty & spray painting.		\$ 700.00
Total		\$ 2,809.98

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.