

ASS. REC. BY:

REF: CS/FCI 18010298/ Rlyd3ⁿ² Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

AWS

From (Person):

Eileen Lee

of

FCI

Date/Time: 6/6/18 @ 12:50pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 3509R

Insured:

SHD 4858A

at Workshop m/s:

Woon Meng Motor

Tel:

63161311

of

50 Bukit Batok St. 23 # 01-06

Policy No:

Claim No:

D18001104MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 03/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS^{1up}

H.O.D. Endorsement:

Date/Time:

2:15pm @ 6/6/18

Person Contacted:

Mrs. Heng

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBC 3509R-X

SHD 4858A-X

13/6/18

Informed FCI pending workshop est by email

9/7/18

Rasul confirmed LS \$1400 (Red 1409.98, 50%)

9/7/18

Email preti. revised to FCI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBC 3509Rat Workshop m/s Woon menhof 50, Parker Barron Cars #01-06Insured: FCI

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBC 3509R Yr Regn: 2012 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN URVAN 3.0 SAT C.C. 2953Colour: MULTI A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1M64E2520796916Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195R15C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 03/02/18 D.O.I. 12/04/18Survey held at Woon menh

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

[Signature]
9/7/2018

RECEIVED 10 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

1) 10/7 - typistReport Format: CWSLump Sum / I.B.I. (\$) 1400/2Days Of Repair: 4Resurvey No. of Trip: -Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

110

50

22

182



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18010298/R1vd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-06-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4858A	Veh. Inspected	GBC 3509R
Policy No.		Coverage (\$)	0.00
Claim No.	D18001104MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	06/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/02/2018	Inspection Date	
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001104MFSH
Our Ref: CS/FCI18010298/R1vd3

Date : 9/7/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. GBC 3509R


We thank you for your instruction on 6/6/2018

Please be informed that we had conducted the inspection of the above mentioned
12/6/2018 at the premises of M/s WOON MENG MOTOR PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$2,809.98
Revised Estimate Amount	: S\$1,769.98
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-02-2018	Our Ref No. D18001104MFSH
Accident Date	03-02-2018	Claim Type. Third Party
Insured Vehicle	SHD4858A	Third Party Vehicle. GBC3509R
Survey Location	50 BUKIT BATOK STREET 23 #01-06 MILDVIEW BUILDING	
Contact Person.	NA	
Contact No.	63161311/ 0	Fax No. 63167050
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WOON MENG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234710)



PRI Documents



Close



PRI Header Details

Claim No	D18001104MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & WOON ME
Workshop Name	WOON MENG MOTOR PTE LTD (Contact Person : NA)	Survey Location & Contact Details	50 BUKIT BATOK STREET 23 #01-06 MILDVIEW BUILDING Mobile: 0 , Phone: 63161311 , Fax: 63167050 EmailId: WOONMENG@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4858A	TP Vehicle No	GBC3509R
PRI Recieved Date	05-06-2018 05:14:10 PM	Surveyor Appointed Date	06-06-2018 12:49:22 PM	Surveyor Accept Date	06-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-06-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 9 July 2018 2:36 PM
To: 'Claim Workflow System'
Cc: 'EILEENLEE@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18001104MFSH/1, GBC 3509R
Attachments: GBC 3509R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GBC 3509R
Date of survey: 12/6/2018
Number of days :4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 13 June 2018 2:05 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001104MFSH/1, GBC 3509R

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBC 3509R on 12/6/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 6 June 2018 2:16 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001104MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Wednesday, 6 June 2018 12:49 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18001104MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 13 June 2018 2:05 PM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001104MFSH/1, GBC 3509R

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBC 3509R on 12/6/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 6 June 2018 2:16 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001104MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 6 June 2018 12:49 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001104MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Heng Sew Sow <woonmeng@singnet.com.sg>
Sent: Tuesday, 19 June 2018 11:23 AM
To: SUR; Rasul (LKKAUTO)
Cc: Admin A
Subject: Accident involving GBC3509R & SHD4858A ON 03.02.18
Attachments: 20180619111429.pdf

Dear Sir/Madam

Attached estimate for your reference.

Best Regards,
Heng Sew Sow (Ms)
Woon Meng Motor Pte Ltd
Tel: 6316 1131/51
Fax: 6316 7050

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
(Email Address : woonmeng @singnet.com.sg)
Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : First Capital Insurance Ltd
Motor Claims Dept

Date : 13 Jun 2018

Dear Sirs :

Fax : 6507 3849

RE : ESTIMATE COST FOR NISSAN E25 - GBC3509R
ACCIDENT INVOLVING GBC3509R & SHD4858A ON 03/02/2018

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper	1pc	\$ 632.70 <i>see</i>
2	Rear bumper retainer @\$15each	2pcs	\$ 30.00 <i>na</i>
3	Rear lamp o/s.	1pc	\$ 208.70 <i>CR</i>
			\$ 871.40
			\$ (261.42)
	Less 30%		\$ 609.98 <i>609.98</i>
4	Rear bumper sensor.	1set	\$ 220.00 <i>X AN</i>
	Sum Carried Forward		\$ 829.98

Sum Carried Forward**\$ 829.98****Labour Charge & Misc**

To remove, repair, replace & install front damaged parts.

} }

\$ ~~600.00~~ 350

To numbering logo.

\$ ~~350.00~~ 200

To remove logo

\$ ~~250.00~~ 150

To R & R sensor/ light wiring

\$ ~~80.00~~ 60

To putty & spray painting.

\$ ~~700.00~~ 400**Total****\$ 2,809.98**

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasm
Hp 90010068

4 days

4s

12/06/18 @ 1630

Resurvey after repair

609.98
1160.00
1769.9820%
1415.98

415.1400

4 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010298/R1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4858A	Veh. Inspected	GBC 3509R	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001104MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	06/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN URVAN 3.0 5MT	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JN1MG4E25Z0796916	Colour	MULTI	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	6 mm	
L/H Front Tyre	195 R15C	MICHELIN	6 mm	
R/H Rear Tyre	195 R15C	MICHELIN	6 mm	
L/H Rear Tyre	195 R15C	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/02/2018	Inspection Date	12/06/2018	
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 3509R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	SCRATCHED	632.70	632.70
2	REAR BUMPER RETAINER @\$15.00	NECESSARY	30.00	30.00
1	REAR LAMP O/S	CRACKED	208.70	208.70
	LESS 30% DISCOUNT		-261.42	-261.42
			609.98	609.98
SPECIAL NETT ITEMS				
1	SET REAR BUMPER SENSOR (SN)	NOT NECESSARY	220.00	-
			220.00	-
LABOUR				
	TO REMOVE,REPAIR,REPLACE & INSTALL FRONT DAMAGED PARTS.		600.00	350.00
	TO NUMBERING LOGO.		350.00	200.00
	TO REMOVE LOGO.		250.00	150.00
	TO R&R SENSOR/LIGHT WIRING.		80.00	60.00
	TO PUTTY & SPRAY PAINTING.		700.00	400.00
			1,980.00	1,160.00
GRAND TOTAL			2,809.98	1,769.98
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS/FCI18010298/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.