

ESTIMATE TO REPAIR

VEHICLE NO. : SLR 9687 Y
 MAKE : TOYOTA
 MODEL : VIOS E AUTO
 YEAR : 2008
 CHASSIS NO : MR053HY9305072404

SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

DATE : 5-Jun-18
 DATE OF ACCIDENT : 28-May-18
 THIRD PARTY REF : SFX 57 P / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 538.40
1 pc	Rear Bumper Lower Spoiler				\$ 525.40
2 pcs	Rear Bumper Retainer		\$ 87.40		\$ 174.80
1 pc	Rear End Panel				\$ 658.16
1 pc	Rear Boot VIOS Emblem				\$ 78.70
1 pc	Rear Boot E SPORTS Emblem				\$ 75.40
					\$ 2,050.86
	Less 25%				\$ 512.72
					\$ 1,538.15
1 set	Rear Bumper Reverse Sensor	S.Nett			\$ 200.00
	To putty & spray painting.				\$ 700.00
	To anti rust.				\$ 50.00
	Labour Charges.				\$ 600.00
TG-RA/-	TOTAL				\$ 3,088.15

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0