

15/5/2011

INS. CASE OWNER:

CC 6/AIG1801 0227, Uub322

LKK:  
IDAC:

Surveyor:

Marius

DOI:

ASSIGNMENT

Date / Time :

6/6/18

Registered in Merimen:

6/6/18

Pre-assign / CCU / FTE



Insured Vehicle No. :

SET 6110R

Name of Insured :

YAP TIONG PENH.

Insured Tel No. :

HP:

20/4/18

Excess Sec II : \$

D.O.A. :

Is driver the owner? ( YES / NO )

Nature of Accident :

If NO, Driver Name / Age : MARINE LEE MEI FOON.

Driver Tel No. :

(V/L: YES / NO )

Claim No. :

44557694154

Policy No. :

20046137-0000

Make / Model :

AUDI

Place of Accident :

JUN OF OUTERMED APTEK.  
LANTANMENT COMPLEX

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SLS 4771E

INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Pennisus


INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/ Time :

8/6/18  
TH

SLS 4771E - X  
SET 6110R - 44557694154 / 20046137-0000 / 20/4/18

Rejected. OZ travelling with his own  
lane TP change lane based on footage  
(marked footage)  
in Merimen



RECEIVED 10 SEP 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

\$

Loss of Rental (LOR):

\$

(

days)

Loss of Use (LOU):

\$

(\$

x

days)

Loss of Income (LOI):

\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

\$

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent )

Legal Cost

\$

Total:

\$

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

Name 1:

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320.00

COPY SENT  
18/9/18

REF:

A14

## ASSIGNMENT

From: Date: 06062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS 1731E

at Workshop m/s:

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

PR. Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLS 4731E Yr Regn: 9 17

Type: Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

6/6/18 confirmed final by \$600 with Gary

\$600.00 + (Red: \$300.00/ 33%)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.F. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Week-end (\$

Survey Fee:

Transportation:

S + R (\$)

Photos

Others

TOTAL




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC6/AIG18010327/Uub3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 06-06-2018	
			Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKT 6110R	Veh. Inspected	SLS 4731E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	06/06/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	20/04/2018	Inspection Date	06/06/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



GST / ROC Company No : 201101753C

Third Party Insurer : AIG

Insured's Veh No : SLS4731E

Date of accident : 20/04/2018

Grab Rentals Pte Ltd  
18 Sin Ming Lane  
#01-08 Midview City  
Singapore 573960

Quotation No : AR/QO18/04-1070

Quotation Date : 20/04/2018

Estimate To Repair TOYOTA PRIUS

Vehicle No : SLS4731E

Chassis No :

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
1		<b>LABOUR &amp; MISC. CHARGES</b>	
		REPAIR 2 DOOR RH	\$400.00
2		PAINT 2 DOOR RH + SIDE SKIRT RH	\$500.00
		Total	\$900.00
<i>not follow LKR take photo after repair 2 day 6/6/18 p/p \$600</i>			
Sub Total			#REF!
GST (7.00%)			#REF!
Total			#REF!

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418

## Thin Thin (LKKAUTO)

---

**From:** Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>  
**Sent:** Wednesday, 29 August 2018 9:02 AM  
**To:** Thin Thin (LKKAUTO)  
**Subject:** RE: Your Ref: 4455369411SG; Our Ref: CC6/AIG18010327/Uub3 [ACCIDENT ON 20/04/2018 INVOLVING VEHICLES SKT 6110R AND SLS 4731E]

Hi Thin Thin,

Agreed with your assessment. Please proceed to reject TPPD claim accordingly.

Thanks.

**Best Regards,**

Bernard Ler  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946 | Fax +(65) 6835 7416

[Bernard-JQ.Ler@aig.com](mailto:Bernard-JQ.Ler@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Thin Thin (LKKAUTO) [mailto:thinthin@lkkauto.com]  
**Sent:** 28 August 2018 8:51 PM  
**To:** Ler, Bernard-JQ  
**Subject:** Your Ref: 4455369411SG; Our Ref: CC6/AIG18010327/Uub3 [ACCIDENT ON 20/04/2018 INVOLVING VEHICLES SKT 6110R AND SLS 4731E]

Your Ref: 4455369411SG  
Our Ref: CC6/AIG18010327/Uub3

Dear Bernard,

ACCIDENT ON 20/04/2018 INVOLVING VEHICLES SKT 6110R AND SLS 4731E

We refer to the above matter.

TP reported that he was driving along Outram road on the left most lane and suddenly OI from right lane come into his lane and collided onto his vehicle.

OI reported that he was driving straight and slowly. Suddenly TP side swipe to his vehicle.

Meanwhile, we had requested the evidence from TP. However, TP do not have any evidence to support their client's version.

After reviewing video footage from insured and report from parties, we are of opinion that our insured was travelling along within in his lane and TP encroached into our insured lane..

As such, we intend to reject the claim and kindly let us have your instruction / approval please.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Thin Thin (LKKAUTO)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Friday, 14 September 2018 5:36 PM  
**To:** 'Pegasus Engineering'  
**Subject:** RE: Acc Inlv SLS4731E & SKT6110R on 20/04/2018 \*\*\*LKK REF:CC6/AIG18010327/ub3  
**Attachments:** Video - Accident.mp4

Without Prejudice,

Dear Ying,

We refer to the below matter.

Our insured has reiterated that the accident was caused due to the negligence of your client.

Based on video footage, it can be seen that our insured vehicle was travelling along within in his own lane and your client's vehicle cut into our insured lane and collided with our insured vehicle.

Under such a circumstances, we are denying liability and unable to look into your client's claim.

Yours faithfully,

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Pegasus Engineering <claims2@pegasusengrg.com.sg>  
**Sent:** Wednesday, 29 August 2018 10:07 AM  
**To:** Thin Thin (LKKAUTO) <thinthin@lkkauto.com>  
**Subject:** Re: Acc Inlv SLS4731E & SKT6110R on 20/04/2018 \*\*\*LKK REF:CC6/AIG18010327/ub3

Hi Thin Thin,

Please be informed, there was no camera / video footage in our client's vehicle.

Thanks & regards  
YING

On Tue, Aug 28, 2018 at 8:25 PM, Thin Thin (LKKAUTO) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)> wrote:

Hi Sebastian,

We understand that there is CCTV in your client's vehicle.

We would like to request the video footage for our necessary action.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Pegasus Engineering <[claims2@pegasusengrg.com.sg](mailto:claims2@pegasusengrg.com.sg)>

**Sent:** Monday, 27 August 2018 2:13 PM

**To:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>

**Subject:** Re: Acc Inv SLS4731E & SKT6110R on 20/04/2018 \*\*\*LKK REF:CC6/AIG18010327/ub3

Hi Thin Thin,

Any update.

Thank you

Sebastian



On Mon, Aug 20, 2018 at 2:52 PM, Pegasus Engineering <[claims2@pegasusengrg.com.sg](mailto:claims2@pegasusengrg.com.sg)> wrote:

hi Thin Thin,

Any update for this case??

Kindly advise..

thanks

ying

On Sat, Jul 14, 2018 at 9:51 AM, Pegasus Engineering <[claims2@pegasusengrg.com.sg](mailto:claims2@pegasusengrg.com.sg)> wrote:

Hi Thin Thin,

Any update on the CCTV footage ?

Thank you

Best Regards,

Sebastian

On Wed, Jun 27, 2018 at 11:50 AM, Thin Thin (LKKAUTO) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)> wrote:

Dear Sebastian,

We are seeking further instruction from our Principal and will revert back to you.

Meanwhile, we would like to request the CCTV footage / accident scene photos / PIR result / evidence in order to support your client's statement.

Thanks.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Pegasus Engineering [mailto:[claims2@pegasusengrg.com.sg](mailto:claims2@pegasusengrg.com.sg)]

**Sent:** Wednesday, 27 June 2018 11:45 AM

**To:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>

**Subject:** Re: Acc Inlv SLS4731E & SKT6110R on 20/04/2018 \*\*\*LKK REF:CC6/AIG18010327/ub3

Hi Thin Thin,

Can you provide us your insured scene video? Your insured mention in the report "our car has in-car camera".

Thank you

Best Regards,

Sebastian

On Wed, Jun 27, 2018 at 11:01 AM, Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)> wrote:

"Without Prejudice"

Hi Sebastian,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is unclear for the above mentioned case. There is no conclusive evidence to substantiate either party's version. Enclosed herewith is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request the CCTV footage / accident scene photos / PIR result / evidence in order to seek further instruction from our principal.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Pegasus Engineering [mailto:[claims2@pegasusengrg.com.sg](mailto:claims2@pegasusengrg.com.sg)]

**Sent:** Wednesday, 27 June 2018 10:37 AM

**To:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>

**Subject:** Re: Acc Inv SLS4731E & SKT6110R on 20/04/2018 \*\*\*LKK REF:CC6/AIG18010327/ub3

Hi Thin Thin,

Please advise liability.

Thank you

Best Regards,

Sebastian

On Wed, Jun 6, 2018 at 5:15 PM, Shu Pei (LKKAuto) <[shupeil@lkkauto.com](mailto:shupeil@lkkauto.com)> wrote:

Dear Gary,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Kindly note that for liability, claim negotiation and settlement, please contact Thin Thin at 6841 2360.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

*To check availability of the case handler , you may contact the undersigned.*

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupei@lkkauto.com](mailto:shupei@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)

**Sent:** Wednesday, 6 June 2018 3:56 PM

**To:** 'Pegasus Engineering' <[claims2@pegasusengrg.com.sg](mailto:claims2@pegasusengrg.com.sg)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Subject:** FW: Acc Inlv SLS4731E & SKT6110R on 20/04/2018

Dear Gary,

Thank you for your email.

Dear Shu Pei,

Kindly assist. (new case)

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Pegasus Engineering [<mailto:claims2@pegasusengrg.com.sg>]

**Sent:** Wednesday, 6 June, 2018 3:48 PM

**To:** Catherine Chong (LKK Auto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Subject:** Acc Inlv SLS4731E & SKT6110R on 20/04/2018

Hi Catherine,

Our Ref : SLS 4731 E

Your Ref : SKT 6110 R

Please advise liability.

Thank you

--

Best Regards,

Gary Seah

Pegasus @ SME Motor

Hp: 83388418

--

Best Regards,

Gary Seah

Pegasus @ SME Motor

Hp: 83388418

--

Best Regards,

Gary Seah

Pegasus @ SME Motor

Hp: 83388418

--  
Best Regards,

Gary Seah

Pegasus @ SME Motor

Hp: 83388418

--  
Best Regards,

Gary Seah

Pegasus @ SME Motor

Hp: 83388418

--  
Best Regards,

Gary Seah

Pegasus @ SME Motor

Hp: 83388418

--  
Best Regards,

Gary Seah

Pegasus @ SME Motor

Hp: 83388418

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2018 <a href="#">Edit Reg</a>		06 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$600.00</b> <a href="#">Edit Estimates</a>	<b>S\$600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	YAP TIONG PENG, ID: S7836126C, Tel: +6591293915		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLS4731E	Date of Loss:	20/04/2018 12:00 - :59 [6 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4455369411SG	Policy/Cover Note No.:	2100416177 (Comprehensive)
Vehicle Reg. No. (Insured):	SKT6110R	Policy No. (Claimant):	A29069766MKF
		Excess:	
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 18/06/2018]		
Driver/Custodian (Insured):	CAROLINE LEE MEI FOONG (), NRIC: S7619468H		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





## Claim Documents

**\*SLS4731E (4455369411SG)**  
**[SKT6110R]**

**TP**

**GRAB RENTALS PTE LTD**

**Apr 20 2018 12:00PM**

**[YAP TIONG PENG]**

**Pegasus Engineering & Trading Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Video</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/06/18 10:27	<b>Video - Accident</b> From: OD - Reg. No: SKT6110R, Claimant: YAP TIONG PENG	Load MP4	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/06/18 10:27	<b>Accident Statement</b> From: OD - Reg. No: SKT6110R, Claimant: YAP TIONG PENG	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
2	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
3	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
4	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
5	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
6	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
7	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
8	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
9	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
10	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
11	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
12	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
13	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
14	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
15	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
16	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
17	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
18	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
19	28/08/18 20:26	<b>Front View Right</b>	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/18 17:13	<b>TP GIA REPORT</b>	Load PDF	
2	07/06/18 19:13	<b>TP ESTIMATE- MARKED</b>	Load PDF	
3	14/09/18 18:25	<b>INSTRUCTION FROM AIG</b>	Load PDF	
4	14/09/18 18:25	<b>Reject email to TP</b>	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/06/18 12:00	<b>OI GIA REPORT</b>	Load PDF	

# Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18010327/UUB3S2

Date: 21/09/2018

## REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100416177
Claimant Vehicle No :	SLS4731E	Insured Vehicle No :	SKT6110R
Date of Loss:	20/04/2018	Nature of Claim:	TP
		Claim No:	4455369411SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SLS4731E</b>	Engine No:	2ZRS090010
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 (A)	Chassis No:	JTDKB3FU403571231
Reg. Date:	26/09/2017 (Man. Year: 2017)	Odometer:	39854 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Gremax 6 mm	Rear Left Side:	Gremax 6 mm
Front Right Side:	Gremax 6 mm	Rear Right Side:	Gremax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	600.00	300.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>900.00</b>	<b>600.00</b>	<b>300.00</b>	<b>33.33</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>63.00</b>	<b>42.00</b>	<b>21.00</b>	<b>33.33</b>
<b>Nett Amount (S\$)</b>	<b>963.00</b>	<b>642.00</b>	<b>321.00</b>	<b>33.33</b>

## INSPECTION

Date of Assignment:	06/06/2018		
Date Inspected:	06/06/2018	Inspected At:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10 Singapore 539216
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPAIR 2 DOOR RH.	New	400.00	200.00
2	PAINT 2 DOOR RH + SIDE SKIRT RH.	New	500.00	400.00
Gross Labour Cost (S\$)			900.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >