



GST / ROC Company No : 201101753C

Third Party Insurer : AIG

Insured's Veh No : SLS4731E

Date of accident : 20/04/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Quotation No : AR/QO18/04-1070

Quotation Date : 20/04/2018

Estimate To Repair TOYOTA PRIUS

Vehicle No : SLS4731E

Chassis No :

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
		LABOUR & MISC. CHARGES	
1		REPAIR 2 DOOR RH	\$400.00
2		PAINT 2 DOOR RH + SIDE SKIRT RH	\$500.00
		Total	\$900.00
		<i>not allowed</i> <i>take photo after repair</i> <i>2 day</i> <i>6/6/18</i> <i>plp \$600</i>	
		Sub Total	#REF!
		GST (7.00%)	#REF!
		Total	#REF!

LKF Auto Consultants hence notify the insurer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418