

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

SCM 8034 X

SUPP 2

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES1890626/YISHUN

Date: 22 Jun 2018

Policy No: 5059034762-05

Veh Reg No: SCM8034X

Make/Model: TOYOTA ESTIMA  
AERAS HYBRID 2.4 A

Chassis No: AHR207064710

Engine No: 2AZH890640

Reg. Date: 14/11/2012

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 06/06/2018

TP Veh Reg No: SHC7292S

## Estimate Repair Cost to Vehicle No :SCM8034X

| Description          | U/Price | Quantity | List Price | Amount     |
|----------------------|---------|----------|------------|------------|
|                      |         |          | <u>S\$</u> | <u>S\$</u> |
| Supplementary 2      |         |          |            |            |
| Special Net          |         |          |            |            |
| 1 REVERSE CAMERA     | 380.00  | 1 SET    | 380.00     | 380.00     |
|                      |         |          | 380.00     | 380.00     |
| Total                |         |          |            | S\$ 380.00 |
| GST Amount           |         |          |            | S\$ 26.60  |
| Total Amount Payable |         |          |            | S\$ 406.60 |

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

SCM 8034x  
SUPP 1

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES1890626/YISHUN

Date: 13 Jun 2018

Policy No: 5059034762-05

Veh Reg No: SCM8034X

Make/Model: TOYOTA ESTIMA  
AERAS HYBRID 2.4 A

Chassis No: AHR207064710

Engine No: 2AZH890640

Reg. Date: 14/11/2012

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 06/06/2018

TP Veh Reg No: SHC7292S

## Estimate Repair Cost to Vehicle No :SCM8034X

| Description                      | U/Price | Quantity | List Price | Amount     |
|----------------------------------|---------|----------|------------|------------|
|                                  |         |          | <u>S\$</u> | <u>S\$</u> |
| Supplementary 1                  |         |          |            |            |
| List Price                       |         |          |            |            |
| 1 REAR PANEL INNER GARNISH LOWER | 197.00  | 1 PC     | 197.00     |            |
|                                  |         |          | 197.00     |            |
|                                  |         | Less 25% | 49.25      | 147.75     |
| Total                            |         |          |            | S\$ 147.75 |
| GST Amount                       |         |          |            | S\$ 10.34  |
| Total Amount Payable             |         |          |            | S\$ 158.09 |

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE