

(SUPPLEMENTARY)

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	PNPV2018-00000121	Date of Loss:	04/06/2018
Vehicle Reg. No.:	SJZ9337P	Driveable?	
Driver Age/Info:	43 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	ADRIAN SIEW MING WAI		
Driver:	KUA YAH LAY		
Make/Model:	HONDA ODYSSEY, 2.4 (A)	Vehicle Reg. Date:	07/01/2011
Vehicle Colour:	Silver		
Engine No:	K24Z21301041	Chassis No:	JHMRB38309C201037
Odometer:	143349 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 12

Description of Accident/Loss REFER TO SKETCH AND POLICE REPORT T/20180605/2023

Present Location: CHARN'S CUSTOMCRAFT (HQ)

COST OF CLAIMS	Amount
Parts	800.00
Miscellaneous Items	50.00
Labour	180.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,030.00
+ GST 7.00% (S\$)	72.10
Nett Amount (S\$)	1,102.10
+ Previous Estimates (S\$)	10,403.08
Claim Total (S\$)	11,505.18

SJZ9337P

Estimates on Miscellaneous Items

No	Cty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Brake oil (S/NETT) <i>leak / not consistent</i>	50.00
Sub Total (\$\$)			50.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Labour to remove and replace the above <i>X</i>	New	180.00
Gross Labour Cost (\$\$)			180.00

Charn's Customcraft/SJZ9337P/19/06/2018 14:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

To Revert to Insurer.
19/6/18

please be inform that *from workshop Charn's custom craft*
16/6/18

Owner collected car on Saturday afternoon and drove the car.
Workshop claim that owner e-mailed them on Sunday 17/6/18 that
the car had a brake issue and drove in the car on Monday
18/6/18. *X*

Workshop checked the car and found out that the brake booster
might be the cause of the brake ~~issue~~ problem.

We came to resurvey the car on Tuesday 19/6/18 and test ride the
car... the car braking system is ~~faulty~~ not effective.

We have review the case and concluded that the brake issue
is not related to the accident.

X owner also mentioned that before the accident
there is no issue with the ~~brake~~ braking system.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jun 2018)

Parts: M1-MPV HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Charn's Customcraft/SJZ9337P/19/06/2018 14:02

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Brake Booster <i>not consistent</i>	0.00	0.00	*800.00 F
			<i>leak</i>			
			Total Parts (S\$)			800.00

F=Franchise part.

Charn's Customcraft/SJZ9337P/19/06/2018 14:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

To Revert to Insurance
19/6/18
[Signature]