

MG SOLUTION

23 Kaki Bukit Avenue 4

Tel: (+65) 6243 1

Reg. No: 20

Email : mg3solut

TO : CHINA TAIPING INSURA
 ATTENTION : MOTOR CLAIMS DEPT
 ESTIMATE REPORT :
VEHICLE DETAILS
 VEHICLE NO : SLK596Y
 MODEL : HYUNDAI ELANTRA 1.
 CHASSIS NO
ACCIDENT DETAILS DATE : 5-Jun-18
 TIME : 08:35HRS
 THIRD PARTY REQUESTOR / CONTACT :

CLAIM DETAIL : PARTS

S/N	DESCRIPTION
1	FRONT BUMPER <i>Dehorn d</i>
2	FRONT BUMPER SIDE RETAINER
3	FRONT BUMPER TOWING COVER
4	FRONT BUMPER REINFORCEMENT
5	FRONT BUMPER REINFORCEMENT S
6	FRONT BUMPER UNDER COVER
7	NUMBER PLATE GARNISH <i>del</i>
8	FRONT CENTRE GRILLE WITH CHRO
9	FRONT CENTRE GRILLE LOGO
10	HEADLAMP <i>Rit cond d</i>
11	BOOTLID <i>Bueled</i>
12	BOOTLID LOGO
13	BOOTLID EMBLEM 'ELANTRA' <i>N</i>
14	BOOTLID EMBLEM 'S' <i>M</i>
15	BOOTLID HINGE <i>re ne</i>
16	BOOTLID TOP LOCK <i>Pang d</i>
17	BOOTLID LOWER CATCH <i>del</i>
18	BOOTLID REFLECTOR <i>caul</i>

495*+
 62*+
 288*3+
 122*+
 103*5+
 460*+
 90*+
 890*+
 907*6+
 58*6+
 35*+
 35*+
 211*+
 570*+
 180*+
 485*+
 295*6+
 180*+
 156*+
 325*+
 164*2+
 797*+
 230*+
 499*3+
 150*+
 =
 7,810.10*

= 7,810*1 x
 80*%
 6,248*08*

200*+
 200*+
 30*+
 900*+
 800*+
 60*+
 30*+
 50*+
 50*+
 50*=
 2,370*.*

50*+
 20*+
 20*+
 50*+
 20*+
 20*+
 22*+
 10*+
 200*=
 412*.*

6,248*08+
 412*+
 2,370*=
 9,030*08*

9,030*08 x
 80*%
 7,224*064*

TOTAL LIST PRICE

\$	630.00
\$	62.00
\$	100.00
\$	288.30
\$	122.00
\$	160.00
\$	103.50
\$	530.00
\$	90.00
\$	1,780.00
\$	1,788.20
\$	58.60
\$	86.90
\$	86.90
\$	241.60
\$	211.00
\$	56.80
\$	680.00

495 ✓
 ✓
 ✓
 ✓
 ✓
 ✓
 ✓
 460 ✓
 ✓
 890 ✓
 907.6 ✓
 ✓
 55 ✓
 35 ✓
 x
 ✓
 x
 570 ✓